PROPERTY CONDITION ASSESSMENT

Ridgeline Ironwood Student Living | Cincinnati, OH

Property	Ridgeline Ironwood Student Living
Address	5000 Market Court, Cincinnati, OH 72833
Site Visit Date	September 2, 2020
Client	Whitfield Park Capital
Immediate Repairs	$444,000

Improvements Description

Amenities include study lounges, a rooftop terrace, 24-hour fitness and a game room. Pre-leasing for the coming academic year stands at 95.0% with rental rates per bed averaging $1,052. The property is located 3 blocks from the main campus with a dedicated shuttle serving fall and spring terms. The roof is a 8-year membrane system with an estimated remaining useful life of 12 years. The community is leased by the bed on individual lease liability with parent guaranties and furnished units. Life-safety systems include a fully sprinklered building, addressable fire alarm panel and emergency lighting.

Pre-leasing for the coming academic year stands at 92.8% with rental rates per bed averaging $1,052. Mechanical systems include rooftop package units and central plant equipment of varying age. The property is located 3 blocks from the main campus with a dedicated shuttle serving fall and spring terms. Life-safety systems include a fully sprinklered building, addressable fire alarm panel and emergency lighting. Ridgeline Ironwood Student Living was originally constructed in 2003 and consists of 215 beds in a building of 5 stories.

Observed Conditions

Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $14,000. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 27 months.

Elevators were last modernized 10 years ago and are operating without deficiency. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $275,000. Domestic water piping is copper and PVC with no evidence of widespread leakage. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 30 months. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months.

Building Systems

Ridgeline Ironwood Student Living was originally constructed in 2003 and consists of 215 beds in a building of 33 stories. The community is leased by the bed on individual lease liability with parent guaranties and furnished units. Pre-leasing for the coming academic year stands at 91.2% with rental rates per bed averaging $1,052. The roof is a 17-year membrane system with an estimated remaining useful life of 4 years. Common area interiors have been refreshed within the last 5 years and are in average to good condition. Life-safety systems include a fully sprinklered building, addressable fire alarm panel and emergency lighting.

Common area interiors have been refreshed within the last 9 years and are in average to good condition. The structure is of wood-frame, masonry and steel-frame construction on a slab-on-grade foundation. The community is leased by the bed on individual lease liability with parent guaranties and furnished units. Amenities include study lounges, a rooftop terrace, 24-hour fitness and a game room. The property is located 9 blocks from the main campus with a dedicated shuttle serving fall and spring terms.

Deferred Maintenance

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Building Systems

The property is located 5 blocks from the main campus with a dedicated shuttle serving fall and spring terms. Ridgeline Ironwood Student Living was originally constructed in 2003 and consists of 215 beds in a building of 17 stories. The roof is a 37-year membrane system with an estimated remaining useful life of 9 years. Amenities include study lounges, a rooftop terrace, 24-hour fitness and a game room. Exterior finishes comprise brick veneer, fiber-cement siding and aluminum storefront glazing in good condition.

Exterior finishes comprise brick veneer, fiber-cement siding and aluminum storefront glazing in good condition. Ridgeline Ironwood Student Living was originally constructed in 2003 and consists of 215 beds in a building of 33 stories. The structure is of wood-frame, masonry and steel-frame construction on a slab-on-grade foundation. The roof is a 31-year membrane system with an estimated remaining useful life of 10 years. Amenities include study lounges, a rooftop terrace, 24-hour fitness and a game room. Life-safety systems include a fully sprinklered building, addressable fire alarm panel and emergency lighting.

Recommendations

Electrical service is adequate for current demand; select panels are nearing the end of their useful life. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $213,000. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Elevators were last modernized 7 years ago and are operating without deficiency.

Domestic water piping is copper and PVC with no evidence of widespread leakage. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 10 months. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Elevators were last modernized 6 years ago and are operating without deficiency.

Improvements Description

Exterior finishes comprise brick veneer, fiber-cement siding and aluminum storefront glazing in good condition. The roof is a 37-year membrane system with an estimated remaining useful life of 6 years. The property is located 5 blocks from the main campus with a dedicated shuttle serving fall and spring terms. The structure is of wood-frame, masonry and steel-frame construction on a slab-on-grade foundation. Ridgeline Ironwood Student Living was originally constructed in 2003 and consists of 215 beds in a building of 40 stories. Life-safety systems include a fully sprinklered building, addressable fire alarm panel and emergency lighting.

Common area interiors have been refreshed within the last 11 years and are in average to good condition. Amenities include study lounges, a rooftop terrace, 24-hour fitness and a game room. Mechanical systems include rooftop package units and central plant equipment of varying age. Pre-leasing for the coming academic year stands at 89.3% with rental rates per bed averaging $1,052. The roof is a 39-year membrane system with an estimated remaining useful life of 7 years. The community is leased by the bed on individual lease liability with parent guaranties and furnished units.

Observed Conditions

Domestic water piping is copper and PVC with no evidence of widespread leakage. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 21 months. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $258,000.

Elevators were last modernized 7 years ago and are operating without deficiency. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 5 months. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months.

Construction Details

The roof is a 35-year membrane system with an estimated remaining useful life of 7 years. Common area interiors have been refreshed within the last 5 years and are in average to good condition. Amenities include study lounges, a rooftop terrace, 24-hour fitness and a game room. Pre-leasing for the coming academic year stands at 88.4% with rental rates per bed averaging $1,052. Life-safety systems include a fully sprinklered building, addressable fire alarm panel and emergency lighting. Mechanical systems include rooftop package units and central plant equipment of varying age.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Immediate Repairs and Replacement Reserve Schedule

System	Age (yrs)	EUL	RUL	Condition	Immediate	Reserve (10-yr)
Roof	37	39	2	Fair	$26,000	$152,000
Paving	31	32	1	Poor	$17,000	$154,000
HVAC	6	17	11	Good	$23,000	$240,000
Plumbing	23	35	12	Poor	$24,000	$234,000
Electrical	31	32	1	Good	$16,000	$260,000
Elevators	14	31	17	Fair	$6,000	$200,000
Fire/Life Safety	19	27	8	Poor	$12,000	$214,000
Windows	24	32	8	Fair	$18,000	$155,000
Siding/Facade	11	11	0	Poor	$17,000	$213,000
Flooring	11	21	10	Good	$15,000	$77,000
Appliances	26	37	11	Poor	$15,000	$95,000
Landscaping	14	22	8	Good	$23,000	$104,000
Pool/Amenity	12	20	8	Poor	$7,000	$99,000
Signage	25	34	9	Fair	$22,000	$193,000
Fencing	15	25	10	Fair	$10,000	$250,000
Roof (2)	25	39	14	Good	$14,000	$206,000
Paving (2)	26	36	10	Fair	$25,000	$69,000
HVAC (2)	17	36	19	Good	$7,000	$25,000
Plumbing (2)	1	28	27	Fair	$15,000	$27,000
Electrical (2)	10	28	18	Poor	$34,000	$198,000
Elevators (2)	10	12	2	Fair	$6,000	$219,000
Fire/Life Safety (2)	15	27	12	Poor	$3,000	$32,000
Windows (2)	13	29	16	Fair	$27,000	$221,000
Siding/Facade (2)	23	23	0	Poor	$11,000	$53,000
Flooring (2)	23	28	5	Fair	$35,000	$188,000
Appliances (2)	2	16	14	Fair	$18,000	$210,000
Landscaping (2)	4	13	9	Fair	$7,000	$72,000
Pool/Amenity (2)	13	13	0	Good	$1,000	$92,000
Signage (2)	10	15	5	Fair	$34,000	$28,000
Fencing (2)	36	36	0	Poor	$9,000	$242,000

Report generated 09/02/2020. Figures are unaudited and subject to change.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Findings and Opinions of Cost

Item	Location	Observed Condition	Recommended Action	Priority	Est. Cost
Stair treads	Bldg A	Worn / loose	Replace treads	Year 1	$8,000
Stair treads	Common	Worn / loose	Replace treads	Year 1	$4,500
Water heater	Bldg A	Corrosion	Replace	Year 2-5	$65,000
Sidewalk	Site	Trip hazards	Grind / replace	Reserve	$78,500
HVAC unit	Bldg B	Beyond useful life	Replace RTU	Year 2-5	$79,500
Sidewalk	Bldg B	Trip hazards	Grind / replace	Year 1	$28,000
Fire extinguishers	Site	Expired tags	Service	Reserve	$23,000
Sidewalk	Common	Trip hazards	Grind / replace	Reserve	$20,000
HVAC unit	Site	Beyond useful life	Replace RTU	Reserve	$8,500
Dumpster enclosure	Bldg B	Damaged gate	Repair	Year 1	$64,000
HVAC unit	Mechanical	Beyond useful life	Replace RTU	Reserve	$85,000
Sprinkler heads	Mechanical	Painted heads	Replace	Reserve	$39,000
Sidewalk	Bldg A	Trip hazards	Grind / replace	Year 2-5	$13,000
Fire extinguishers	Roof	Expired tags	Service	Immediate	$64,000
HVAC unit	Bldg A	Beyond useful life	Replace RTU	Immediate	$52,500
Asphalt paving	Bldg A	Alligator cracking	Mill and overlay	Year 2-5	$62,000
Sidewalk	Bldg A	Trip hazards	Grind / replace	Year 2-5	$23,500
Roof membrane	Site	Ponding / seams	Re-seal and repair	Reserve	$50,500
Water heater	Site	Corrosion	Replace	Reserve	$51,500
Asphalt paving	Bldg B	Alligator cracking	Mill and overlay	Reserve	$71,500
Dumpster enclosure	Mechanical	Damaged gate	Repair	Year 1	$31,500
Stair treads	Mechanical	Worn / loose	Replace treads	Year 1	$49,500
HVAC unit	Roof	Beyond useful life	Replace RTU	Reserve	$45,000
Window sealant	Bldg B	Failed	Re-caulk	Year 1	$9,500
Fire extinguishers	Bldg A	Expired tags	Service	Year 2-5	$55,500
Asphalt paving	Bldg A	Alligator cracking	Mill and overlay	Reserve	$47,500
Stair treads	Mechanical	Worn / loose	Replace treads	Immediate	$2,000
Dumpster enclosure	Common	Damaged gate	Repair	Immediate	$51,000
Fire extinguishers	Roof	Expired tags	Service	Immediate	$72,500
Sidewalk	Site	Trip hazards	Grind / replace	Year 2-5	$77,500
Sidewalk	Roof	Trip hazards	Grind / replace	Year 1	$90,000
Window sealant	Site	Failed	Re-caulk	Year 1	$67,000
Handrail	Bldg B	Loose	Secure	Year 1	$3,000
Window sealant	Common	Failed	Re-caulk	Year 2-5	$60,000
Roof membrane	Site	Ponding / seams	Re-seal and repair	Reserve	$15,000
Sprinkler heads	Site	Painted heads	Replace	Reserve	$57,500
HVAC unit	Mechanical	Beyond useful life	Replace RTU	Year 1	$46,000
Sidewalk	Common	Trip hazards	Grind / replace	Reserve	$13,000
Fire extinguishers	Bldg B	Expired tags	Service	Immediate	$15,500
Fire extinguishers	Roof	Expired tags	Service	Year 1	$15,500
HVAC unit	Bldg B	Beyond useful life	Replace RTU	Immediate	$15,000

Report generated 09/02/2020. Figures are unaudited and subject to change.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Observed Conditions

Electrical service is adequate for current demand; select panels are nearing the end of their useful life. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $138,000. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 6 months. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months.

ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $352,000. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Domestic water piping is copper and PVC with no evidence of widespread leakage. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 27 months.

Deferred Maintenance

Domestic water piping is copper and PVC with no evidence of widespread leakage. Elevators were last modernized 10 years ago and are operating without deficiency. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $456,000. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 8 months. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations.

Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 3 months. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations.

Observed Conditions

Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 16 months. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Domestic water piping is copper and PVC with no evidence of widespread leakage. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $238,000. Elevators were last modernized 3 years ago and are operating without deficiency.

The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 22 months. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $343,000.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Building Systems

Common area interiors have been refreshed within the last 12 years and are in average to good condition. The structure is of wood-frame, masonry and steel-frame construction on a slab-on-grade foundation. Ridgeline Ironwood Student Living was originally constructed in 2003 and consists of 215 beds in a building of 10 stories. The property is located 8 blocks from the main campus with a dedicated shuttle serving fall and spring terms. The community is leased by the bed on individual lease liability with parent guaranties and furnished units. Pre-leasing for the coming academic year stands at 96.8% with rental rates per bed averaging $1,052.

The roof is a 42-year membrane system with an estimated remaining useful life of 12 years. The structure is of wood-frame, masonry and steel-frame construction on a slab-on-grade foundation. Amenities include study lounges, a rooftop terrace, 24-hour fitness and a game room. The community is leased by the bed on individual lease liability with parent guaranties and furnished units. Common area interiors have been refreshed within the last 9 years and are in average to good condition. Life-safety systems include a fully sprinklered building, addressable fire alarm panel and emergency lighting.

Recommendations

Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Elevators were last modernized 9 years ago and are operating without deficiency. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $190,000. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months.

The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $148,000. Domestic water piping is copper and PVC with no evidence of widespread leakage. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 12 months. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations.

Building Systems

Common area interiors have been refreshed within the last 5 years and are in average to good condition. The community is leased by the bed on individual lease liability with parent guaranties and furnished units. The structure is of wood-frame, masonry and steel-frame construction on a slab-on-grade foundation. The roof is a 4-year membrane system with an estimated remaining useful life of 8 years.

The property is located 8 blocks from the main campus with a dedicated shuttle serving fall and spring terms. The community is leased by the bed on individual lease liability with parent guaranties and furnished units. Ridgeline Ironwood Student Living was originally constructed in 2003 and consists of 215 beds in a building of 29 stories. The roof is a 21-year membrane system with an estimated remaining useful life of 7 years.

Recommendations

Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Domestic water piping is copper and PVC with no evidence of widespread leakage. Elevators were last modernized 5 years ago and are operating without deficiency.

Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 33 months. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Domestic water piping is copper and PVC with no evidence of widespread leakage.

Building Systems

Pre-leasing for the coming academic year stands at 93.6% with rental rates per bed averaging $1,052. Common area interiors have been refreshed within the last 4 years and are in average to good condition. The property is located 9 blocks from the main campus with a dedicated shuttle serving fall and spring terms. Life-safety systems include a fully sprinklered building, addressable fire alarm panel and emergency lighting. The community is leased by the bed on individual lease liability with parent guaranties and furnished units. Ridgeline Ironwood Student Living was originally constructed in 2003 and consists of 215 beds in a building of 22 stories.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Immediate Repairs and Replacement Reserve Schedule

System	Age (yrs)	EUL	RUL	Condition	Immediate	Reserve (10-yr)
Roof	17	20	3	Fair	$10,000	$153,000
Paving	4	24	20	Poor	$14,000	$189,000
HVAC	12	40	28	Good	$23,000	$271,000
Plumbing	11	34	23	Fair	$15,000	$168,000
Electrical	6	14	8	Poor	$38,000	$106,000
Elevators	21	31	10	Fair	$15,000	$152,000
Fire/Life Safety	26	35	9	Fair	$2,000	$38,000
Windows	5	11	6	Poor	$38,000	$272,000
Siding/Facade	7	22	15	Good	$7,000	$193,000
Flooring	16	34	18	Fair	$33,000	$110,000
Appliances	14	23	9	Poor	$7,000	$117,000
Landscaping	18	34	16	Fair	$19,000	$206,000
Pool/Amenity	2	16	14	Poor	$38,000	$272,000
Signage	14	26	12	Fair	$28,000	$11,000
Fencing	4	31	27	Good	$24,000	$191,000
Roof (2)	7	24	17	Poor	$15,000	$39,000
Paving (2)	8	19	11	Good	$0	$219,000
HVAC (2)	7	35	28	Fair	$29,000	$109,000
Plumbing (2)	4	36	32	Fair	$25,000	$176,000
Electrical (2)	18	19	1	Fair	$26,000	$236,000
Elevators (2)	33	36	3	Good	$6,000	$76,000
Fire/Life Safety (2)	25	31	6	Fair	$0	$202,000
Windows (2)	11	26	15	Good	$1,000	$32,000
Siding/Facade (2)	11	25	14	Good	$33,000	$104,000
Flooring (2)	7	21	14	Fair	$20,000	$17,000
Appliances (2)	27	39	12	Fair	$2,000	$227,000
Landscaping (2)	3	20	17	Fair	$23,000	$88,000
Pool/Amenity (2)	3	39	36	Fair	$26,000	$44,000
Signage (2)	25	35	10	Fair	$13,000	$39,000
Fencing (2)	20	40	20	Fair	$2,000	$141,000

Report generated 09/02/2020. Figures are unaudited and subject to change.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Findings and Opinions of Cost

Item	Location	Observed Condition	Recommended Action	Priority	Est. Cost
Asphalt paving	Site	Alligator cracking	Mill and overlay	Reserve	$77,000
Asphalt paving	Bldg A	Alligator cracking	Mill and overlay	Year 1	$53,000
Dumpster enclosure	Roof	Damaged gate	Repair	Year 1	$45,500
Roof membrane	Roof	Ponding / seams	Re-seal and repair	Year 2-5	$21,500
Handrail	Bldg B	Loose	Secure	Year 1	$7,000
Roof membrane	Site	Ponding / seams	Re-seal and repair	Year 2-5	$78,500
Fire extinguishers	Bldg B	Expired tags	Service	Reserve	$5,500
Sprinkler heads	Bldg A	Painted heads	Replace	Immediate	$61,000
Roof membrane	Site	Ponding / seams	Re-seal and repair	Year 1	$54,500
HVAC unit	Bldg A	Beyond useful life	Replace RTU	Immediate	$6,500
Sidewalk	Roof	Trip hazards	Grind / replace	Reserve	$67,000
Water heater	Bldg B	Corrosion	Replace	Reserve	$30,000
Sidewalk	Bldg B	Trip hazards	Grind / replace	Immediate	$71,000
Sprinkler heads	Bldg B	Painted heads	Replace	Immediate	$83,000
Sprinkler heads	Bldg B	Painted heads	Replace	Year 2-5	$44,500
Asphalt paving	Site	Alligator cracking	Mill and overlay	Immediate	$25,000
Asphalt paving	Common	Alligator cracking	Mill and overlay	Immediate	$79,000
Sprinkler heads	Site	Painted heads	Replace	Year 2-5	$2,500
Fire extinguishers	Roof	Expired tags	Service	Reserve	$4,500
Sidewalk	Roof	Trip hazards	Grind / replace	Reserve	$19,500
Water heater	Bldg A	Corrosion	Replace	Year 2-5	$29,000
Dumpster enclosure	Roof	Damaged gate	Repair	Reserve	$15,000
Handrail	Common	Loose	Secure	Year 1	$87,000
Stair treads	Bldg B	Worn / loose	Replace treads	Reserve	$11,500
Fire extinguishers	Common	Expired tags	Service	Year 2-5	$23,500
Window sealant	Site	Failed	Re-caulk	Year 1	$61,000
Handrail	Roof	Loose	Secure	Reserve	$16,000
Asphalt paving	Site	Alligator cracking	Mill and overlay	Immediate	$28,500
Stair treads	Bldg B	Worn / loose	Replace treads	Year 1	$48,000
Roof membrane	Roof	Ponding / seams	Re-seal and repair	Year 1	$51,500
Stair treads	Site	Worn / loose	Replace treads	Year 1	$30,500
Handrail	Bldg A	Loose	Secure	Year 1	$84,000
Stair treads	Roof	Worn / loose	Replace treads	Immediate	$53,000
Sprinkler heads	Common	Painted heads	Replace	Year 2-5	$18,500
Window sealant	Bldg A	Failed	Re-caulk	Year 2-5	$64,500
Sidewalk	Bldg B	Trip hazards	Grind / replace	Immediate	$66,500
Window sealant	Site	Failed	Re-caulk	Immediate	$67,000
Window sealant	Common	Failed	Re-caulk	Year 1	$8,500
Fire extinguishers	Mechanical	Expired tags	Service	Year 1	$12,000
Sidewalk	Roof	Trip hazards	Grind / replace	Immediate	$33,000

Report generated 09/02/2020. Figures are unaudited and subject to change.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Observed Conditions

Domestic water piping is copper and PVC with no evidence of widespread leakage. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $464,000. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months.

Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Elevators were last modernized 9 years ago and are operating without deficiency. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $263,000.

Recommendations

Domestic water piping is copper and PVC with no evidence of widespread leakage. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $259,000. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 15 months.

Domestic water piping is copper and PVC with no evidence of widespread leakage. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $272,000. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 44 months. Elevators were last modernized 9 years ago and are operating without deficiency. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months.

Recommendations

Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 25 months. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $76,000. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations.

Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Domestic water piping is copper and PVC with no evidence of widespread leakage. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 43 months. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Improvements Description

Exterior finishes comprise brick veneer, fiber-cement siding and aluminum storefront glazing in good condition. Pre-leasing for the coming academic year stands at 88.7% with rental rates per bed averaging $1,052. Common area interiors have been refreshed within the last 4 years and are in average to good condition. The structure is of wood-frame, masonry and steel-frame construction on a slab-on-grade foundation. Ridgeline Ironwood Student Living was originally constructed in 2003 and consists of 215 beds in a building of 16 stories.

Pre-leasing for the coming academic year stands at 92.5% with rental rates per bed averaging $1,052. Exterior finishes comprise brick veneer, fiber-cement siding and aluminum storefront glazing in good condition. Ridgeline Ironwood Student Living was originally constructed in 2003 and consists of 215 beds in a building of 18 stories. The roof is a 4-year membrane system with an estimated remaining useful life of 5 years. Amenities include study lounges, a rooftop terrace, 24-hour fitness and a game room.

Observed Conditions

Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 16 months. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $229,000. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Domestic water piping is copper and PVC with no evidence of widespread leakage. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months.

Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 25 months. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $226,000. Elevators were last modernized 12 years ago and are operating without deficiency.

Improvements Description

Common area interiors have been refreshed within the last 6 years and are in average to good condition. Life-safety systems include a fully sprinklered building, addressable fire alarm panel and emergency lighting. The roof is a 23-year membrane system with an estimated remaining useful life of 3 years. Ridgeline Ironwood Student Living was originally constructed in 2003 and consists of 215 beds in a building of 40 stories. The structure is of wood-frame, masonry and steel-frame construction on a slab-on-grade foundation. Mechanical systems include rooftop package units and central plant equipment of varying age.

Life-safety systems include a fully sprinklered building, addressable fire alarm panel and emergency lighting. Mechanical systems include rooftop package units and central plant equipment of varying age. Pre-leasing for the coming academic year stands at 93.0% with rental rates per bed averaging $1,052. Ridgeline Ironwood Student Living was originally constructed in 2003 and consists of 215 beds in a building of 48 stories. The structure is of wood-frame, masonry and steel-frame construction on a slab-on-grade foundation.

Observed Conditions

ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $468,000. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 34 months. Elevators were last modernized 8 years ago and are operating without deficiency. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations.

Domestic water piping is copper and PVC with no evidence of widespread leakage. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $367,000. Elevators were last modernized 11 years ago and are operating without deficiency. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 45 months.

Construction Details

Common area interiors have been refreshed within the last 9 years and are in average to good condition. Amenities include study lounges, a rooftop terrace, 24-hour fitness and a game room. Pre-leasing for the coming academic year stands at 93.9% with rental rates per bed averaging $1,052. The property is located 5 blocks from the main campus with a dedicated shuttle serving fall and spring terms. The structure is of wood-frame, masonry and steel-frame construction on a slab-on-grade foundation.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Immediate Repairs and Replacement Reserve Schedule

System	Age (yrs)	EUL	RUL	Condition	Immediate	Reserve (10-yr)
Roof	21	21	0	Fair	$0	$216,000
Paving	4	22	18	Fair	$7,000	$262,000
HVAC	10	33	23	Good	$36,000	$44,000
Plumbing	5	25	20	Good	$40,000	$58,000
Electrical	7	36	29	Good	$34,000	$79,000
Elevators	27	29	2	Poor	$1,000	$250,000
Fire/Life Safety	6	25	19	Good	$37,000	$13,000
Windows	14	40	26	Fair	$2,000	$160,000
Siding/Facade	2	27	25	Poor	$10,000	$90,000
Flooring	5	15	10	Fair	$34,000	$88,000
Appliances	13	29	16	Fair	$26,000	$260,000
Landscaping	10	38	28	Fair	$5,000	$15,000
Pool/Amenity	26	34	8	Good	$26,000	$23,000
Signage	18	39	21	Poor	$19,000	$181,000
Fencing	8	21	13	Fair	$18,000	$85,000
Roof (2)	23	27	4	Fair	$35,000	$44,000
Paving (2)	25	27	2	Good	$4,000	$208,000
HVAC (2)	4	31	27	Good	$13,000	$250,000
Plumbing (2)	14	24	10	Good	$13,000	$131,000
Electrical (2)	1	20	19	Good	$28,000	$98,000
Elevators (2)	10	11	1	Fair	$40,000	$32,000
Fire/Life Safety (2)	16	31	15	Poor	$17,000	$183,000
Windows (2)	3	29	26	Poor	$8,000	$90,000
Siding/Facade (2)	9	38	29	Fair	$29,000	$144,000
Flooring (2)	7	10	3	Good	$35,000	$165,000
Appliances (2)	30	34	4	Poor	$24,000	$218,000
Landscaping (2)	10	35	25	Fair	$35,000	$54,000
Pool/Amenity (2)	3	20	17	Fair	$10,000	$115,000
Signage (2)	4	14	10	Poor	$20,000	$214,000
Fencing (2)	1	11	10	Fair	$9,000	$106,000

Report generated 09/02/2020. Figures are unaudited and subject to change.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Certification

I certify that, to the best of my knowledge and belief, the statements of fact contained in this report are true and correct and that I have no present or prospective interest in Ridgeline Ironwood Student Living and no personal interest with respect to the parties involved.

The analyses, opinions and conclusions are limited only by the reported assumptions and limiting conditions. The inspection of the property was performed on August 18, 2020.

_____

Natalie Underwood, PE

Northbridge Inspection Services

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only