# PHASE I ENVIRONMENTAL SITE ASSESSMENT

Ridgeline Manor | Dallas, TX

| | |
|---|---|
| **Site** | Ridgeline Manor |
| **Address** | 7944 Airport Drive, Dallas, TX 64569 |
| **Prepared For** | Vireo Income Properties |
| **Report Date** | November 25, 2023 |
| **Standard** | ASTM E1527-21 |

## Site Description

Access to the site is provided by 5 curb cuts and the property is served by municipal water and sanitary sewer. Utilities, including electric, natural gas and telecommunications, are available to the site from the street. The site contains approximately 14.14 acres and is generally level with frontage along Airport Drive. Surrounding land uses include residential, commercial and light industrial properties of similar vintage.

Soils are typical of the region and no evidence of unsuitable conditions was observed at the time of inspection. Utilities, including electric, natural gas and telecommunications, are available to the site from the street. Surrounding land uses include residential, commercial and light industrial properties of similar vintage. The site contains approximately 35.35 acres and is generally level with frontage along Airport Drive.

## Site Reconnaissance

Vapor encroachment screening did not identify a condition requiring further evaluation. No recognized environmental conditions (RECs) were identified in connection with the subject property. A former dry cleaner located 3 blocks to the north is listed as a closed case and is not expected to impact the site. A review of regulatory databases identified no listings for the subject property within the ASTM-specified search distances. Based on the age of construction, an asbestos operations and maintenance program is recommended for suspect materials.

A former dry cleaner located 6 blocks to the north is listed as a closed case and is not expected to impact the site. No evidence of underground storage tanks, stained soils or stressed vegetation was observed during the site reconnaissance. A review of regulatory databases identified no listings for the subject property within the ASTM-specified search distances. Vapor encroachment screening did not identify a condition requiring further evaluation.

## Topography and Flood Zone

The site is not located within a designated 100-year floodplain according to the FEMA flood map in effect. The site contains approximately 47.47 acres and is generally level with frontage along Airport Drive. Utilities, including electric, natural gas and telecommunications, are available to the site from the street. Access to the site is provided by 28 curb cuts and the property is served by municipal water and sanitary sewer. Soils are typical of the region and no evidence of unsuitable conditions was observed at the time of inspection.

The site is not located within a designated 100-year floodplain according to the FEMA flood map in effect. The site contains approximately 37.37 acres and is generally level with frontage along Airport Drive. Utilities, including electric, natural gas and telecommunications, are available to the site from the street. Surrounding land uses include residential, commercial and light industrial properties of similar vintage.

## Findings and Opinions

A review of regulatory databases identified no listings for the subject property within the ASTM-specified search distances. No recognized environmental conditions (RECs) were identified in connection with the subject property. A former dry cleaner located 8 blocks to the north is listed as a closed case and is not expected to impact the site. Based on the age of construction, an asbestos operations and maintenance program is recommended for suspect materials.

No recognized environmental conditions (RECs) were identified in connection with the subject property. A review of regulatory databases identified no listings for the subject property within the ASTM-specified search distances. Based on the age of construction, an asbestos operations and maintenance program is recommended for suspect materials. A former dry cleaner located 5 blocks to the north is listed as a closed case and is not expected to impact the site.

## Topography and Flood Zone

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

## Site Description

Surrounding land uses include residential, commercial and light industrial properties of similar vintage. Access to the site is provided by 47 curb cuts and the property is served by municipal water and sanitary sewer. Utilities, including electric, natural gas and telecommunications, are available to the site from the street. The site is not located within a designated 100-year floodplain according to the FEMA flood map in effect. Soils are typical of the region and no evidence of unsuitable conditions was observed at the time of inspection.

The site is not located within a designated 100-year floodplain according to the FEMA flood map in effect. Surrounding land uses include residential, commercial and light industrial properties of similar vintage. The site contains approximately 38.38 acres and is generally level with frontage along Airport Drive. Soils are typical of the region and no evidence of unsuitable conditions was observed at the time of inspection. Utilities, including electric, natural gas and telecommunications, are available to the site from the street.

## Records Review

Historical sources indicate the site was previously used for agricultural and light commercial purposes. No evidence of underground storage tanks, stained soils or stressed vegetation was observed during the site reconnaissance. Based on the age of construction, an asbestos operations and maintenance program is recommended for suspect materials. A former dry cleaner located 2 blocks to the north is listed as a closed case and is not expected to impact the site. Vapor encroachment screening did not identify a condition requiring further evaluation.

No evidence of underground storage tanks, stained soils or stressed vegetation was observed during the site reconnaissance. No recognized environmental conditions (RECs) were identified in connection with the subject property. Vapor encroachment screening did not identify a condition requiring further evaluation. Based on the age of construction, an asbestos operations and maintenance program is recommended for suspect materials.

## Access and Utilities

The site is not located within a designated 100-year floodplain according to the FEMA flood map in effect. Utilities, including electric, natural gas and telecommunications, are available to the site from the street. Surrounding land uses include residential, commercial and light industrial properties of similar vintage. The site contains approximately 14.14 acres and is generally level with frontage along Airport Drive. Soils are typical of the region and no evidence of unsuitable conditions was observed at the time of inspection.

Access to the site is provided by 7 curb cuts and the property is served by municipal water and sanitary sewer. Surrounding land uses include residential, commercial and light industrial properties of similar vintage. Soils are typical of the region and no evidence of unsuitable conditions was observed at the time of inspection. Utilities, including electric, natural gas and telecommunications, are available to the site from the street. The site contains approximately 33.33 acres and is generally level with frontage along Airport Drive. The site is not located within a designated 100-year floodplain according to the FEMA flood map in effect.

## Records Review

A review of regulatory databases identified no listings for the subject property within the ASTM-specified search distances. Based on the age of construction, an asbestos operations and maintenance program is recommended for suspect materials. Vapor encroachment screening did not identify a condition requiring further evaluation. A former dry cleaner located 2 blocks to the north is listed as a closed case and is not expected to impact the site. No recognized environmental conditions (RECs) were identified in connection with the subject property.

No recognized environmental conditions (RECs) were identified in connection with the subject property. Based on the age of construction, an asbestos operations and maintenance program is recommended for suspect materials. A review of regulatory databases identified no listings for the subject property within the ASTM-specified search distances. No evidence of underground storage tanks, stained soils or stressed vegetation was observed during the site reconnaissance. A former dry cleaner located 5 blocks to the north is listed as a closed case and is not expected to impact the site.

## Access and Utilities

Utilities, including electric, natural gas and telecommunications, are available to the site from the street. Soils are typical of the region and no evidence of unsuitable conditions was observed at the time of inspection. Access to the site is provided by 10 curb cuts and the property is served by municipal water and sanitary sewer. The site is not located within a designated 100-year floodplain according to the FEMA flood map in effect.

The site is not located within a designated 100-year floodplain according to the FEMA flood map in effect. The site contains approximately 47.47 acres and is generally level with frontage along Airport Drive. Surrounding land uses include residential, commercial and light industrial properties of similar vintage. Access to the site is provided by 41 curb cuts and the property is served by municipal water and sanitary sewer. Soils are typical of the region and no evidence of unsuitable conditions was observed at the time of inspection.

## Historical Use

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

## Regulatory Database Search Results

| Database | Search Radius (mi) | Sites Within Radius | Subject Property? | Further Evaluation |
|---|---|---|---|---|
| NPL (Superfund) | 0.5 | 0 | No | None |
| CERCLIS / SEMS | 0.5 | 1 | No | None |
| RCRA - Generators | 0.5 | 1 | No | None |
| RCRA - TSD | 0.5 | 4 | No | None |
| LUST | 0.25 | 1 | No | Reviewed - no action |
| UST | 0.5 | 0 | No | Reviewed - no action |
| State Hazardous Waste Sites | 1.0 | 2 | No | None |
| Brownfields | 0.25 | 0 | No | None |
| Engineering Controls | 0.25 | 4 | No | None |
| Institutional Controls | 0.5 | 1 | No | None |
| ERNS | 1.0 | 0 | No | None |
| Drycleaner Facilities | 0.5 | 7 | No | None |
| Solid Waste Landfills | 0.5 | 0 | No | None |
| Voluntary Cleanup | 1.0 | 0 | No | None |
| Historical Auto Stations | 0.25 | 7 | No | None |
| NPL (Superfund) | 0.5 | 2 | No | None |
| CERCLIS / SEMS | 0.5 | 0 | No | Reviewed - no action |
| RCRA - Generators | 0.5 | 2 | No | Reviewed - no action |
| RCRA - TSD | 0.5 | 0 | No | None |
| LUST | 0.25 | 4 | No | None |
| UST | 0.5 | 2 | No | None |
| State Hazardous Waste Sites | 0.5 | 7 | No | Reviewed - no action |
| Brownfields | 0.25 | 0 | No | Reviewed - no action |
| Engineering Controls | 0.25 | 0 | No | None |
| Institutional Controls | 0.25 | 0 | No | None |
| ERNS | 0.5 | 0 | No | None |
| Drycleaner Facilities | 0.5 | 4 | No | Reviewed - no action |
| Solid Waste Landfills | 1.0 | 4 | No | None |
| Voluntary Cleanup | 0.5 | 2 | No | Reviewed - no action |
| Historical Auto Stations | 0.5 | 1 | No | None |

Report generated 11/25/2023. Figures are unaudited and subject to change.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

## Site Reconnaissance

No recognized environmental conditions (RECs) were identified in connection with the subject property. A former dry cleaner located 4 blocks to the north is listed as a closed case and is not expected to impact the site. A review of regulatory databases identified no listings for the subject property within the ASTM-specified search distances. Historical sources indicate the site was previously used for agricultural and light commercial purposes.

A review of regulatory databases identified no listings for the subject property within the ASTM-specified search distances. Based on the age of construction, an asbestos operations and maintenance program is recommended for suspect materials. No evidence of underground storage tanks, stained soils or stressed vegetation was observed during the site reconnaissance. No recognized environmental conditions (RECs) were identified in connection with the subject property.

## Historical Use

Historical sources indicate the site was previously used for agricultural and light commercial purposes. Based on the age of construction, an asbestos operations and maintenance program is recommended for suspect materials. No evidence of underground storage tanks, stained soils or stressed vegetation was observed during the site reconnaissance. No recognized environmental conditions (RECs) were identified in connection with the subject property. A review of regulatory databases identified no listings for the subject property within the ASTM-specified search distances. A former dry cleaner located 4 blocks to the north is listed as a closed case and is not expected to impact the site.

A former dry cleaner located 3 blocks to the north is listed as a closed case and is not expected to impact the site. Historical sources indicate the site was previously used for agricultural and light commercial purposes. No recognized environmental conditions (RECs) were identified in connection with the subject property. A review of regulatory databases identified no listings for the subject property within the ASTM-specified search distances. No evidence of underground storage tanks, stained soils or stressed vegetation was observed during the site reconnaissance.

## Historical Use

No recognized environmental conditions (RECs) were identified in connection with the subject property. Based on the age of construction, an asbestos operations and maintenance program is recommended for suspect materials. A review of regulatory databases identified no listings for the subject property within the ASTM-specified search distances. Historical sources indicate the site was previously used for agricultural and light commercial purposes. No evidence of underground storage tanks, stained soils or stressed vegetation was observed during the site reconnaissance. A former dry cleaner located 7 blocks to the north is listed as a closed case and is not expected to impact the site.

Historical sources indicate the site was previously used for agricultural and light commercial purposes. A former dry cleaner located 7 blocks to the north is listed as a closed case and is not expected to impact the site. No recognized environmental conditions (RECs) were identified in connection with the subject property. A review of regulatory databases identified no listings for the subject property within the ASTM-specified search distances.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

# Certification

I certify that, to the best of my knowledge and belief, the statements of fact contained in this report are true and correct and that I have no present or prospective interest in Ridgeline Manor and no personal interest with respect to the parties involved.

The analyses, opinions and conclusions are limited only by the reported assumptions and limiting conditions. The inspection of the property was performed on October 26, 2023.

_____

Susan Moreno, MAI

TerraSound Environmental

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only