CAPITAL IMPROVEMENT PLAN

Amberly Suites | Birmingham, AL

Property	Amberly Suites
Plan Date	May 27, 2024
Prepared For	Vireo Income Properties
Total Plan Budget	$432,000

Capital Project Schedule

Project	Category	Start	Completion	Budget	Spent to Date	Status
Pool resurfacing	Energy	05/31/23	Q2 2027	$807,000	$463,076	Bidding
Water heater replacement	Site	11/05/26	Q2 2026	$684,000	$158,401	Complete
Fence replacement	Site	04/17/23	Q3 2025	$108,000	$92,411	Complete
Parking lot resurfacing	Interior	07/31/26	Q3 2027	$39,000	$40,354	Complete
Storefront glazing	Building	10/04/25	Q4 2027	$67,000	$56,913	Approved
Exterior paint	Life Safety	09/05/26	Q1 2027	$794,000	$679,149	Bidding
Pool resurfacing	Site	02/24/26	Q3 2027	$703,000	$447,117	Deferred
ADA compliance	Energy	04/04/24	Q1 2026	$810,000	$537,023	Complete
Fence replacement	Interior	05/05/25	Q4 2026	$30,000	$29,355	Approved
Sewer line repair	Building	04/04/25	Q1 2026	$645,000	$471,250	Bidding
HVAC replacement	Interior	02/11/25	Q1 2025	$834,000	$184,460	Bidding
HVAC replacement	Interior	01/10/26	Q1 2025	$819,000	$457,373	Bidding
Signage / monument	Site	02/11/23	Q1 2026	$286,000	$292,157	Deferred
Roof replacement - Bldg C	Building	02/15/23	Q4 2026	$480,000	$74,955	Deferred
Landscape / irrigation	Life Safety	01/07/25	Q1 2025	$78,000	$55,101	Bidding
Security camera upgrade	Energy	01/18/24	Q4 2026	$458,000	$278,414	In progress
Parking lot resurfacing	Site	06/07/23	Q1 2027	$576,000	$482,402	Approved
Pool resurfacing	Energy	09/10/26	Q2 2026	$796,000	$35,008	Deferred
Parking lot resurfacing	Life Safety	11/24/24	Q1 2027	$297,000	$190,449	Approved
ADA compliance	Energy	07/08/26	Q1 2025	$407,000	$178,868	Approved
Signage / monument	Building	06/05/23	Q2 2027	$789,000	$49,187	Approved
Security camera upgrade	Interior	08/31/25	Q1 2027	$144,000	$65,026	Approved
Elevator modernization	Site	05/18/25	Q3 2027	$839,000	$368,077	Complete

Report generated 05/27/2024. Figures are unaudited and subject to change.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Capital Project Schedule

Project	Category	Start	Completion	Budget	Spent to Date	Status
ADA compliance	Life Safety	10/08/24	Q4 2025	$430,000	$156,149	Complete
Unit interior upgrades	Building	02/20/25	Q1 2027	$686,000	$469,294	In progress
Elevator modernization	Interior	07/27/23	Q2 2027	$230,000	$183,192	Complete
Roof replacement - Bldg C	Energy	08/24/25	Q2 2027	$178,000	$104,700	In progress
Door hardware	Building	11/18/25	Q3 2025	$632,000	$68,688	In progress
Parking lot resurfacing	Building	08/03/25	Q1 2027	$305,000	$112,713	In progress
Signage / monument	Building	01/04/25	Q4 2027	$481,000	$378,988	Complete
Pool resurfacing	Site	06/01/24	Q4 2026	$287,000	$195,432	In progress
Elevator modernization	Site	09/21/23	Q2 2026	$621,000	$619,920	Complete
LED lighting retrofit	Interior	07/09/23	Q1 2025	$755,000	$32,073	Bidding
Security camera upgrade	Building	07/20/23	Q2 2027	$21,000	$9,190	Approved
Parking lot resurfacing	Site	09/14/24	Q3 2027	$315,000	$246,478	In progress
LED lighting retrofit	Site	09/24/25	Q3 2026	$382,000	$183,195	Complete
Amenity renovation	Interior	08/13/24	Q4 2027	$350,000	$135,216	Approved
Elevator modernization	Site	08/14/25	Q2 2026	$776,000	$677,755	Bidding
Elevator modernization	Life Safety	10/27/23	Q1 2026	$33,000	$16,670	Bidding
Lobby renovation	Site	06/01/26	Q3 2026	$758,000	$222,158	Deferred
Security camera upgrade	Energy	08/27/26	Q2 2026	$676,000	$17,895	Approved
Amenity renovation	Interior	05/17/26	Q1 2026	$811,000	$272,850	Approved
Pool resurfacing	Interior	04/09/26	Q4 2025	$220,000	$156,770	Complete
Unit interior upgrades	Site	08/14/26	Q3 2025	$229,000	$178,354	Deferred
Water heater replacement	Life Safety	06/25/25	Q3 2026	$388,000	$246,943	Complete
Water heater replacement	Energy	04/11/26	Q1 2025	$608,000	$542,787	In progress
Sewer line repair	Site	10/06/25	Q2 2027	$720,000	$156,455	Complete
Elevator modernization	Energy	03/27/24	Q3 2025	$732,000	$596,623	Complete
Amenity renovation	Building	12/09/24	Q3 2026	$238,000	$24,366	In progress
Signage / monument	Building	06/11/26	Q4 2027	$883,000	$821,027	Approved
Elevator modernization	Interior	08/30/24	Q1 2027	$603,000	$455,730	Approved
Pool resurfacing	Interior	07/23/23	Q2 2025	$298,000	$163,247	Deferred
Sewer line repair	Building	06/03/24	Q4 2026	$519,000	$416,913	Approved
Pool resurfacing	Energy	03/23/25	Q1 2025	$555,000	$211,672	Complete
Exterior paint	Interior	01/26/24	Q3 2027	$421,000	$377,637	Bidding
Elevator modernization	Energy	10/28/23	Q3 2026	$221,000	$112,708	Bidding
Pool resurfacing	Energy	03/19/25	Q1 2027	$557,000	$322,264	Deferred
Lobby renovation	Building	08/25/24	Q2 2027	$460,000	$453,682	Approved
HVAC replacement	Interior	12/30/23	Q3 2026	$264,000	$188,538	Approved
LED lighting retrofit	Interior	01/24/24	Q4 2027	$122,000	$108,500	In progress
Storefront glazing	Site	02/04/23	Q2 2027	$182,000	$137,968	Bidding
Door hardware	Site	01/21/25	Q4 2026	$238,000	$88,059	Approved
Lobby renovation	Site	09/15/24	Q3 2027	$14,000	$11,086	Approved
Roof replacement - Bldg B	Life Safety	11/23/26	Q2 2026	$759,000	$100,087	Approved
Water heater replacement	Building	06/15/23	Q4 2027	$163,000	$41,252	Complete

Report generated 05/27/2024. Figures are unaudited and subject to change.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Observed Conditions

Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 36 months. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Domestic water piping is copper and PVC with no evidence of widespread leakage. Elevators were last modernized 9 years ago and are operating without deficiency. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $116,000.

Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 33 months. Domestic water piping is copper and PVC with no evidence of widespread leakage. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $403,000.

Business Plan Progress

Projected levered IRR is 11.5% with an equity multiple of 1.45x over the hold period. Revenue is driven by transient corporate demand, group business and weekend leisure travel. The investment thesis is based on stabilizing occupancy, completing the capital plan and capturing rent growth to market. Key risks include interest rate exposure, tenant rollover, construction cost overruns and local supply additions. Leasing velocity improved during the period and management expects further upward pressure on in-place rents. The business plan contemplates a hold period of 5 years with disposition upon achievement of target returns.

The hotel operates under a franchise agreement with Crestwood Inn, with a complimentary breakfast, indoor pool and 13 meeting rooms. Projected levered IRR is 13.3% with an equity multiple of 1.23x over the hold period. Distributions to investors for the quarter were paid at an annualized rate of 5.1% on contributed capital. Trailing twelve-month occupancy was 91.2% with an average daily rate of $117 and RevPAR indexing above the competitive set. Key risks include interest rate exposure, tenant rollover, construction cost overruns and local supply additions.

Observed Conditions

Elevators were last modernized 11 years ago and are operating without deficiency. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 17 months. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations.

Domestic water piping is copper and PVC with no evidence of widespread leakage. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 46 months. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $325,000. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Electrical service is adequate for current demand; select panels are nearing the end of their useful life.

Risk Considerations

Revenue is driven by transient corporate demand, group business and weekend leisure travel. The hotel operates under a franchise agreement with Crestwood Inn, with a complimentary breakfast, indoor pool and 19 meeting rooms. Key risks include interest rate exposure, tenant rollover, construction cost overruns and local supply additions. The investment thesis is based on stabilizing occupancy, completing the capital plan and capturing rent growth to market.

Trailing twelve-month occupancy was 90.7% with an average daily rate of $117 and RevPAR indexing above the competitive set. A product improvement plan for guest rooms and corridors is scheduled under the brand standards. The investment thesis is based on stabilizing occupancy, completing the capital plan and capturing rent growth to market. Revenue is driven by transient corporate demand, group business and weekend leisure travel. The business plan contemplates a hold period of 4 years with disposition upon achievement of target returns.

Observed Conditions

ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $401,000. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 10 months. Domestic water piping is copper and PVC with no evidence of widespread leakage.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Capital Project Schedule

Project	Category	Start	Completion	Budget	Spent to Date	Status
Fire alarm panel upgrade	Life Safety	10/22/25	Q1 2027	$677,000	$269,472	Complete
Pool resurfacing	Interior	03/03/26	Q2 2027	$496,000	$374,343	In progress
Signage / monument	Life Safety	10/03/24	Q4 2027	$823,000	$717,123	Approved
Exterior paint	Energy	02/23/25	Q3 2025	$85,000	$64,299	Complete
Elevator modernization	Building	11/07/23	Q1 2026	$50,000	$14,720	Deferred
Unit interior upgrades	Building	12/04/23	Q3 2025	$807,000	$266,337	Approved
Water heater replacement	Site	01/04/23	Q2 2025	$232,000	$20,811	Bidding
Parking lot resurfacing	Life Safety	02/24/24	Q4 2027	$418,000	$248,646	Approved
Lobby renovation	Building	03/19/25	Q3 2027	$818,000	$103,851	In progress
Unit interior upgrades	Site	10/18/23	Q1 2027	$351,000	$281,410	Deferred
Storefront glazing	Energy	10/20/24	Q2 2025	$658,000	$111,680	In progress
ADA compliance	Building	12/14/24	Q4 2026	$359,000	$215,510	Bidding
Sewer line repair	Life Safety	06/09/25	Q2 2025	$723,000	$227,008	In progress
Door hardware	Interior	01/15/25	Q4 2026	$862,000	$586,233	Complete
Security camera upgrade	Life Safety	09/11/23	Q4 2027	$333,000	$50,265	In progress
Roof replacement - Bldg D	Site	08/07/23	Q3 2026	$20,000	$11,173	Bidding
Pool resurfacing	Building	04/09/24	Q3 2026	$269,000	$30,068	Bidding
Water heater replacement	Site	06/11/26	Q3 2027	$722,000	$282,622	Deferred
Amenity renovation	Site	02/02/24	Q4 2025	$46,000	$39,778	Complete
Water heater replacement	Site	05/24/24	Q1 2027	$520,000	$281,524	Complete
Exterior paint	Interior	11/11/23	Q2 2025	$120,000	$113,153	Approved
Security camera upgrade	Energy	04/26/24	Q3 2025	$880,000	$194,474	Bidding
Security camera upgrade	Energy	08/16/24	Q3 2027	$394,000	$274,844	Approved
Parking lot resurfacing	Life Safety	07/28/24	Q4 2026	$48,000	$1,091	Bidding
Storefront glazing	Life Safety	07/10/23	Q2 2025	$617,000	$373,322	In progress
Exterior paint	Energy	06/13/24	Q2 2025	$893,000	$455,947	Approved
LED lighting retrofit	Site	09/21/24	Q4 2027	$11,000	$4,136	Approved
Roof replacement - Bldg C	Site	05/07/26	Q4 2025	$305,000	$242,527	Complete
Fire alarm panel upgrade	Building	05/28/25	Q4 2026	$730,000	$127,780	In progress
Parking lot resurfacing	Site	11/29/25	Q3 2026	$510,000	$414,116	Approved
Amenity renovation	Site	11/02/23	Q3 2026	$599,000	$573,067	Deferred
Landscape / irrigation	Site	05/02/26	Q1 2025	$541,000	$492,163	Approved
Fence replacement	Site	10/26/24	Q4 2027	$429,000	$80,569	Approved
Security camera upgrade	Energy	03/19/23	Q1 2025	$522,000	$486,153	Complete
Security camera upgrade	Building	06/17/23	Q2 2025	$775,000	$90,707	Bidding
Pool resurfacing	Life Safety	09/19/23	Q3 2026	$530,000	$284,690	Approved
ADA compliance	Life Safety	12/24/23	Q2 2027	$220,000	$2,857	Complete
Landscape / irrigation	Interior	08/20/26	Q3 2026	$722,000	$655,794	Deferred
Exterior paint	Interior	10/31/25	Q3 2025	$678,000	$388,475	Bidding
Roof replacement - Bldg D	Energy	09/21/24	Q2 2026	$847,000	$381,372	Complete
Fence replacement	Interior	05/18/23	Q1 2026	$148,000	$144,215	Approved
Pool resurfacing	Energy	08/09/26	Q4 2026	$621,000	$23,471	Bidding

Report generated 05/27/2024. Figures are unaudited and subject to change.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Deferred Maintenance

The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Domestic water piping is copper and PVC with no evidence of widespread leakage. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Elevators were last modernized 10 years ago and are operating without deficiency. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 15 months. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $110,000.

Elevators were last modernized 3 years ago and are operating without deficiency. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 40 months. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $112,000.

Business Plan Progress

The investment thesis is based on stabilizing occupancy, completing the capital plan and capturing rent growth to market. The hotel operates under a franchise agreement with Crestwood Inn, with a complimentary breakfast, indoor pool and 14 meeting rooms. Distributions to investors for the quarter were paid at an annualized rate of 5.4% on contributed capital. Leasing velocity improved during the period and management expects further upward pressure on in-place rents.

Projected levered IRR is 12.7% with an equity multiple of 1.3x over the hold period. Trailing twelve-month occupancy was 88.6% with an average daily rate of $117 and RevPAR indexing above the competitive set. Distributions to investors for the quarter were paid at an annualized rate of 3.4% on contributed capital. Leasing velocity improved during the period and management expects further upward pressure on in-place rents.

Deferred Maintenance

Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $367,000. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Electrical service is adequate for current demand; select panels are nearing the end of their useful life.

Electrical service is adequate for current demand; select panels are nearing the end of their useful life. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 35 months. Elevators were last modernized 11 years ago and are operating without deficiency. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Domestic water piping is copper and PVC with no evidence of widespread leakage.

Investment Overview

A product improvement plan for guest rooms and corridors is scheduled under the brand standards. Projected levered IRR is 13.2% with an equity multiple of 1.11x over the hold period. The investment thesis is based on stabilizing occupancy, completing the capital plan and capturing rent growth to market. The hotel operates under a franchise agreement with Crestwood Inn, with a complimentary breakfast, indoor pool and 4 meeting rooms. Leasing velocity improved during the period and management expects further upward pressure on in-place rents. Distributions to investors for the quarter were paid at an annualized rate of 4.5% on contributed capital.

Trailing twelve-month occupancy was 93.1% with an average daily rate of $117 and RevPAR indexing above the competitive set. Leasing velocity improved during the period and management expects further upward pressure on in-place rents. The hotel operates under a franchise agreement with Crestwood Inn, with a complimentary breakfast, indoor pool and 25 meeting rooms. The business plan contemplates a hold period of 9 years with disposition upon achievement of target returns. Revenue is driven by transient corporate demand, group business and weekend leisure travel.

Deferred Maintenance

Elevators were last modernized 6 years ago and are operating without deficiency. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 6 months. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $110,000. Electrical service is adequate for current demand; select panels are nearing the end of their useful life.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Capital Project Schedule

Project	Category	Start	Completion	Budget	Spent to Date	Status
Landscape / irrigation	Life Safety	01/02/25	Q4 2026	$781,000	$20,669	Bidding
Signage / monument	Life Safety	02/15/26	Q4 2027	$626,000	$120,625	Bidding
Amenity renovation	Building	02/07/25	Q4 2027	$418,000	$144,684	Approved
Parking lot resurfacing	Energy	02/18/23	Q1 2027	$547,000	$268,089	Deferred
Fence replacement	Building	02/26/26	Q3 2027	$770,000	$13,343	Bidding
Sewer line repair	Energy	10/05/26	Q4 2025	$520,000	$539,216	Bidding
Pool resurfacing	Interior	12/02/24	Q2 2027	$412,000	$353,109	Deferred
Fire alarm panel upgrade	Energy	04/14/25	Q1 2027	$743,000	$85,410	Bidding
Sewer line repair	Energy	04/22/23	Q1 2026	$31,000	$31,303	Complete
ADA compliance	Building	02/09/24	Q4 2025	$723,000	$732,829	Bidding
Pool resurfacing	Site	01/13/26	Q2 2025	$553,000	$32,645	Bidding
Door hardware	Interior	06/28/24	Q4 2025	$489,000	$33,844	Approved
Storefront glazing	Building	08/20/23	Q1 2027	$724,000	$721,919	Approved
ADA compliance	Life Safety	08/01/23	Q4 2025	$257,000	$155,234	Approved
Unit interior upgrades	Interior	03/04/26	Q4 2025	$725,000	$404,083	In progress
ADA compliance	Energy	10/31/24	Q4 2027	$499,000	$213,952	Bidding
Landscape / irrigation	Site	12/28/24	Q1 2026	$255,000	$262,705	Deferred
Unit interior upgrades	Building	06/02/26	Q1 2026	$721,000	$645,265	Bidding
Elevator modernization	Interior	10/13/24	Q4 2026	$698,000	$437,689	Bidding
Pool resurfacing	Interior	02/09/23	Q4 2026	$28,000	$2,924	Deferred
Elevator modernization	Site	09/18/23	Q3 2026	$646,000	$313,084	Approved
Security camera upgrade	Site	05/08/24	Q4 2027	$465,000	$239,460	Deferred
Unit interior upgrades	Life Safety	02/19/24	Q4 2027	$547,000	$202,227	Approved
ADA compliance	Site	07/19/23	Q2 2025	$442,000	$56,720	Complete
Security camera upgrade	Building	11/16/23	Q1 2026	$278,000	$201,672	Deferred
Door hardware	Interior	08/02/25	Q4 2026	$260,000	$23,497	In progress
Roof replacement - Bldg D	Interior	07/22/23	Q4 2027	$137,000	$100,100	Bidding
LED lighting retrofit	Interior	01/16/26	Q1 2025	$100,000	$90,367	Deferred
Sewer line repair	Interior	06/29/26	Q1 2027	$112,000	$54,694	Deferred
Elevator modernization	Interior	05/07/23	Q3 2027	$664,000	$659,520	Bidding
Landscape / irrigation	Life Safety	09/18/25	Q2 2026	$820,000	$761,857	Complete
Roof replacement - Bldg D	Interior	05/08/24	Q3 2025	$11,000	$4,745	Bidding
HVAC replacement	Building	04/22/26	Q2 2027	$727,000	$284,291	Bidding
Elevator modernization	Life Safety	09/06/23	Q2 2026	$437,000	$183,552	Complete
Exterior paint	Building	08/05/26	Q2 2027	$741,000	$724,159	Deferred
Roof replacement - Bldg D	Interior	07/22/25	Q3 2027	$409,000	$19,456	Deferred
Pool resurfacing	Interior	10/01/24	Q4 2027	$540,000	$3,489	Bidding
Security camera upgrade	Energy	10/11/23	Q1 2027	$346,000	$314,811	In progress
Pool resurfacing	Energy	08/29/23	Q3 2026	$670,000	$494,786	Bidding
Roof replacement - Bldg A	Interior	08/02/25	Q1 2027	$81,000	$42,709	In progress
Landscape / irrigation	Life Safety	11/15/24	Q4 2025	$387,000	$291,153	Complete
Storefront glazing	Site	03/19/25	Q4 2025	$254,000	$10,255	Complete

Report generated 05/27/2024. Figures are unaudited and subject to change.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Recommendations

Elevators were last modernized 3 years ago and are operating without deficiency. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 22 months. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Domestic water piping is copper and PVC with no evidence of widespread leakage. Electrical service is adequate for current demand; select panels are nearing the end of their useful life.

Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 3 months. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $431,000. Electrical service is adequate for current demand; select panels are nearing the end of their useful life.

Business Plan Progress

The hotel operates under a franchise agreement with Crestwood Inn, with a complimentary breakfast, indoor pool and 6 meeting rooms. Projected levered IRR is 4.1% with an equity multiple of 1.16x over the hold period. A product improvement plan for guest rooms and corridors is scheduled under the brand standards. Leasing velocity improved during the period and management expects further upward pressure on in-place rents.

Projected levered IRR is 3.3% with an equity multiple of 1.33x over the hold period. The investment thesis is based on stabilizing occupancy, completing the capital plan and capturing rent growth to market. The business plan contemplates a hold period of 8 years with disposition upon achievement of target returns. Key risks include interest rate exposure, tenant rollover, construction cost overruns and local supply additions.

Observed Conditions

Elevators were last modernized 10 years ago and are operating without deficiency. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 2 months. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $73,000. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months.

Elevators were last modernized 5 years ago and are operating without deficiency. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Domestic water piping is copper and PVC with no evidence of widespread leakage. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 4 months.

Business Plan Progress

Leasing velocity improved during the period and management expects further upward pressure on in-place rents. A product improvement plan for guest rooms and corridors is scheduled under the brand standards. The investment thesis is based on stabilizing occupancy, completing the capital plan and capturing rent growth to market. The business plan contemplates a hold period of 8 years with disposition upon achievement of target returns. Distributions to investors for the quarter were paid at an annualized rate of 4.6% on contributed capital. Key risks include interest rate exposure, tenant rollover, construction cost overruns and local supply additions.

The investment thesis is based on stabilizing occupancy, completing the capital plan and capturing rent growth to market. A product improvement plan for guest rooms and corridors is scheduled under the brand standards. Revenue is driven by transient corporate demand, group business and weekend leisure travel. The business plan contemplates a hold period of 10 years with disposition upon achievement of target returns.

Observed Conditions

ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $473,000. Domestic water piping is copper and PVC with no evidence of widespread leakage. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Elevators were last modernized 12 years ago and are operating without deficiency. Electrical service is adequate for current demand; select panels are nearing the end of their useful life.

Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 44 months. Domestic water piping is copper and PVC with no evidence of widespread leakage. Electrical service is adequate for current demand; select panels are nearing the end of their useful life.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Capital Project Schedule

Project	Category	Start	Completion	Budget	Spent to Date	Status
Lobby renovation	Energy	05/27/24	Q1 2027	$270,000	$210,375	Deferred
Roof replacement - Bldg D	Life Safety	08/21/25	Q4 2027	$791,000	$515,239	Approved
Landscape / irrigation	Energy	01/23/23	Q2 2026	$574,000	$259,036	Approved
Security camera upgrade	Site	02/05/25	Q4 2026	$57,000	$45,507	Approved
Sewer line repair	Site	07/16/26	Q3 2027	$324,000	$325,472	In progress
Fence replacement	Energy	01/21/23	Q3 2025	$205,000	$27,156	In progress
Storefront glazing	Site	09/08/24	Q4 2027	$24,000	$2,524	Complete
Exterior paint	Life Safety	08/20/24	Q2 2025	$546,000	$7,871	Complete
Unit interior upgrades	Building	02/12/24	Q3 2026	$749,000	$253,598	In progress
Fence replacement	Site	05/29/23	Q2 2027	$689,000	$311,622	Deferred
Sewer line repair	Site	05/29/25	Q1 2026	$366,000	$95,698	Complete
LED lighting retrofit	Building	10/16/26	Q3 2026	$153,000	$67,110	Approved
Fence replacement	Energy	02/05/25	Q2 2027	$826,000	$483,210	Deferred
Elevator modernization	Building	10/03/23	Q2 2025	$468,000	$397,432	Approved
Storefront glazing	Energy	12/22/23	Q1 2025	$258,000	$52,920	Deferred
Signage / monument	Building	01/03/23	Q3 2026	$556,000	$250,503	Complete
Door hardware	Life Safety	12/05/25	Q1 2026	$28,000	$15,057	Bidding
Roof replacement - Bldg B	Building	09/21/26	Q4 2025	$781,000	$772,484	Deferred
Fire alarm panel upgrade	Life Safety	07/21/25	Q2 2025	$276,000	$258,086	Deferred
Landscape / irrigation	Site	05/19/24	Q1 2026	$185,000	$37,507	Bidding
Door hardware	Interior	03/14/26	Q1 2025	$480,000	$476,529	Deferred
Fence replacement	Building	09/25/24	Q1 2027	$330,000	$11,129	In progress
Storefront glazing	Site	01/07/24	Q3 2025	$34,000	$9,288	In progress
Water heater replacement	Site	11/23/26	Q2 2027	$538,000	$153,665	Complete
Landscape / irrigation	Energy	06/15/25	Q1 2027	$94,000	$40,649	Bidding
Sewer line repair	Building	11/27/23	Q2 2027	$466,000	$250,172	Deferred
Roof replacement - Bldg A	Interior	05/01/23	Q4 2027	$351,000	$140,109	Bidding
Parking lot resurfacing	Interior	08/24/25	Q1 2025	$591,000	$90,669	Bidding
Door hardware	Site	08/04/25	Q2 2026	$325,000	$194,525	Complete
Amenity renovation	Energy	11/08/26	Q1 2027	$260,000	$108,099	Approved
Parking lot resurfacing	Site	12/05/26	Q3 2027	$480,000	$493,560	Bidding
Unit interior upgrades	Life Safety	03/07/25	Q2 2026	$202,000	$99,297	Complete
Roof replacement - Bldg A	Site	02/17/26	Q3 2027	$733,000	$22,114	In progress
Fire alarm panel upgrade	Energy	05/30/26	Q1 2025	$473,000	$108,270	Complete
Landscape / irrigation	Interior	09/06/23	Q1 2025	$220,000	$104,926	Bidding
Roof replacement - Bldg A	Interior	01/07/25	Q1 2027	$351,000	$203,223	Bidding
Unit interior upgrades	Life Safety	01/22/24	Q2 2026	$562,000	$233,544	Bidding
Lobby renovation	Site	02/13/25	Q3 2027	$377,000	$340,469	Deferred
Fence replacement	Building	06/16/23	Q1 2025	$201,000	$175,879	In progress
Elevator modernization	Energy	02/15/26	Q4 2026	$692,000	$260,831	Deferred
Fence replacement	Site	08/31/23	Q4 2025	$699,000	$562,948	In progress

Report generated 05/27/2024. Figures are unaudited and subject to change.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Recommendations

ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $403,000. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 48 months. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations.

Domestic water piping is copper and PVC with no evidence of widespread leakage. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 20 months. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $361,000. Elevators were last modernized 12 years ago and are operating without deficiency.

Risk Considerations

The investment thesis is based on stabilizing occupancy, completing the capital plan and capturing rent growth to market. A product improvement plan for guest rooms and corridors is scheduled under the brand standards. The hotel operates under a franchise agreement with Crestwood Inn, with a complimentary breakfast, indoor pool and 45 meeting rooms. Key risks include interest rate exposure, tenant rollover, construction cost overruns and local supply additions.

Projected levered IRR is 11.5% with an equity multiple of 1.42x over the hold period. The investment thesis is based on stabilizing occupancy, completing the capital plan and capturing rent growth to market. Leasing velocity improved during the period and management expects further upward pressure on in-place rents. Distributions to investors for the quarter were paid at an annualized rate of 7.9% on contributed capital.

Observed Conditions

Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 44 months. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Domestic water piping is copper and PVC with no evidence of widespread leakage. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $455,000. Elevators were last modernized 12 years ago and are operating without deficiency.

Elevators were last modernized 10 years ago and are operating without deficiency. Domestic water piping is copper and PVC with no evidence of widespread leakage. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $311,000. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 25 months.

Investment Overview

Key risks include interest rate exposure, tenant rollover, construction cost overruns and local supply additions. Distributions to investors for the quarter were paid at an annualized rate of 6.0% on contributed capital. Projected levered IRR is 5.5% with an equity multiple of 1.17x over the hold period. Trailing twelve-month occupancy was 90.2% with an average daily rate of $117 and RevPAR indexing above the competitive set. The business plan contemplates a hold period of 11 years with disposition upon achievement of target returns.

A product improvement plan for guest rooms and corridors is scheduled under the brand standards. Trailing twelve-month occupancy was 94.5% with an average daily rate of $117 and RevPAR indexing above the competitive set. Key risks include interest rate exposure, tenant rollover, construction cost overruns and local supply additions. The business plan contemplates a hold period of 5 years with disposition upon achievement of target returns.

Observed Conditions

Domestic water piping is copper and PVC with no evidence of widespread leakage. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Elevators were last modernized 5 years ago and are operating without deficiency. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 33 months.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Capital Project Schedule

Project	Category	Start	Completion	Budget	Spent to Date	Status
Unit interior upgrades	Energy	03/26/24	Q3 2027	$807,000	$806,939	Approved
Exterior paint	Site	11/30/26	Q3 2027	$697,000	$211,577	Deferred
ADA compliance	Interior	10/02/26	Q2 2027	$763,000	$233,392	Approved
Signage / monument	Building	01/04/26	Q3 2026	$229,000	$238,104	Deferred
Signage / monument	Building	07/25/25	Q4 2027	$774,000	$69,091	Approved
Parking lot resurfacing	Building	03/13/25	Q4 2026	$13,000	$2,980	Deferred
Storefront glazing	Site	05/30/26	Q4 2026	$164,000	$63,324	Complete
ADA compliance	Building	03/01/23	Q3 2027	$32,000	$30,385	Complete
Water heater replacement	Energy	08/24/25	Q1 2026	$652,000	$549,906	Complete
Sewer line repair	Energy	09/09/23	Q2 2027	$560,000	$480,502	Deferred
Door hardware	Building	11/04/26	Q3 2027	$426,000	$359,923	Approved
HVAC replacement	Interior	02/14/26	Q3 2026	$894,000	$874,367	Bidding
Elevator modernization	Site	09/22/23	Q4 2025	$748,000	$610,406	Deferred
Water heater replacement	Energy	07/30/24	Q3 2025	$62,000	$34,735	Approved
Fence replacement	Interior	04/12/25	Q2 2025	$795,000	$586,518	Deferred
Exterior paint	Site	06/16/23	Q4 2025	$806,000	$226,755	Complete
Signage / monument	Site	01/02/26	Q4 2027	$829,000	$98,964	Bidding
Exterior paint	Interior	09/27/26	Q4 2027	$722,000	$322,557	Deferred
Lobby renovation	Site	08/29/26	Q3 2025	$146,000	$22,268	Bidding
Door hardware	Site	10/03/26	Q1 2025	$287,000	$277,862	Complete
Lobby renovation	Interior	02/08/24	Q1 2025	$894,000	$409,203	In progress
Fence replacement	Interior	01/06/25	Q3 2026	$385,000	$314,704	Complete
Roof replacement - Bldg B	Life Safety	12/29/25	Q2 2027	$26,000	$8,822	Approved
Water heater replacement	Site	11/14/26	Q1 2027	$107,000	$31,150	Bidding
Lobby renovation	Site	10/12/24	Q1 2027	$333,000	$79,515	Bidding
LED lighting retrofit	Life Safety	07/30/24	Q2 2027	$249,000	$3,738	Deferred
Exterior paint	Energy	02/11/25	Q2 2026	$622,000	$208,852	Approved
Pool resurfacing	Energy	04/25/24	Q4 2025	$613,000	$430,593	In progress
Parking lot resurfacing	Energy	07/07/24	Q3 2026	$192,000	$31,637	Complete
Water heater replacement	Building	02/03/23	Q1 2025	$65,000	$54,637	Deferred
Landscape / irrigation	Energy	08/14/24	Q3 2027	$218,000	$57,278	Approved
Unit interior upgrades	Energy	02/05/25	Q4 2025	$410,000	$348,626	Approved
Storefront glazing	Site	02/11/26	Q1 2025	$143,000	$69,702	Approved
Sewer line repair	Building	12/10/25	Q1 2026	$871,000	$677,248	Bidding
Unit interior upgrades	Life Safety	02/27/25	Q1 2027	$764,000	$630,798	Deferred
Elevator modernization	Building	04/03/25	Q3 2027	$501,000	$448,136	Deferred
Roof replacement - Bldg C	Interior	12/17/26	Q2 2026	$681,000	$394,729	Complete
Exterior paint	Interior	01/23/26	Q3 2027	$520,000	$7,515	Bidding
Unit interior upgrades	Life Safety	08/23/25	Q2 2025	$31,000	$20,147	Bidding
Parking lot resurfacing	Energy	09/28/25	Q2 2026	$608,000	$242,781	Bidding

Report generated 05/27/2024. Figures are unaudited and subject to change.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Recommendations

The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Domestic water piping is copper and PVC with no evidence of widespread leakage. Elevators were last modernized 10 years ago and are operating without deficiency. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $240,000.

Electrical service is adequate for current demand; select panels are nearing the end of their useful life. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $293,000. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Elevators were last modernized 7 years ago and are operating without deficiency. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 14 months. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months.

Business Plan Progress

The business plan contemplates a hold period of 3 years with disposition upon achievement of target returns. Distributions to investors for the quarter were paid at an annualized rate of 4.3% on contributed capital. Trailing twelve-month occupancy was 90.9% with an average daily rate of $117 and RevPAR indexing above the competitive set. Revenue is driven by transient corporate demand, group business and weekend leisure travel. Projected levered IRR is 11.8% with an equity multiple of 1.27x over the hold period. A product improvement plan for guest rooms and corridors is scheduled under the brand standards.

Key risks include interest rate exposure, tenant rollover, construction cost overruns and local supply additions. Leasing velocity improved during the period and management expects further upward pressure on in-place rents. A product improvement plan for guest rooms and corridors is scheduled under the brand standards. The investment thesis is based on stabilizing occupancy, completing the capital plan and capturing rent growth to market. Trailing twelve-month occupancy was 90.7% with an average daily rate of $117 and RevPAR indexing above the competitive set. The business plan contemplates a hold period of 9 years with disposition upon achievement of target returns.

Observed Conditions

Elevators were last modernized 3 years ago and are operating without deficiency. Domestic water piping is copper and PVC with no evidence of widespread leakage. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 8 months. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $455,000.

Domestic water piping is copper and PVC with no evidence of widespread leakage. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Elevators were last modernized 5 years ago and are operating without deficiency.

Investment Overview

The investment thesis is based on stabilizing occupancy, completing the capital plan and capturing rent growth to market. A product improvement plan for guest rooms and corridors is scheduled under the brand standards. Projected levered IRR is 9.8% with an equity multiple of 1.22x over the hold period. Trailing twelve-month occupancy was 96.0% with an average daily rate of $117 and RevPAR indexing above the competitive set. The business plan contemplates a hold period of 7 years with disposition upon achievement of target returns.

Projected levered IRR is 5.8% with an equity multiple of 1.2x over the hold period. Trailing twelve-month occupancy was 89.7% with an average daily rate of $117 and RevPAR indexing above the competitive set. Key risks include interest rate exposure, tenant rollover, construction cost overruns and local supply additions. The business plan contemplates a hold period of 7 years with disposition upon achievement of target returns. A product improvement plan for guest rooms and corridors is scheduled under the brand standards.

Deferred Maintenance

The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Domestic water piping is copper and PVC with no evidence of widespread leakage. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 36 months.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Capital Project Schedule

Project	Category	Start	Completion	Budget	Spent to Date	Status
ADA compliance	Building	10/22/24	Q2 2026	$248,000	$239,761	Complete
Exterior paint	Site	01/25/26	Q1 2026	$533,000	$325,390	Approved
Landscape / irrigation	Building	04/06/25	Q4 2026	$632,000	$545,032	In progress
Security camera upgrade	Building	12/07/26	Q1 2027	$120,000	$14,771	Deferred
Elevator modernization	Interior	10/29/25	Q2 2026	$286,000	$88,275	In progress
Storefront glazing	Energy	05/25/23	Q2 2025	$372,000	$268,334	In progress
Security camera upgrade	Energy	02/08/24	Q3 2026	$840,000	$778,085	Bidding
Fire alarm panel upgrade	Site	03/05/26	Q4 2025	$487,000	$342,414	Bidding
Lobby renovation	Building	04/07/23	Q1 2025	$708,000	$155,670	In progress
Roof replacement - Bldg D	Building	04/17/25	Q1 2026	$298,000	$1,397	Deferred
Security camera upgrade	Building	08/26/25	Q2 2025	$454,000	$230,241	Complete
Lobby renovation	Site	02/10/26	Q2 2026	$371,000	$253,860	Bidding
Exterior paint	Life Safety	10/21/25	Q3 2025	$639,000	$383,298	Approved
Door hardware	Site	04/07/26	Q2 2025	$742,000	$480,680	Bidding
Pool resurfacing	Life Safety	06/22/24	Q4 2026	$454,000	$414,174	In progress
Signage / monument	Life Safety	09/13/26	Q2 2025	$581,000	$587,648	In progress
Lobby renovation	Site	06/03/25	Q1 2025	$448,000	$169,485	In progress
Fire alarm panel upgrade	Building	09/24/26	Q3 2027	$242,000	$129,623	Complete
LED lighting retrofit	Life Safety	06/17/26	Q1 2027	$635,000	$316,549	Approved
Exterior paint	Site	11/18/23	Q3 2027	$549,000	$246,335	In progress
LED lighting retrofit	Energy	10/03/23	Q2 2027	$648,000	$358,833	Approved
Unit interior upgrades	Energy	08/08/23	Q1 2026	$839,000	$58,377	Bidding
Unit interior upgrades	Interior	01/08/24	Q2 2027	$681,000	$102,265	Bidding
Parking lot resurfacing	Life Safety	01/15/23	Q4 2025	$567,000	$186,411	Complete
Exterior paint	Energy	06/09/23	Q2 2027	$524,000	$81,131	Approved
Door hardware	Interior	06/05/23	Q2 2026	$271,000	$43,848	In progress
Landscape / irrigation	Energy	02/15/24	Q1 2025	$892,000	$593,300	In progress
Sewer line repair	Building	06/13/24	Q2 2027	$555,000	$27,996	Deferred
Unit interior upgrades	Interior	11/14/25	Q4 2025	$20,000	$1,235	Approved
Parking lot resurfacing	Energy	12/15/26	Q2 2027	$263,000	$145,541	Complete
Landscape / irrigation	Interior	03/31/26	Q2 2026	$741,000	$495,428	Approved
Roof replacement - Bldg D	Life Safety	05/31/25	Q2 2026	$264,000	$150,660	Bidding
Fire alarm panel upgrade	Life Safety	10/02/24	Q2 2026	$30,000	$14,031	Approved
Water heater replacement	Energy	04/15/24	Q4 2026	$751,000	$87,390	Complete
Elevator modernization	Site	08/19/25	Q1 2026	$481,000	$154,222	Approved
ADA compliance	Site	03/25/25	Q3 2027	$93,000	$61,922	Bidding
Unit interior upgrades	Energy	01/13/23	Q4 2025	$725,000	$650,082	Complete
Parking lot resurfacing	Life Safety	05/29/26	Q4 2026	$361,000	$372,605	Complete
Landscape / irrigation	Site	08/17/23	Q4 2027	$33,000	$11,143	Approved
ADA compliance	Life Safety	06/25/25	Q2 2025	$691,000	$109,036	Bidding

Report generated 05/27/2024. Figures are unaudited and subject to change.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Deferred Maintenance

Electrical service is adequate for current demand; select panels are nearing the end of their useful life. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $70,000. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 22 months. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Elevators were last modernized 12 years ago and are operating without deficiency.

Domestic water piping is copper and PVC with no evidence of widespread leakage. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Electrical service is adequate for current demand; select panels are nearing the end of their useful life.

Risk Considerations

Leasing velocity improved during the period and management expects further upward pressure on in-place rents. The investment thesis is based on stabilizing occupancy, completing the capital plan and capturing rent growth to market. The business plan contemplates a hold period of 3 years with disposition upon achievement of target returns. Revenue is driven by transient corporate demand, group business and weekend leisure travel. Distributions to investors for the quarter were paid at an annualized rate of 3.2% on contributed capital. The hotel operates under a franchise agreement with Crestwood Inn, with a complimentary breakfast, indoor pool and 5 meeting rooms.

Key risks include interest rate exposure, tenant rollover, construction cost overruns and local supply additions. The business plan contemplates a hold period of 6 years with disposition upon achievement of target returns. The investment thesis is based on stabilizing occupancy, completing the capital plan and capturing rent growth to market. The hotel operates under a franchise agreement with Crestwood Inn, with a complimentary breakfast, indoor pool and 30 meeting rooms. Revenue is driven by transient corporate demand, group business and weekend leisure travel.

Recommendations

Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 18 months. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $205,000. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Domestic water piping is copper and PVC with no evidence of widespread leakage. Elevators were last modernized 8 years ago and are operating without deficiency.

ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $299,000. Elevators were last modernized 4 years ago and are operating without deficiency. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Domestic water piping is copper and PVC with no evidence of widespread leakage. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 19 months.

Business Plan Progress

Distributions to investors for the quarter were paid at an annualized rate of 4.0% on contributed capital. Revenue is driven by transient corporate demand, group business and weekend leisure travel. The investment thesis is based on stabilizing occupancy, completing the capital plan and capturing rent growth to market. Key risks include interest rate exposure, tenant rollover, construction cost overruns and local supply additions. Projected levered IRR is 4.3% with an equity multiple of 1.42x over the hold period. The business plan contemplates a hold period of 5 years with disposition upon achievement of target returns.

Key risks include interest rate exposure, tenant rollover, construction cost overruns and local supply additions. The hotel operates under a franchise agreement with Crestwood Inn, with a complimentary breakfast, indoor pool and 41 meeting rooms. A product improvement plan for guest rooms and corridors is scheduled under the brand standards. Revenue is driven by transient corporate demand, group business and weekend leisure travel. The investment thesis is based on stabilizing occupancy, completing the capital plan and capturing rent growth to market.

Deferred Maintenance

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only