PHASE I ENVIRONMENTAL SITE ASSESSMENT

Osprey Secure Storage | Phoenix, AZ

Site	Osprey Secure Storage
Address	7739 Market Avenue, Phoenix, AZ 15898
Prepared For	Sunbelt Ridge Acquisitions
Report Date	October 10, 2020
Standard	ASTM E1527-21

Access and Utilities

The site is not located within a designated 100-year floodplain according to the FEMA flood map in effect. The site contains approximately 15.15 acres and is generally level with frontage along Market Avenue. Utilities, including electric, natural gas and telecommunications, are available to the site from the street. Soils are typical of the region and no evidence of unsuitable conditions was observed at the time of inspection. Access to the site is provided by 19 curb cuts and the property is served by municipal water and sanitary sewer.

The site is not located within a designated 100-year floodplain according to the FEMA flood map in effect. Soils are typical of the region and no evidence of unsuitable conditions was observed at the time of inspection. The site contains approximately 29.29 acres and is generally level with frontage along Market Avenue. Access to the site is provided by 17 curb cuts and the property is served by municipal water and sanitary sewer.

Findings and Opinions

No evidence of underground storage tanks, stained soils or stressed vegetation was observed during the site reconnaissance. Historical sources indicate the site was previously used for agricultural and light commercial purposes. A former dry cleaner located 5 blocks to the north is listed as a closed case and is not expected to impact the site. Based on the age of construction, an asbestos operations and maintenance program is recommended for suspect materials.

A review of regulatory databases identified no listings for the subject property within the ASTM-specified search distances. Historical sources indicate the site was previously used for agricultural and light commercial purposes. Based on the age of construction, an asbestos operations and maintenance program is recommended for suspect materials. No recognized environmental conditions (RECs) were identified in connection with the subject property. A former dry cleaner located 5 blocks to the north is listed as a closed case and is not expected to impact the site. No evidence of underground storage tanks, stained soils or stressed vegetation was observed during the site reconnaissance.

Site Description

The site is not located within a designated 100-year floodplain according to the FEMA flood map in effect. Soils are typical of the region and no evidence of unsuitable conditions was observed at the time of inspection. Surrounding land uses include residential, commercial and light industrial properties of similar vintage. Access to the site is provided by 47 curb cuts and the property is served by municipal water and sanitary sewer. The site contains approximately 45.45 acres and is generally level with frontage along Market Avenue. Utilities, including electric, natural gas and telecommunications, are available to the site from the street.

Soils are typical of the region and no evidence of unsuitable conditions was observed at the time of inspection. Surrounding land uses include residential, commercial and light industrial properties of similar vintage. Utilities, including electric, natural gas and telecommunications, are available to the site from the street. The site contains approximately 26.26 acres and is generally level with frontage along Market Avenue.

Records Review

A review of regulatory databases identified no listings for the subject property within the ASTM-specified search distances. No recognized environmental conditions (RECs) were identified in connection with the subject property. No evidence of underground storage tanks, stained soils or stressed vegetation was observed during the site reconnaissance. Historical sources indicate the site was previously used for agricultural and light commercial purposes. A former dry cleaner located 2 blocks to the north is listed as a closed case and is not expected to impact the site. Based on the age of construction, an asbestos operations and maintenance program is recommended for suspect materials.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only