PHASE I ENVIRONMENTAL SITE ASSESSMENT

Cedar Station District | Orlando, FL

Site	Cedar Station District
Address	8117 Heritage Street, Orlando, FL 87518
Prepared For	Juniper Peak Real Estate Fund
Report Date	April 4, 2022
Standard	ASTM E1527-21

Topography and Flood Zone

Soils are typical of the region and no evidence of unsuitable conditions was observed at the time of inspection. The site is not located within a designated 100-year floodplain according to the FEMA flood map in effect. Surrounding land uses include residential, commercial and light industrial properties of similar vintage. The site contains approximately 6.6 acres and is generally level with frontage along Heritage Street.

Soils are typical of the region and no evidence of unsuitable conditions was observed at the time of inspection. Surrounding land uses include residential, commercial and light industrial properties of similar vintage. Utilities, including electric, natural gas and telecommunications, are available to the site from the street. The site is not located within a designated 100-year floodplain according to the FEMA flood map in effect.

Records Review

No recognized environmental conditions (RECs) were identified in connection with the subject property. No evidence of underground storage tanks, stained soils or stressed vegetation was observed during the site reconnaissance. Vapor encroachment screening did not identify a condition requiring further evaluation. Historical sources indicate the site was previously used for agricultural and light commercial purposes. A former dry cleaner located 8 blocks to the north is listed as a closed case and is not expected to impact the site. Based on the age of construction, an asbestos operations and maintenance program is recommended for suspect materials.

No recognized environmental conditions (RECs) were identified in connection with the subject property. Vapor encroachment screening did not identify a condition requiring further evaluation. Historical sources indicate the site was previously used for agricultural and light commercial purposes. Based on the age of construction, an asbestos operations and maintenance program is recommended for suspect materials. A former dry cleaner located 4 blocks to the north is listed as a closed case and is not expected to impact the site. No evidence of underground storage tanks, stained soils or stressed vegetation was observed during the site reconnaissance.

Site Description

The site is not located within a designated 100-year floodplain according to the FEMA flood map in effect. Surrounding land uses include residential, commercial and light industrial properties of similar vintage. Utilities, including electric, natural gas and telecommunications, are available to the site from the street. The site contains approximately 35.35 acres and is generally level with frontage along Heritage Street. Access to the site is provided by 24 curb cuts and the property is served by municipal water and sanitary sewer. Soils are typical of the region and no evidence of unsuitable conditions was observed at the time of inspection.

Soils are typical of the region and no evidence of unsuitable conditions was observed at the time of inspection. Utilities, including electric, natural gas and telecommunications, are available to the site from the street. The site is not located within a designated 100-year floodplain according to the FEMA flood map in effect. Access to the site is provided by 21 curb cuts and the property is served by municipal water and sanitary sewer. Surrounding land uses include residential, commercial and light industrial properties of similar vintage. The site contains approximately 22.22 acres and is generally level with frontage along Heritage Street.

Records Review

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Site Description

Soils are typical of the region and no evidence of unsuitable conditions was observed at the time of inspection. Surrounding land uses include residential, commercial and light industrial properties of similar vintage. Access to the site is provided by 5 curb cuts and the property is served by municipal water and sanitary sewer. The site contains approximately 6.6 acres and is generally level with frontage along Heritage Street. Utilities, including electric, natural gas and telecommunications, are available to the site from the street. The site is not located within a designated 100-year floodplain according to the FEMA flood map in effect.

The site contains approximately 5.5 acres and is generally level with frontage along Heritage Street. Utilities, including electric, natural gas and telecommunications, are available to the site from the street. Access to the site is provided by 39 curb cuts and the property is served by municipal water and sanitary sewer. Surrounding land uses include residential, commercial and light industrial properties of similar vintage. The site is not located within a designated 100-year floodplain according to the FEMA flood map in effect. Soils are typical of the region and no evidence of unsuitable conditions was observed at the time of inspection.

Findings and Opinions

Vapor encroachment screening did not identify a condition requiring further evaluation. Based on the age of construction, an asbestos operations and maintenance program is recommended for suspect materials. A review of regulatory databases identified no listings for the subject property within the ASTM-specified search distances. A former dry cleaner located 1 blocks to the north is listed as a closed case and is not expected to impact the site.

A review of regulatory databases identified no listings for the subject property within the ASTM-specified search distances. No evidence of underground storage tanks, stained soils or stressed vegetation was observed during the site reconnaissance. A former dry cleaner located 4 blocks to the north is listed as a closed case and is not expected to impact the site. Historical sources indicate the site was previously used for agricultural and light commercial purposes.

Topography and Flood Zone

Access to the site is provided by 11 curb cuts and the property is served by municipal water and sanitary sewer. The site is not located within a designated 100-year floodplain according to the FEMA flood map in effect. Soils are typical of the region and no evidence of unsuitable conditions was observed at the time of inspection. Utilities, including electric, natural gas and telecommunications, are available to the site from the street. The site contains approximately 37.37 acres and is generally level with frontage along Heritage Street. Surrounding land uses include residential, commercial and light industrial properties of similar vintage.

Access to the site is provided by 45 curb cuts and the property is served by municipal water and sanitary sewer. Soils are typical of the region and no evidence of unsuitable conditions was observed at the time of inspection. The site contains approximately 16.16 acres and is generally level with frontage along Heritage Street. The site is not located within a designated 100-year floodplain according to the FEMA flood map in effect. Surrounding land uses include residential, commercial and light industrial properties of similar vintage. Utilities, including electric, natural gas and telecommunications, are available to the site from the street.

Findings and Opinions

A former dry cleaner located 4 blocks to the north is listed as a closed case and is not expected to impact the site. Based on the age of construction, an asbestos operations and maintenance program is recommended for suspect materials. A review of regulatory databases identified no listings for the subject property within the ASTM-specified search distances. No evidence of underground storage tanks, stained soils or stressed vegetation was observed during the site reconnaissance.

Based on the age of construction, an asbestos operations and maintenance program is recommended for suspect materials. Historical sources indicate the site was previously used for agricultural and light commercial purposes. Vapor encroachment screening did not identify a condition requiring further evaluation. A former dry cleaner located 9 blocks to the north is listed as a closed case and is not expected to impact the site.

Access and Utilities

Utilities, including electric, natural gas and telecommunications, are available to the site from the street. The site contains approximately 6.6 acres and is generally level with frontage along Heritage Street. Access to the site is provided by 35 curb cuts and the property is served by municipal water and sanitary sewer. The site is not located within a designated 100-year floodplain according to the FEMA flood map in effect. Soils are typical of the region and no evidence of unsuitable conditions was observed at the time of inspection. Surrounding land uses include residential, commercial and light industrial properties of similar vintage.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Regulatory Database Search Results

Database	Search Radius (mi)	Sites Within Radius	Subject Property?	Further Evaluation
NPL (Superfund)	0.5	0	No	None
CERCLIS / SEMS	0.5	2	No	Reviewed - no action
RCRA - Generators	0.25	0	No	None
RCRA - TSD	1.0	0	No	None
LUST	0.25	4	No	None
UST	0.25	2	No	Reviewed - no action
State Hazardous Waste Sites	1.0	1	No	None
Brownfields	1.0	0	No	Reviewed - no action
Engineering Controls	0.25	2	No	Reviewed - no action
Institutional Controls	0.25	7	No	Reviewed - no action
ERNS	0.5	7	No	Reviewed - no action
Drycleaner Facilities	0.25	1	No	Reviewed - no action
Solid Waste Landfills	1.0	4	No	None
Voluntary Cleanup	1.0	0	No	Reviewed - no action
Historical Auto Stations	0.25	0	No	None
NPL (Superfund)	1.0	0	No	Reviewed - no action
CERCLIS / SEMS	0.5	0	No	None
RCRA - Generators	0.25	0	No	None
RCRA - TSD	1.0	0	No	None
LUST	1.0	4	No	Reviewed - no action
UST	0.25	7	No	None
State Hazardous Waste Sites	0.5	0	No	Reviewed - no action
Brownfields	0.5	0	No	None
Engineering Controls	0.25	2	No	None
Institutional Controls	1.0	7	No	Reviewed - no action
ERNS	0.25	7	No	Reviewed - no action
Drycleaner Facilities	0.25	7	No	None
Solid Waste Landfills	1.0	0	No	None
Voluntary Cleanup	0.5	2	No	None
Historical Auto Stations	0.5	2	No	None

Report generated 04/04/2022. Figures are unaudited and subject to change.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Certification

I certify that, to the best of my knowledge and belief, the statements of fact contained in this report are true and correct and that I have no present or prospective interest in Cedar Station District and no personal interest with respect to the parties involved.

The analyses, opinions and conclusions are limited only by the reported assumptions and limiting conditions. The inspection of the property was performed on March 17, 2022.

_____

Fatima Vasquez, RPLS

Bluewater Site Sciences

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only