PROPERTY CONDITION ASSESSMENT

Quarry Station District | Cleveland, OH

Property	Quarry Station District
Address	3072 Ridge Avenue, Cleveland, OH 69868
Site Visit Date	January 7, 2022
Client	Tidewater Core Fund
Immediate Repairs	$79,000

Building Systems

Life-safety systems include a fully sprinklered building, addressable fire alarm panel and emergency lighting. The project combines ground-floor retail and restaurant space with upper-level residential and office components. Exterior finishes comprise brick veneer, fiber-cement siding and aluminum storefront glazing in good condition. The property is walkable to transit, with 41 structured parking spaces shared between uses. The structure is of wood-frame, masonry and steel-frame construction on a slab-on-grade foundation. The roof is a 22-year membrane system with an estimated remaining useful life of 12 years.

Quarry Station District was originally constructed in 1964 and consists of 344,993 SF in a building of 22 stories. The roof is a 11-year membrane system with an estimated remaining useful life of 11 years. The project combines ground-floor retail and restaurant space with upper-level residential and office components. The structure is of wood-frame, masonry and steel-frame construction on a slab-on-grade foundation. Residential units are leased on 12-month terms while the commercial component is leased on a triple net basis. Life-safety systems include a fully sprinklered building, addressable fire alarm panel and emergency lighting.

Observed Conditions

Domestic water piping is copper and PVC with no evidence of widespread leakage. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 12 months. Electrical service is adequate for current demand; select panels are nearing the end of their useful life.

Domestic water piping is copper and PVC with no evidence of widespread leakage. Elevators were last modernized 10 years ago and are operating without deficiency. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 24 months. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months.

Construction Details

Percentage rent and CAM reimbursements are tracked separately for the commercial component. Common area interiors have been refreshed within the last 10 years and are in average to good condition. The property is walkable to transit, with 3 structured parking spaces shared between uses. The project combines ground-floor retail and restaurant space with upper-level residential and office components.

Common area interiors have been refreshed within the last 4 years and are in average to good condition. The structure is of wood-frame, masonry and steel-frame construction on a slab-on-grade foundation. Life-safety systems include a fully sprinklered building, addressable fire alarm panel and emergency lighting. The property is walkable to transit, with 18 structured parking spaces shared between uses.

Observed Conditions

Elevators were last modernized 3 years ago and are operating without deficiency. Domestic water piping is copper and PVC with no evidence of widespread leakage. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 20 months.

Elevators were last modernized 7 years ago and are operating without deficiency. Domestic water piping is copper and PVC with no evidence of widespread leakage. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months.

Construction Details

Exterior finishes comprise brick veneer, fiber-cement siding and aluminum storefront glazing in good condition. Life-safety systems include a fully sprinklered building, addressable fire alarm panel and emergency lighting. Common area interiors have been refreshed within the last 4 years and are in average to good condition. The structure is of wood-frame, masonry and steel-frame construction on a slab-on-grade foundation. Mechanical systems include rooftop package units and central plant equipment of varying age.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Building Systems

The property is walkable to transit, with 28 structured parking spaces shared between uses. The structure is of wood-frame, masonry and steel-frame construction on a slab-on-grade foundation. Residential units are leased on 12-month terms while the commercial component is leased on a triple net basis. Life-safety systems include a fully sprinklered building, addressable fire alarm panel and emergency lighting. The roof is a 25-year membrane system with an estimated remaining useful life of 4 years. The project combines ground-floor retail and restaurant space with upper-level residential and office components.

Percentage rent and CAM reimbursements are tracked separately for the commercial component. Exterior finishes comprise brick veneer, fiber-cement siding and aluminum storefront glazing in good condition. The roof is a 26-year membrane system with an estimated remaining useful life of 4 years. The property is walkable to transit, with 6 structured parking spaces shared between uses. The structure is of wood-frame, masonry and steel-frame construction on a slab-on-grade foundation. Life-safety systems include a fully sprinklered building, addressable fire alarm panel and emergency lighting.

Deferred Maintenance

Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 13 months. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Domestic water piping is copper and PVC with no evidence of widespread leakage. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $400,000. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Elevators were last modernized 5 years ago and are operating without deficiency.

Domestic water piping is copper and PVC with no evidence of widespread leakage. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 25 months. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Elevators were last modernized 7 years ago and are operating without deficiency. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $9,000.

Construction Details

Mechanical systems include rooftop package units and central plant equipment of varying age. The property is walkable to transit, with 2 structured parking spaces shared between uses. Residential units are leased on 12-month terms while the commercial component is leased on a triple net basis. The project combines ground-floor retail and restaurant space with upper-level residential and office components. Common area interiors have been refreshed within the last 11 years and are in average to good condition.

The property is walkable to transit, with 12 structured parking spaces shared between uses. Common area interiors have been refreshed within the last 10 years and are in average to good condition. Percentage rent and CAM reimbursements are tracked separately for the commercial component. Mechanical systems include rooftop package units and central plant equipment of varying age.

Recommendations

Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $101,000. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 18 months.

Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Domestic water piping is copper and PVC with no evidence of widespread leakage. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $279,000.

Improvements Description

Quarry Station District was originally constructed in 1964 and consists of 344,993 SF in a building of 21 stories. Exterior finishes comprise brick veneer, fiber-cement siding and aluminum storefront glazing in good condition. The structure is of wood-frame, masonry and steel-frame construction on a slab-on-grade foundation. The property is walkable to transit, with 39 structured parking spaces shared between uses. Percentage rent and CAM reimbursements are tracked separately for the commercial component.

The structure is of wood-frame, masonry and steel-frame construction on a slab-on-grade foundation. Exterior finishes comprise brick veneer, fiber-cement siding and aluminum storefront glazing in good condition. Life-safety systems include a fully sprinklered building, addressable fire alarm panel and emergency lighting. Residential units are leased on 12-month terms while the commercial component is leased on a triple net basis.

Deferred Maintenance

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Immediate Repairs and Replacement Reserve Schedule

System	Age (yrs)	EUL	RUL	Condition	Immediate	Reserve (10-yr)
Roof	15	39	24	Good	$37,000	$142,000
Paving	3	13	10	Good	$33,000	$31,000
HVAC	1	10	9	Good	$24,000	$269,000
Plumbing	12	33	21	Fair	$12,000	$217,000
Electrical	4	11	7	Poor	$30,000	$197,000
Elevators	4	20	16	Fair	$7,000	$93,000
Fire/Life Safety	3	27	24	Good	$9,000	$71,000
Windows	8	11	3	Poor	$22,000	$268,000
Siding/Facade	8	31	23	Poor	$3,000	$121,000
Flooring	29	38	9	Good	$5,000	$202,000
Appliances	24	24	0	Poor	$6,000	$147,000
Landscaping	7	27	20	Poor	$28,000	$133,000
Pool/Amenity	12	18	6	Fair	$9,000	$253,000
Signage	15	35	20	Good	$20,000	$180,000
Fencing	33	33	0	Fair	$8,000	$119,000
Roof (2)	1	10	9	Fair	$14,000	$140,000
Paving (2)	19	28	9	Good	$30,000	$239,000
HVAC (2)	14	34	20	Fair	$5,000	$152,000
Plumbing (2)	7	27	20	Fair	$37,000	$151,000
Electrical (2)	23	34	11	Good	$28,000	$107,000
Elevators (2)	21	21	0	Fair	$17,000	$79,000
Fire/Life Safety (2)	29	40	11	Fair	$14,000	$170,000
Windows (2)	10	29	19	Fair	$6,000	$28,000
Siding/Facade (2)	2	21	19	Fair	$24,000	$67,000
Flooring (2)	8	11	3	Good	$7,000	$270,000
Appliances (2)	31	40	9	Good	$1,000	$93,000
Landscaping (2)	9	37	28	Fair	$22,000	$128,000
Pool/Amenity (2)	7	23	16	Fair	$8,000	$76,000
Signage (2)	22	28	6	Poor	$9,000	$64,000
Fencing (2)	24	26	2	Good	$38,000	$5,000

Report generated 01/07/2022. Figures are unaudited and subject to change.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Findings and Opinions of Cost

Item	Location	Observed Condition	Recommended Action	Priority	Est. Cost
Fire extinguishers	Roof	Expired tags	Service	Reserve	$67,000
Asphalt paving	Common	Alligator cracking	Mill and overlay	Immediate	$22,000
Sprinkler heads	Common	Painted heads	Replace	Immediate	$31,500
Roof membrane	Roof	Ponding / seams	Re-seal and repair	Reserve	$51,500
Handrail	Common	Loose	Secure	Immediate	$71,000
Dumpster enclosure	Bldg B	Damaged gate	Repair	Reserve	$11,500
Window sealant	Bldg A	Failed	Re-caulk	Year 2-5	$88,500
Dumpster enclosure	Bldg B	Damaged gate	Repair	Year 2-5	$73,000
HVAC unit	Bldg A	Beyond useful life	Replace RTU	Year 2-5	$83,500
Asphalt paving	Roof	Alligator cracking	Mill and overlay	Reserve	$13,000
Window sealant	Bldg B	Failed	Re-caulk	Reserve	$76,000
Asphalt paving	Bldg B	Alligator cracking	Mill and overlay	Year 1	$80,000
HVAC unit	Site	Beyond useful life	Replace RTU	Year 2-5	$86,500
HVAC unit	Roof	Beyond useful life	Replace RTU	Immediate	$18,000
Stair treads	Roof	Worn / loose	Replace treads	Year 1	$75,500
Water heater	Common	Corrosion	Replace	Reserve	$56,500
HVAC unit	Bldg B	Beyond useful life	Replace RTU	Year 2-5	$31,500
Window sealant	Bldg B	Failed	Re-caulk	Year 2-5	$77,000
Fire extinguishers	Bldg A	Expired tags	Service	Reserve	$67,500
Stair treads	Bldg B	Worn / loose	Replace treads	Reserve	$37,000
Fire extinguishers	Bldg A	Expired tags	Service	Year 2-5	$63,500
HVAC unit	Mechanical	Beyond useful life	Replace RTU	Year 1	$1,500
Water heater	Mechanical	Corrosion	Replace	Immediate	$53,000
HVAC unit	Bldg A	Beyond useful life	Replace RTU	Immediate	$48,000
Roof membrane	Bldg B	Ponding / seams	Re-seal and repair	Year 2-5	$59,000
Window sealant	Bldg A	Failed	Re-caulk	Year 1	$88,500
HVAC unit	Bldg A	Beyond useful life	Replace RTU	Reserve	$13,000
Sprinkler heads	Bldg B	Painted heads	Replace	Reserve	$65,500
Dumpster enclosure	Bldg A	Damaged gate	Repair	Immediate	$55,000
Stair treads	Common	Worn / loose	Replace treads	Year 1	$41,500
Asphalt paving	Bldg A	Alligator cracking	Mill and overlay	Reserve	$27,500
Handrail	Bldg B	Loose	Secure	Immediate	$28,000
Sprinkler heads	Bldg A	Painted heads	Replace	Immediate	$36,000
Sidewalk	Site	Trip hazards	Grind / replace	Year 2-5	$65,000
Sidewalk	Bldg B	Trip hazards	Grind / replace	Reserve	$8,500
Water heater	Mechanical	Corrosion	Replace	Immediate	$30,000
Asphalt paving	Mechanical	Alligator cracking	Mill and overlay	Reserve	$76,500
Dumpster enclosure	Common	Damaged gate	Repair	Year 2-5	$13,500
Handrail	Roof	Loose	Secure	Year 1	$57,500
Roof membrane	Site	Ponding / seams	Re-seal and repair	Reserve	$46,500
Dumpster enclosure	Bldg A	Damaged gate	Repair	Immediate	$29,500

Report generated 01/07/2022. Figures are unaudited and subject to change.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Certification

I certify that, to the best of my knowledge and belief, the statements of fact contained in this report are true and correct and that I have no present or prospective interest in Quarry Station District and no personal interest with respect to the parties involved.

The analyses, opinions and conclusions are limited only by the reported assumptions and limiting conditions. The inspection of the property was performed on December 30, 2021.

_____

Jerome Foster, RPLS

Structura Property Assessments

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only