CAPITAL IMPROVEMENT PLAN

Eastlake Ridgeline Collegiate Commons | Birmingham, AL

Property	Eastlake Ridgeline Collegiate Commons
Plan Date	April 23, 2026
Prepared For	Anchorage Meadow Partners
Total Plan Budget	$410,000

Capital Project Schedule

Project	Category	Start	Completion	Budget	Spent to Date	Status
Pool resurfacing	Energy	01/14/26	Q4 2026	$661,000	$421,263	Deferred
Door hardware	Building	04/13/24	Q4 2026	$191,000	$155,749	Complete
Fire alarm panel upgrade	Life Safety	07/10/23	Q3 2026	$350,000	$364,118	Complete
Water heater replacement	Building	09/15/23	Q2 2027	$526,000	$396,548	In progress
Unit interior upgrades	Energy	08/13/25	Q2 2025	$563,000	$132,275	In progress
Amenity renovation	Building	01/06/23	Q1 2026	$401,000	$179,257	In progress
Exterior paint	Interior	11/18/25	Q1 2026	$617,000	$274,856	Complete
Sewer line repair	Building	11/07/23	Q2 2027	$190,000	$124,906	Complete
Unit interior upgrades	Site	05/04/26	Q3 2026	$362,000	$88,786	Deferred
Pool resurfacing	Life Safety	01/13/26	Q2 2025	$634,000	$282,548	Approved
Sewer line repair	Interior	02/08/23	Q2 2026	$8,000	$4,272	Bidding
Storefront glazing	Building	03/09/26	Q3 2027	$885,000	$384,457	Complete
Security camera upgrade	Life Safety	07/19/26	Q2 2027	$612,000	$101,345	In progress
Unit interior upgrades	Energy	02/01/26	Q1 2026	$886,000	$498,996	Deferred
LED lighting retrofit	Life Safety	06/17/24	Q2 2025	$347,000	$210,086	Approved
Unit interior upgrades	Interior	12/25/26	Q2 2027	$154,000	$25,249	Bidding
Water heater replacement	Building	11/27/26	Q2 2025	$232,000	$131,343	Complete
Security camera upgrade	Energy	01/24/24	Q4 2026	$555,000	$539,983	Complete
Sewer line repair	Interior	02/14/25	Q2 2026	$688,000	$628,608	Complete
Roof replacement - Bldg D	Building	05/28/24	Q1 2026	$681,000	$186,621	Approved
Sewer line repair	Life Safety	09/27/23	Q3 2025	$595,000	$535,255	Complete
ADA compliance	Building	03/12/23	Q2 2025	$865,000	$37,688	Complete
Pool resurfacing	Energy	12/09/25	Q3 2025	$822,000	$126,733	Approved
Sewer line repair	Interior	11/12/26	Q4 2026	$556,000	$53,430	Approved
Amenity renovation	Site	08/20/26	Q1 2026	$186,000	$94,650	Bidding

Report generated 04/23/2026. Figures are unaudited and subject to change.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Capital Project Schedule

Project	Category	Start	Completion	Budget	Spent to Date	Status
Unit interior upgrades	Interior	11/18/24	Q3 2026	$198,000	$77,935	Bidding
Elevator modernization	Interior	05/03/24	Q3 2025	$118,000	$78,487	In progress
Parking lot resurfacing	Interior	01/23/26	Q4 2026	$54,000	$24,975	Complete
Amenity renovation	Life Safety	10/25/23	Q1 2025	$275,000	$257,149	Approved
HVAC replacement	Building	12/08/23	Q2 2026	$39,000	$14,702	Deferred
Unit interior upgrades	Interior	01/22/23	Q4 2027	$534,000	$154,784	Bidding
Landscape / irrigation	Interior	08/30/25	Q2 2027	$593,000	$554,486	Approved
Signage / monument	Building	07/07/24	Q4 2027	$65,000	$67,221	In progress
Lobby renovation	Building	05/14/26	Q1 2025	$376,000	$122,657	Deferred
HVAC replacement	Site	01/02/24	Q1 2026	$719,000	$626,592	Bidding
Door hardware	Interior	10/30/26	Q1 2025	$394,000	$8,086	Bidding
Fire alarm panel upgrade	Life Safety	09/20/26	Q1 2026	$245,000	$149,374	Deferred
HVAC replacement	Interior	01/17/26	Q1 2026	$515,000	$109,616	Bidding
Pool resurfacing	Building	09/22/25	Q1 2027	$559,000	$354,712	Deferred
Pool resurfacing	Site	11/17/23	Q4 2025	$457,000	$178,707	Deferred
Sewer line repair	Site	11/28/26	Q4 2027	$159,000	$72,665	Complete
Fire alarm panel upgrade	Site	04/25/25	Q1 2027	$850,000	$328,282	In progress
Signage / monument	Site	04/10/24	Q3 2026	$685,000	$192,240	Deferred
Signage / monument	Site	11/10/23	Q4 2025	$441,000	$372,500	Approved
Door hardware	Interior	03/12/24	Q2 2025	$184,000	$31,231	In progress
Signage / monument	Site	10/31/23	Q1 2027	$39,000	$32,335	Bidding
Fence replacement	Interior	07/05/23	Q3 2027	$824,000	$792,892	Approved
Water heater replacement	Energy	03/09/25	Q2 2027	$216,000	$171,950	In progress
Sewer line repair	Site	11/04/23	Q1 2026	$771,000	$542,315	Approved
Unit interior upgrades	Life Safety	06/08/26	Q3 2025	$75,000	$69,417	Complete
Unit interior upgrades	Building	12/03/26	Q3 2027	$686,000	$360,774	Bidding
Exterior paint	Energy	02/25/24	Q1 2027	$351,000	$167,491	Complete
Signage / monument	Interior	03/19/23	Q4 2025	$482,000	$252,819	Complete
Unit interior upgrades	Interior	12/07/24	Q2 2027	$47,000	$2,294	Approved
Signage / monument	Site	06/27/23	Q3 2027	$704,000	$379,780	In progress
Security camera upgrade	Site	04/20/26	Q1 2027	$514,000	$8,162	Bidding
Water heater replacement	Energy	08/03/25	Q4 2026	$611,000	$193,576	In progress
ADA compliance	Site	11/08/24	Q2 2025	$766,000	$266,315	Bidding
Fire alarm panel upgrade	Site	06/06/23	Q4 2027	$876,000	$42,680	Complete
Storefront glazing	Interior	06/21/23	Q2 2026	$360,000	$189,843	Complete
Signage / monument	Building	03/02/24	Q4 2025	$114,000	$100,753	Complete
HVAC replacement	Building	03/30/25	Q3 2025	$192,000	$64,523	Deferred
ADA compliance	Life Safety	08/20/24	Q2 2025	$585,000	$278,422	Deferred
ADA compliance	Site	10/21/23	Q3 2027	$379,000	$148,248	Deferred
Door hardware	Interior	05/16/26	Q2 2025	$647,000	$456,420	Deferred
Sewer line repair	Interior	12/30/24	Q3 2026	$284,000	$158,534	Deferred
Parking lot resurfacing	Life Safety	03/01/24	Q4 2026	$421,000	$181,938	Complete

Report generated 04/23/2026. Figures are unaudited and subject to change.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Deferred Maintenance

Elevators were last modernized 3 years ago and are operating without deficiency. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Domestic water piping is copper and PVC with no evidence of widespread leakage. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $392,000. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months.

Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Domestic water piping is copper and PVC with no evidence of widespread leakage. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 21 months. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $352,000.

Risk Considerations

The investment thesis is based on stabilizing occupancy, completing the capital plan and capturing rent growth to market. Projected levered IRR is 6.1% with an equity multiple of 1.43x over the hold period. Pre-leasing for the coming academic year stands at 91.9% with rental rates per bed averaging $1,152. Key risks include interest rate exposure, tenant rollover, construction cost overruns and local supply additions. The property is located 8 blocks from the main campus with a dedicated shuttle serving fall and spring terms. The business plan contemplates a hold period of 6 years with disposition upon achievement of target returns.

The business plan contemplates a hold period of 12 years with disposition upon achievement of target returns. Key risks include interest rate exposure, tenant rollover, construction cost overruns and local supply additions. Distributions to investors for the quarter were paid at an annualized rate of 6.5% on contributed capital. The community is leased by the bed on individual lease liability with parent guaranties and furnished units. Projected levered IRR is 11.9% with an equity multiple of 1.28x over the hold period. Amenities include study lounges, a rooftop terrace, 24-hour fitness and a game room.

Observed Conditions

The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 23 months. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Elevators were last modernized 12 years ago and are operating without deficiency.

Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Elevators were last modernized 12 years ago and are operating without deficiency. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Domestic water piping is copper and PVC with no evidence of widespread leakage. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $385,000.

Risk Considerations

The business plan contemplates a hold period of 7 years with disposition upon achievement of target returns. Leasing velocity improved during the period and management expects further upward pressure on in-place rents. Key risks include interest rate exposure, tenant rollover, construction cost overruns and local supply additions. The investment thesis is based on stabilizing occupancy, completing the capital plan and capturing rent growth to market.

The community is leased by the bed on individual lease liability with parent guaranties and furnished units. The business plan contemplates a hold period of 10 years with disposition upon achievement of target returns. The investment thesis is based on stabilizing occupancy, completing the capital plan and capturing rent growth to market. Pre-leasing for the coming academic year stands at 93.0% with rental rates per bed averaging $1,152. The property is located 1 blocks from the main campus with a dedicated shuttle serving fall and spring terms. Amenities include study lounges, a rooftop terrace, 24-hour fitness and a game room.

Recommendations

The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Elevators were last modernized 8 years ago and are operating without deficiency. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 29 months.

The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Domestic water piping is copper and PVC with no evidence of widespread leakage. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $306,000. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Elevators were last modernized 12 years ago and are operating without deficiency.

Investor Distributions

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Summary and Notes

Operating Performance

Debt service coverage ratio was 6.40x on a trailing basis against a covenant minimum of 1.20x. Management fees are calculated at 7.6% of collected revenue and are included in operating expenses. The going-in capitalization rate of 7.14% reflects the in-place income and the stabilized occupancy assumption. Effective gross income for the trailing period was $98,000, representing a 9.8% increase over the prior year.

Amenities include study lounges, a rooftop terrace, 24-hour fitness and a game room. The property is located 5 blocks from the main campus with a dedicated shuttle serving fall and spring terms. Effective gross income for the trailing period was $287,000, representing a 8.1% increase over the prior year. Debt service coverage ratio was 5.90x on a trailing basis against a covenant minimum of 1.20x.

Property Operations

The manager completes a monthly walk of the property and submits a variance report to the owner by the 24th business day. The community is leased by the bed on individual lease liability with parent guaranties and furnished units. Collections for the period were 96.4% of billed charges, with bad debt of 3.2% of gross potential income. Pre-leasing for the coming academic year stands at 94.3% with rental rates per bed averaging $1,152. Marketing efforts include digital listings, signage, broker outreach and a resident referral program. Service requests are tracked through a work-order system with an average completion time of 45 hours.

Amenities include study lounges, a rooftop terrace, 24-hour fitness and a game room. On-site staffing consists of a property manager, assistant manager, maintenance supervisor and 29 additional team members. Pre-leasing for the coming academic year stands at 92.2% with rental rates per bed averaging $1,152. The manager completes a monthly walk of the property and submits a variance report to the owner by the 19th business day. The property is located 3 blocks from the main campus with a dedicated shuttle serving fall and spring terms.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only