PROPERTY CONDITION ASSESSMENT

Verde Parkview Residences | Naperville, IL

Property	Verde Parkview Residences
Address	2747 Quarry Parkway, Naperville, IL 94981
Site Visit Date	April 28, 2021
Client	Vireo Income Properties
Immediate Repairs	$354,000

Improvements Description

Common area interiors have been refreshed within the last 4 years and are in average to good condition. Resident turnover has averaged 11.8% annually with renewal retention above 93.2%. Average in-place rent is $1,825 per month against an average unit size of 932 square feet. Unit interiors feature quartz countertops, stainless appliances, in-unit washer and dryer and plank flooring in select renovated homes. The roof is a 6-year membrane system with an estimated remaining useful life of 7 years.

Average in-place rent is $1,825 per month against an average unit size of 932 square feet. The community offers a resort-style pool, fitness center, resident clubhouse, package lockers and a dog park. Verde Parkview Residences was originally constructed in 1972 and consists of 171 apartment homes in a building of 47 stories. Common area interiors have been refreshed within the last 8 years and are in average to good condition. Resident turnover has averaged 13.8% annually with renewal retention above 90.3%.

Observed Conditions

Domestic water piping is copper and PVC with no evidence of widespread leakage. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $240,000. Elevators were last modernized 12 years ago and are operating without deficiency. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 36 months. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations.

The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $85,000. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 10 months. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Elevators were last modernized 9 years ago and are operating without deficiency.

Building Systems

Resident turnover has averaged 6.1% annually with renewal retention above 93.4%. Mechanical systems include rooftop package units and central plant equipment of varying age. Verde Parkview Residences was originally constructed in 1972 and consists of 171 apartment homes in a building of 10 stories. The structure is of wood-frame, masonry and steel-frame construction on a slab-on-grade foundation. Average in-place rent is $1,825 per month against an average unit size of 932 square feet. Exterior finishes comprise brick veneer, fiber-cement siding and aluminum storefront glazing in good condition.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Improvements Description

Exterior finishes comprise brick veneer, fiber-cement siding and aluminum storefront glazing in good condition. Unit interiors feature quartz countertops, stainless appliances, in-unit washer and dryer and plank flooring in select renovated homes. Resident turnover has averaged 7.5% annually with renewal retention above 91.4%. The roof is a 11-year membrane system with an estimated remaining useful life of 5 years.

Unit interiors feature quartz countertops, stainless appliances, in-unit washer and dryer and plank flooring in select renovated homes. Common area interiors have been refreshed within the last 3 years and are in average to good condition. Mechanical systems include rooftop package units and central plant equipment of varying age. Verde Parkview Residences was originally constructed in 1972 and consists of 171 apartment homes in a building of 12 stories. Life-safety systems include a fully sprinklered building, addressable fire alarm panel and emergency lighting. Resident turnover has averaged 9.3% annually with renewal retention above 91.4%.

Recommendations

Elevators were last modernized 11 years ago and are operating without deficiency. Domestic water piping is copper and PVC with no evidence of widespread leakage. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 6 months.

Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Domestic water piping is copper and PVC with no evidence of widespread leakage. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 29 months. Elevators were last modernized 6 years ago and are operating without deficiency. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months.

Building Systems

Exterior finishes comprise brick veneer, fiber-cement siding and aluminum storefront glazing in good condition. Average in-place rent is $1,825 per month against an average unit size of 932 square feet. Unit interiors feature quartz countertops, stainless appliances, in-unit washer and dryer and plank flooring in select renovated homes. The community offers a resort-style pool, fitness center, resident clubhouse, package lockers and a dog park.

Common area interiors have been refreshed within the last 3 years and are in average to good condition. The roof is a 12-year membrane system with an estimated remaining useful life of 6 years. Average in-place rent is $1,825 per month against an average unit size of 932 square feet. Unit interiors feature quartz countertops, stainless appliances, in-unit washer and dryer and plank flooring in select renovated homes.

Observed Conditions

Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Domestic water piping is copper and PVC with no evidence of widespread leakage. Elevators were last modernized 4 years ago and are operating without deficiency. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 27 months. Electrical service is adequate for current demand; select panels are nearing the end of their useful life.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Immediate Repairs and Replacement Reserve Schedule

System	Age (yrs)	EUL	RUL	Condition	Immediate	Reserve (10-yr)
Roof	23	30	7	Poor	$14,000	$182,000
Paving	9	11	2	Poor	$40,000	$39,000
HVAC	3	26	23	Fair	$21,000	$20,000
Plumbing	7	11	4	Good	$25,000	$43,000
Electrical	10	12	2	Fair	$38,000	$245,000
Elevators	6	11	5	Good	$10,000	$25,000
Fire/Life Safety	9	23	14	Good	$26,000	$266,000
Windows	2	11	9	Fair	$6,000	$279,000
Siding/Facade	5	39	34	Poor	$27,000	$50,000
Flooring	9	10	1	Fair	$34,000	$96,000
Appliances	19	24	5	Poor	$14,000	$38,000
Landscaping	3	18	15	Good	$15,000	$25,000
Pool/Amenity	18	26	8	Poor	$11,000	$244,000
Signage	17	18	1	Poor	$32,000	$203,000
Fencing	14	35	21	Fair	$1,000	$30,000
Roof (2)	10	29	19	Fair	$26,000	$99,000
Paving (2)	13	33	20	Fair	$12,000	$153,000
HVAC (2)	12	22	10	Poor	$35,000	$85,000
Plumbing (2)	11	27	16	Fair	$21,000	$131,000
Electrical (2)	4	12	8	Fair	$4,000	$116,000
Elevators (2)	10	21	11	Good	$1,000	$267,000
Fire/Life Safety (2)	37	38	1	Fair	$5,000	$125,000
Windows (2)	17	23	6	Fair	$0	$179,000
Siding/Facade (2)	2	20	18	Fair	$13,000	$108,000
Flooring (2)	9	26	17	Poor	$24,000	$250,000
Appliances (2)	27	35	8	Good	$31,000	$180,000
Landscaping (2)	14	16	2	Fair	$21,000	$180,000
Pool/Amenity (2)	12	15	3	Good	$32,000	$96,000
Signage (2)	4	23	19	Fair	$23,000	$68,000
Fencing (2)	3	34	31	Poor	$23,000	$64,000

Report generated 04/28/2021. Figures are unaudited and subject to change.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Findings and Opinions of Cost

Item	Location	Observed Condition	Recommended Action	Priority	Est. Cost
Fire extinguishers	Bldg A	Expired tags	Service	Year 2-5	$5,000
HVAC unit	Bldg B	Beyond useful life	Replace RTU	Year 1	$18,500
HVAC unit	Bldg B	Beyond useful life	Replace RTU	Immediat	$55,000
Handrail	Bldg B	Loose	Secure	Year 2-5	$28,500
Asphalt paving	Common	Alligator cracking	Mill and overlay	Immediat	$20,500
Sidewalk	Common	Trip hazards	Grind / replace	Year 2-5	$68,500
Dumpster enclosure	Bldg B	Damaged gate	Repair	Reserve	$55,000
Water heater	Bldg B	Corrosion	Replace	Year 2-5	$51,500
Fire extinguishers	Mechanical	Expired tags	Service	Year 2-5	$12,000
Fire extinguishers	Roof	Expired tags	Service	Year 2-5	$41,000
Fire extinguishers	Mechanical	Expired tags	Service	Immediat	$55,500
Handrail	Mechanical	Loose	Secure	Year 1	$53,000
Water heater	Common	Corrosion	Replace	Immediat	$20,000
Dumpster enclosure	Mechanical	Damaged gate	Repair	Reserve	$16,000
Fire extinguishers	Common	Expired tags	Service	Year 1	$56,000
Window sealant	Common	Failed	Re-caulk	Year 2-5	$85,500
Window sealant	Mechanical	Failed	Re-caulk	Year 1	$8,000
Water heater	Bldg A	Corrosion	Replace	Year 2-5	$21,500
Stair treads	Roof	Worn / loose	Replace treads	Immediat	$2,000
Roof membrane	Roof	Ponding / seams	Re-seal and repair	Year 2-5	$84,000
Water heater	Mechanical	Corrosion	Replace	Reserve	$18,000
Handrail	Common	Loose	Secure	Immediat	$61,500
Fire extinguishers	Common	Expired tags	Service	Reserve	$52,000
Window sealant	Site	Failed	Re-caulk	Reserve	$26,000
Window sealant	Common	Failed	Re-caulk	Immediat	$41,000
Dumpster enclosure	Bldg B	Damaged gate	Repair	Year 1	$82,500
Window sealant	Site	Failed	Re-caulk	Year 1	$13,000
Sprinkler heads	Bldg B	Painted heads	Replace	Year 1	$84,500
Roof membrane	Bldg A	Ponding / seams	Re-seal and repair	Year 1	$73,500
Window sealant	Bldg A	Failed	Re-caulk	Immediat	$21,000
HVAC unit	Mechanical	Beyond useful life	Replace RTU	Year 2-5	$32,000
Asphalt paving	Common	Alligator cracking	Mill and overlay	Year 1	$61,000
Stair treads	Mechanical	Worn / loose	Replace treads	Reserve	$18,000
HVAC unit	Bldg A	Beyond useful life	Replace RTU	Reserve	$64,500
Stair treads	Roof	Worn / loose	Replace treads	Year 1	$60,500
Fire extinguishers	Site	Expired tags	Service	Year 2-5	$41,500
Stair treads	Mechanical	Worn / loose	Replace treads	Immediat	$64,000
Water heater	Common	Corrosion	Replace	Year 2-5	$6,500
Sidewalk	Bldg B	Trip hazards	Grind / replace	Immediat	$77,000
Handrail	Bldg B	Loose	Secure	Reserve	$87,500
Sidewalk	Roof	Trip hazards	Grind / replace	Immediat	$51,000
Window sealant	Common	Failed	Re-caulk	Immediat	$69,000
Stair treads	Site	Worn / loose	Replace treads	Year 2-5	$57,500

Report generated 04/28/2021. Figures are unaudited and subject to change.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Recommendations

Electrical service is adequate for current demand; select panels are nearing the end of their useful life. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Elevators were last modernized 6 years ago and are operating without deficiency. Domestic water piping is copper and PVC with no evidence of widespread leakage. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 17 months. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $373,000.

ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $421,000. Elevators were last modernized 10 years ago and are operating without deficiency. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 22 months. Domestic water piping is copper and PVC with no evidence of widespread leakage.

Recommendations

Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 21 months. Domestic water piping is copper and PVC with no evidence of widespread leakage. Elevators were last modernized 9 years ago and are operating without deficiency. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $82,000.

Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $229,000. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 27 months. Domestic water piping is copper and PVC with no evidence of widespread leakage. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Elevators were last modernized 7 years ago and are operating without deficiency.

Recommendations

Domestic water piping is copper and PVC with no evidence of widespread leakage. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 35 months. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Elevators were last modernized 12 years ago and are operating without deficiency.

The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Elevators were last modernized 9 years ago and are operating without deficiency. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $73,000.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Improvements Description

Verde Parkview Residences was originally constructed in 1972 and consists of 171 apartment homes in a building of 43 stories. The community offers a resort-style pool, fitness center, resident clubhouse, package lockers and a dog park. The roof is a 23-year membrane system with an estimated remaining useful life of 5 years. Exterior finishes comprise brick veneer, fiber-cement siding and aluminum storefront glazing in good condition. The structure is of wood-frame, masonry and steel-frame construction on a slab-on-grade foundation. Average in-place rent is $1,825 per month against an average unit size of 932 square feet.

The roof is a 9-year membrane system with an estimated remaining useful life of 10 years. Unit interiors feature quartz countertops, stainless appliances, in-unit washer and dryer and plank flooring in select renovated homes. Verde Parkview Residences was originally constructed in 1972 and consists of 171 apartment homes in a building of 23 stories. Resident turnover has averaged 5.2% annually with renewal retention above 92.5%.

Deferred Maintenance

Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $425,000. Elevators were last modernized 11 years ago and are operating without deficiency. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 48 months. Domestic water piping is copper and PVC with no evidence of widespread leakage. Electrical service is adequate for current demand; select panels are nearing the end of their useful life.

Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 37 months. Domestic water piping is copper and PVC with no evidence of widespread leakage. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $420,000.

Construction Details

Unit interiors feature quartz countertops, stainless appliances, in-unit washer and dryer and plank flooring in select renovated homes. The structure is of wood-frame, masonry and steel-frame construction on a slab-on-grade foundation. The roof is a 2-year membrane system with an estimated remaining useful life of 12 years. Mechanical systems include rooftop package units and central plant equipment of varying age. Average in-place rent is $1,825 per month against an average unit size of 932 square feet. Life-safety systems include a fully sprinklered building, addressable fire alarm panel and emergency lighting.

Average in-place rent is $1,825 per month against an average unit size of 932 square feet. The community offers a resort-style pool, fitness center, resident clubhouse, package lockers and a dog park. Verde Parkview Residences was originally constructed in 1972 and consists of 171 apartment homes in a building of 32 stories. Exterior finishes comprise brick veneer, fiber-cement siding and aluminum storefront glazing in good condition. Unit interiors feature quartz countertops, stainless appliances, in-unit washer and dryer and plank flooring in select renovated homes. Life-safety systems include a fully sprinklered building, addressable fire alarm panel and emergency lighting.

Observed Conditions

The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Domestic water piping is copper and PVC with no evidence of widespread leakage. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 26 months. Electrical service is adequate for current demand; select panels are nearing the end of their useful life.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Immediate Repairs and Replacement Reserve Schedule

System	Age (yrs)	EUL	RUL	Condition	Immediate	Reserve (10-yr)
Roof	17	18	1	Poor	$3,000	$188,000
Paving	7	11	4	Good	$14,000	$271,000
HVAC	8	16	8	Poor	$18,000	$83,000
Plumbing	10	39	29	Poor	$28,000	$161,000
Electrical	5	40	35	Fair	$2,000	$50,000
Elevators	27	28	1	Fair	$31,000	$243,000
Fire/Life Safety	25	26	1	Fair	$18,000	$145,000
Windows	3	10	7	Fair	$38,000	$78,000
Siding/Facade	19	25	6	Good	$15,000	$143,000
Flooring	2	37	35	Good	$22,000	$218,000
Appliances	19	33	14	Good	$31,000	$45,000
Landscaping	35	38	3	Poor	$32,000	$190,000
Pool/Amenity	1	11	10	Fair	$5,000	$25,000
Signage	33	36	3	Fair	$7,000	$238,000
Fencing	12	19	7	Fair	$15,000	$32,000
Roof (2)	1	27	26	Good	$14,000	$195,000
Paving (2)	1	17	16	Fair	$14,000	$13,000
HVAC (2)	31	33	2	Fair	$2,000	$58,000
Plumbing (2)	8	14	6	Fair	$20,000	$260,000
Electrical (2)	12	15	3	Poor	$12,000	$76,000
Elevators (2)	3	26	23	Fair	$33,000	$233,000
Fire/Life Safety (2)	11	12	1	Poor	$27,000	$275,000
Windows (2)	1	27	26	Poor	$5,000	$57,000
Siding/Facade (2)	12	15	3	Good	$37,000	$83,000
Flooring (2)	1	29	28	Fair	$3,000	$67,000
Appliances (2)	10	10	0	Good	$18,000	$275,000
Landscaping (2)	23	24	1	Poor	$28,000	$245,000
Pool/Amenity (2)	18	24	6	Fair	$14,000	$67,000
Signage (2)	5	26	21	Fair	$13,000	$45,000
Fencing (2)	17	19	2	Poor	$39,000	$241,000

Report generated 04/28/2021. Figures are unaudited and subject to change.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Findings and Opinions of Cost

Item	Location	Observed Condition	Recommended Action	Priority	Est. Cost
Handrail	Common	Loose	Secure	Reserve	$53,000
Stair treads	Site	Worn / loose	Replace treads	Year 1	$12,500
Handrail	Site	Loose	Secure	Immediat	$38,500
Dumpster enclosure	Mechanical	Damaged gate	Repair	Year 1	$46,000
Water heater	Bldg B	Corrosion	Replace	Year 2-5	$10,500
Roof membrane	Mechanical	Ponding / seams	Re-seal and repair	Reserve	$8,000
Roof membrane	Roof	Ponding / seams	Re-seal and repair	Year 1	$14,000
Fire extinguishers	Bldg A	Expired tags	Service	Immediat	$80,500
Window sealant	Mechanical	Failed	Re-caulk	Year 1	$74,000
Dumpster enclosure	Common	Damaged gate	Repair	Year 1	$13,000
Stair treads	Common	Worn / loose	Replace treads	Year 2-5	$48,000
Window sealant	Site	Failed	Re-caulk	Year 1	$33,500
Dumpster enclosure	Common	Damaged gate	Repair	Reserve	$43,500
Roof membrane	Roof	Ponding / seams	Re-seal and repair	Year 2-5	$87,500
Asphalt paving	Common	Alligator cracking	Mill and overlay	Year 2-5	$62,500
Window sealant	Mechanical	Failed	Re-caulk	Year 2-5	$6,000
Handrail	Bldg B	Loose	Secure	Year 1	$82,500
Water heater	Mechanical	Corrosion	Replace	Year 2-5	$65,500
Dumpster enclosure	Site	Damaged gate	Repair	Year 2-5	$9,000
HVAC unit	Mechanical	Beyond useful life	Replace RTU	Reserve	$53,000
Sprinkler heads	Roof	Painted heads	Replace	Year 1	$17,500
Dumpster enclosure	Roof	Damaged gate	Repair	Year 2-5	$4,000
Water heater	Roof	Corrosion	Replace	Year 1	$19,000
Roof membrane	Common	Ponding / seams	Re-seal and repair	Immediat	$47,000
Stair treads	Site	Worn / loose	Replace treads	Immediat	$6,500
Fire extinguishers	Bldg A	Expired tags	Service	Reserve	$2,000
Fire extinguishers	Mechanical	Expired tags	Service	Year 2-5	$77,500
HVAC unit	Site	Beyond useful life	Replace RTU	Immediat	$90,000
Stair treads	Common	Worn / loose	Replace treads	Year 1	$67,000
Fire extinguishers	Bldg B	Expired tags	Service	Year 1	$67,000
Fire extinguishers	Common	Expired tags	Service	Reserve	$80,500
Roof membrane	Mechanical	Ponding / seams	Re-seal and repair	Year 1	$47,500
Stair treads	Mechanical	Worn / loose	Replace treads	Year 2-5	$83,500
Fire extinguishers	Common	Expired tags	Service	Year 2-5	$500
Sidewalk	Mechanical	Trip hazards	Grind / replace	Immediat	$53,500
Water heater	Bldg A	Corrosion	Replace	Reserve	$66,500
Stair treads	Bldg B	Worn / loose	Replace treads	Reserve	$68,500
Sprinkler heads	Roof	Painted heads	Replace	Year 1	$67,000
Roof membrane	Bldg B	Ponding / seams	Re-seal and repair	Year 2-5	$48,500
Water heater	Common	Corrosion	Replace	Year 2-5	$72,000
Sidewalk	Bldg B	Trip hazards	Grind / replace	Immediat	$48,000
Roof membrane	Roof	Ponding / seams	Re-seal and repair	Year 2-5	$37,500
Dumpster enclosure	Bldg A	Damaged gate	Repair	Reserve	$73,000

Report generated 04/28/2021. Figures are unaudited and subject to change.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Deferred Maintenance

Domestic water piping is copper and PVC with no evidence of widespread leakage. Elevators were last modernized 10 years ago and are operating without deficiency. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 17 months. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $179,000.

Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 41 months. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Domestic water piping is copper and PVC with no evidence of widespread leakage. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $94,000.

Observed Conditions

ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $360,000. Elevators were last modernized 11 years ago and are operating without deficiency. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Domestic water piping is copper and PVC with no evidence of widespread leakage. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months.

Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Elevators were last modernized 10 years ago and are operating without deficiency. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 44 months. Domestic water piping is copper and PVC with no evidence of widespread leakage.

Deferred Maintenance

Domestic water piping is copper and PVC with no evidence of widespread leakage. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $369,000. Elevators were last modernized 10 years ago and are operating without deficiency. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 12 months. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Electrical service is adequate for current demand; select panels are nearing the end of their useful life.

Elevators were last modernized 9 years ago and are operating without deficiency. Domestic water piping is copper and PVC with no evidence of widespread leakage. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $153,000. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Certification

I certify that, to the best of my knowledge and belief, the statements of fact contained in this report are true and correct and that I have no present or prospective interest in Verde Parkview Residences and no personal interest with respect to the parties involved.

The analyses, opinions and conclusions are limited only by the reported assumptions and limiting conditions. The inspection of the property was performed on March 29, 2021.

_____

Maria Harper, MAI

Structura Property Assessments

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only