PROPERTY CONDITION ASSESSMENT

Elmhurst Senior Living | Naperville, IL

Property	Elmhurst Senior Living
Address	6306 Quarry Parkway, Naperville, IL 13180
Site Visit Date	December 17, 2021
Client	Keel & Compass Properties
Immediate Repairs	$148,000

Improvements Description

Life-safety systems include a fully sprinklered building, addressable fire alarm panel and emergency lighting. The structure is of wood-frame, masonry and steel-frame construction on a slab-on-grade foundation. The roof is a 26-year membrane system with an estimated remaining useful life of 12 years. The community provides assisted living and memory care services under a state-issued license with 34 full-time caregivers per shift. Occupancy stands at 88.9% with an average resident length of stay of 4 years. Elmhurst Senior Living was originally constructed in 1967 and consists of 105 units in a building of 45 stories.

The structure is of wood-frame, masonry and steel-frame construction on a slab-on-grade foundation. Average monthly revenue per occupied unit is $5,108, inclusive of base rent and levels of care. Occupancy stands at 95.8% with an average resident length of stay of 10 years. Common area interiors have been refreshed within the last 9 years and are in average to good condition. Mechanical systems include rooftop package units and central plant equipment of varying age. Exterior finishes comprise brick veneer, fiber-cement siding and aluminum storefront glazing in good condition.

Observed Conditions

Electrical service is adequate for current demand; select panels are nearing the end of their useful life. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Elevators were last modernized 8 years ago and are operating without deficiency. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 21 months. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations.

Electrical service is adequate for current demand; select panels are nearing the end of their useful life. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Domestic water piping is copper and PVC with no evidence of widespread leakage. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 7 months.

Building Systems

Mechanical systems include rooftop package units and central plant equipment of varying age. Life-safety systems include a fully sprinklered building, addressable fire alarm panel and emergency lighting. The community provides assisted living and memory care services under a state-issued license with 3 full-time caregivers per shift. The roof is a 30-year membrane system with an estimated remaining useful life of 12 years. Elmhurst Senior Living was originally constructed in 1967 and consists of 105 units in a building of 31 stories. Occupancy stands at 93.6% with an average resident length of stay of 3 years.

The community provides assisted living and memory care services under a state-issued license with 5 full-time caregivers per shift. Exterior finishes comprise brick veneer, fiber-cement siding and aluminum storefront glazing in good condition. Occupancy stands at 88.1% with an average resident length of stay of 8 years. Elmhurst Senior Living was originally constructed in 1967 and consists of 105 units in a building of 22 stories. The structure is of wood-frame, masonry and steel-frame construction on a slab-on-grade foundation. Dining, housekeeping, transportation and activities programming are included in the base fee.

Recommendations

Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Elevators were last modernized 10 years ago and are operating without deficiency. Domestic water piping is copper and PVC with no evidence of widespread leakage. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 35 months. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Construction Details

The structure is of wood-frame, masonry and steel-frame construction on a slab-on-grade foundation. Elmhurst Senior Living was originally constructed in 1967 and consists of 105 units in a building of 47 stories. Dining, housekeeping, transportation and activities programming are included in the base fee. Life-safety systems include a fully sprinklered building, addressable fire alarm panel and emergency lighting. Mechanical systems include rooftop package units and central plant equipment of varying age. Common area interiors have been refreshed within the last 4 years and are in average to good condition.

Occupancy stands at 88.7% with an average resident length of stay of 12 years. Life-safety systems include a fully sprinklered building, addressable fire alarm panel and emergency lighting. Mechanical systems include rooftop package units and central plant equipment of varying age. The roof is a 31-year membrane system with an estimated remaining useful life of 3 years.

Observed Conditions

Elevators were last modernized 6 years ago and are operating without deficiency. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 4 months. Domestic water piping is copper and PVC with no evidence of widespread leakage. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months.

The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Elevators were last modernized 6 years ago and are operating without deficiency. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 45 months. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $65,000.

Building Systems

The roof is a 20-year membrane system with an estimated remaining useful life of 10 years. Dining, housekeeping, transportation and activities programming are included in the base fee. Elmhurst Senior Living was originally constructed in 1967 and consists of 105 units in a building of 4 stories. Exterior finishes comprise brick veneer, fiber-cement siding and aluminum storefront glazing in good condition. Occupancy stands at 92.8% with an average resident length of stay of 5 years.

Common area interiors have been refreshed within the last 9 years and are in average to good condition. Occupancy stands at 91.3% with an average resident length of stay of 12 years. The community provides assisted living and memory care services under a state-issued license with 18 full-time caregivers per shift. The roof is a 16-year membrane system with an estimated remaining useful life of 11 years. The structure is of wood-frame, masonry and steel-frame construction on a slab-on-grade foundation. Mechanical systems include rooftop package units and central plant equipment of varying age.

Observed Conditions

Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Domestic water piping is copper and PVC with no evidence of widespread leakage. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $43,000. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 8 months.

Electrical service is adequate for current demand; select panels are nearing the end of their useful life. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Domestic water piping is copper and PVC with no evidence of widespread leakage. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $168,000. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 40 months.

Construction Details

Average monthly revenue per occupied unit is $5,108, inclusive of base rent and levels of care. The structure is of wood-frame, masonry and steel-frame construction on a slab-on-grade foundation. Elmhurst Senior Living was originally constructed in 1967 and consists of 105 units in a building of 45 stories. Occupancy stands at 92.3% with an average resident length of stay of 3 years.

The community provides assisted living and memory care services under a state-issued license with 9 full-time caregivers per shift. Occupancy stands at 97.0% with an average resident length of stay of 10 years. Dining, housekeeping, transportation and activities programming are included in the base fee. Elmhurst Senior Living was originally constructed in 1967 and consists of 105 units in a building of 23 stories. Common area interiors have been refreshed within the last 9 years and are in average to good condition. The structure is of wood-frame, masonry and steel-frame construction on a slab-on-grade foundation.

Deferred Maintenance

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Immediate Repairs and Replacement Reserve Schedule

System	Age (yrs)	EUL	RUL	Condition	Immediate	Reserve (10-yr)
Roof	14	29	15	Fair	$9,000	$258,000
Paving	13	27	14	Good	$4,000	$71,000
HVAC	23	37	14	Poor	$12,000	$23,000
Plumbing	16	30	14	Fair	$36,000	$167,000
Electrical	30	33	3	Good	$18,000	$179,000
Elevators	19	37	18	Fair	$28,000	$105,000
Fire/Life Safety	11	37	26	Good	$30,000	$104,000
Windows	7	15	8	Poor	$22,000	$261,000
Siding/Facade	11	14	3	Fair	$23,000	$24,000
Flooring	2	19	17	Fair	$38,000	$147,000
Appliances	13	30	17	Fair	$21,000	$43,000
Landscaping	22	38	16	Good	$21,000	$120,000
Pool/Amenity	8	10	2	Good	$36,000	$101,000
Signage	11	30	19	Poor	$8,000	$45,000
Fencing	2	10	8	Good	$24,000	$5,000
Roof (2)	5	35	30	Fair	$30,000	$27,000
Paving (2)	24	25	1	Fair	$13,000	$165,000
HVAC (2)	7	13	6	Good	$5,000	$45,000
Plumbing (2)	15	31	16	Poor	$25,000	$149,000
Electrical (2)	12	17	5	Fair	$37,000	$158,000
Elevators (2)	9	13	4	Poor	$1,000	$135,000
Fire/Life Safety (2)	16	17	1	Fair	$2,000	$243,000
Windows (2)	40	40	0	Poor	$14,000	$76,000
Siding/Facade (2)	16	29	13	Fair	$39,000	$184,000
Flooring (2)	20	37	17	Fair	$11,000	$250,000
Appliances (2)	33	37	4	Poor	$6,000	$166,000
Landscaping (2)	6	23	17	Poor	$29,000	$134,000
Pool/Amenity (2)	17	30	13	Good	$18,000	$231,000
Signage (2)	10	12	2	Fair	$40,000	$128,000
Fencing (2)	8	14	6	Fair	$22,000	$248,000

Report generated 12/17/2021. Figures are unaudited and subject to change.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Findings and Opinions of Cost

Item	Location	Observed Condition	Recommended Action	Priority	Est. Cost
Roof membrane	Roof	Ponding / seams	Re-seal and repair	Year 1	$69,500
Stair treads	Roof	Worn / loose	Replace treads	Immediate	$37,000
Fire extinguishers	Bldg B	Expired tags	Service	Reserve	$67,500
Sprinkler heads	Common	Painted heads	Replace	Immediate	$45,500
Asphalt paving	Roof	Alligator cracking	Mill and overlay	Reserve	$7,000
Window sealant	Mechanical	Failed	Re-caulk	Year 1	$13,500
HVAC unit	Bldg B	Beyond useful life	Replace RTU	Year 2-5	$15,000
Handrail	Site	Loose	Secure	Immediate	$22,500
Window sealant	Common	Failed	Re-caulk	Year 2-5	$17,000
HVAC unit	Bldg A	Beyond useful life	Replace RTU	Year 1	$63,000
Sprinkler heads	Bldg B	Painted heads	Replace	Year 2-5	$69,500
Sidewalk	Mechanical	Trip hazards	Grind / replace	Immediate	$60,000
Water heater	Mechanical	Corrosion	Replace	Year 2-5	$41,500
Window sealant	Site	Failed	Re-caulk	Year 1	$24,500
Window sealant	Mechanical	Failed	Re-caulk	Reserve	$49,500
Stair treads	Bldg A	Worn / loose	Replace treads	Reserve	$42,500
Sprinkler heads	Bldg A	Painted heads	Replace	Year 1	$41,500
Stair treads	Bldg B	Worn / loose	Replace treads	Year 2-5	$37,500
Stair treads	Bldg A	Worn / loose	Replace treads	Year 2-5	$54,000
Sidewalk	Bldg B	Trip hazards	Grind / replace	Year 1	$13,500
Stair treads	Site	Worn / loose	Replace treads	Reserve	$8,000
Sprinkler heads	Common	Painted heads	Replace	Year 1	$72,000
Sprinkler heads	Common	Painted heads	Replace	Year 2-5	$35,000
HVAC unit	Bldg B	Beyond useful life	Replace RTU	Immediate	$50,500
Water heater	Bldg B	Corrosion	Replace	Year 2-5	$31,000
Handrail	Bldg B	Loose	Secure	Year 1	$12,000
Dumpster enclosure	Site	Damaged gate	Repair	Year 1	$29,000
Window sealant	Roof	Failed	Re-caulk	Immediate	$11,500
Water heater	Bldg B	Corrosion	Replace	Year 1	$43,500
Roof membrane	Bldg A	Ponding / seams	Re-seal and repair	Immediate	$78,500
Fire extinguishers	Common	Expired tags	Service	Year 2-5	$36,500
Fire extinguishers	Roof	Expired tags	Service	Immediate	$24,000
Dumpster enclosure	Roof	Damaged gate	Repair	Reserve	$1,500
Dumpster enclosure	Common	Damaged gate	Repair	Reserve	$6,000
Water heater	Bldg A	Corrosion	Replace	Immediate	$56,500
Roof membrane	Mechanical	Ponding / seams	Re-seal and repair	Reserve	$16,500
Fire extinguishers	Mechanical	Expired tags	Service	Year 2-5	$65,500
Stair treads	Bldg B	Worn / loose	Replace treads	Immediate	$9,500
HVAC unit	Site	Beyond useful life	Replace RTU	Year 2-5	$74,000
Dumpster enclosure	Mechanical	Damaged gate	Repair	Year 2-5	$20,500
Fire extinguishers	Mechanical	Expired tags	Service	Reserve	$3,000

Report generated 12/17/2021. Figures are unaudited and subject to change.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Certification

I certify that, to the best of my knowledge and belief, the statements of fact contained in this report are true and correct and that I have no present or prospective interest in Elmhurst Senior Living and no personal interest with respect to the parties involved.

The analyses, opinions and conclusions are limited only by the reported assumptions and limiting conditions. The inspection of the property was performed on November 23, 2021.

_____

James Patel, CPG

Lindqvist Engineering Group

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only