PROPERTY CONDITION ASSESSMENT

Sterling Student Living | Omaha, NE

Property	Sterling Student Living
Address	305 Airport Parkway, Omaha, NE 36356
Site Visit Date	December 18, 2019
Client	Beacon Hollow Investors
Immediate Repairs	$206,000

Improvements Description

Sterling Student Living was originally constructed in 1973 and consists of 434 beds in a building of 16 stories. The roof is a 17-year membrane system with an estimated remaining useful life of 11 years. Mechanical systems include rooftop package units and central plant equipment of varying age. Pre-leasing for the coming academic year stands at 91.8% with rental rates per bed averaging $1,062. Common area interiors have been refreshed within the last 9 years and are in average to good condition. Amenities include study lounges, a rooftop terrace, 24-hour fitness and a game room.

Exterior finishes comprise brick veneer, fiber-cement siding and aluminum storefront glazing in good condition. Life-safety systems include a fully sprinklered building, addressable fire alarm panel and emergency lighting. Pre-leasing for the coming academic year stands at 96.0% with rental rates per bed averaging $1,062. Mechanical systems include rooftop package units and central plant equipment of varying age. Common area interiors have been refreshed within the last 11 years and are in average to good condition.

Recommendations

The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 33 months. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $42,000. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Elevators were last modernized 4 years ago and are operating without deficiency. Electrical service is adequate for current demand; select panels are nearing the end of their useful life.

The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 30 months.

Improvements Description

Amenities include study lounges, a rooftop terrace, 24-hour fitness and a game room. Mechanical systems include rooftop package units and central plant equipment of varying age. The community is leased by the bed on individual lease liability with parent guaranties and furnished units. Life-safety systems include a fully sprinklered building, addressable fire alarm panel and emergency lighting.

Exterior finishes comprise brick veneer, fiber-cement siding and aluminum storefront glazing in good condition. The structure is of wood-frame, masonry and steel-frame construction on a slab-on-grade foundation. Common area interiors have been refreshed within the last 11 years and are in average to good condition. The roof is a 35-year membrane system with an estimated remaining useful life of 7 years. Pre-leasing for the coming academic year stands at 93.2% with rental rates per bed averaging $1,062. The community is leased by the bed on individual lease liability with parent guaranties and furnished units.

Deferred Maintenance

Elevators were last modernized 4 years ago and are operating without deficiency. Domestic water piping is copper and PVC with no evidence of widespread leakage. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $164,000. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 4 months.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Building Systems

Life-safety systems include a fully sprinklered building, addressable fire alarm panel and emergency lighting. The property is located 4 blocks from the main campus with a dedicated shuttle serving fall and spring terms. The community is leased by the bed on individual lease liability with parent guaranties and furnished units. Mechanical systems include rooftop package units and central plant equipment of varying age. Exterior finishes comprise brick veneer, fiber-cement siding and aluminum storefront glazing in good condition.

The structure is of wood-frame, masonry and steel-frame construction on a slab-on-grade foundation. Amenities include study lounges, a rooftop terrace, 24-hour fitness and a game room. The community is leased by the bed on individual lease liability with parent guaranties and furnished units. Life-safety systems include a fully sprinklered building, addressable fire alarm panel and emergency lighting.

Recommendations

Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Elevators were last modernized 7 years ago and are operating without deficiency. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $58,000. Domestic water piping is copper and PVC with no evidence of widespread leakage.

Domestic water piping is copper and PVC with no evidence of widespread leakage. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 36 months. Elevators were last modernized 8 years ago and are operating without deficiency.

Improvements Description

The community is leased by the bed on individual lease liability with parent guaranties and furnished units. Life-safety systems include a fully sprinklered building, addressable fire alarm panel and emergency lighting. Amenities include study lounges, a rooftop terrace, 24-hour fitness and a game room. Sterling Student Living was originally constructed in 1973 and consists of 434 beds in a building of 26 stories.

Mechanical systems include rooftop package units and central plant equipment of varying age. The structure is of wood-frame, masonry and steel-frame construction on a slab-on-grade foundation. Common area interiors have been refreshed within the last 7 years and are in average to good condition. The roof is a 35-year membrane system with an estimated remaining useful life of 8 years.

Deferred Maintenance

Elevators were last modernized 6 years ago and are operating without deficiency. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Domestic water piping is copper and PVC with no evidence of widespread leakage. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 29 months.

ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $369,000. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Elevators were last modernized 9 years ago and are operating without deficiency. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 48 months. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Domestic water piping is copper and PVC with no evidence of widespread leakage.

Building Systems

Exterior finishes comprise brick veneer, fiber-cement siding and aluminum storefront glazing in good condition. Pre-leasing for the coming academic year stands at 90.7% with rental rates per bed averaging $1,062. The structure is of wood-frame, masonry and steel-frame construction on a slab-on-grade foundation. The roof is a 41-year membrane system with an estimated remaining useful life of 5 years. Sterling Student Living was originally constructed in 1973 and consists of 434 beds in a building of 7 stories.

The roof is a 10-year membrane system with an estimated remaining useful life of 12 years. Life-safety systems include a fully sprinklered building, addressable fire alarm panel and emergency lighting. Amenities include study lounges, a rooftop terrace, 24-hour fitness and a game room. Exterior finishes comprise brick veneer, fiber-cement siding and aluminum storefront glazing in good condition.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Immediate Repairs and Replacement Reserve Schedule

System	Age (yrs)	EUL	RUL	Condition	Immediate	Reserve (10-yr)
Roof	2	21	19	Poor	$8,000	$60,000
Paving	8	11	3	Poor	$27,000	$194,000
HVAC	10	34	24	Good	$5,000	$33,000
Plumbing	15	33	18	Good	$30,000	$247,000
Electrical	6	29	23	Fair	$23,000	$28,000
Elevators	4	23	19	Good	$35,000	$203,000
Fire/Life Safety	3	17	14	Fair	$23,000	$279,000
Windows	14	20	6	Poor	$32,000	$71,000
Siding/Facade	4	36	32	Good	$13,000	$279,000
Flooring	1	20	19	Fair	$1,000	$270,000
Appliances	18	19	1	Fair	$5,000	$210,000
Landscaping	24	24	0	Poor	$9,000	$252,000
Pool/Amenity	1	21	20	Good	$12,000	$273,000
Signage	8	16	8	Poor	$35,000	$43,000
Fencing	4	29	25	Fair	$20,000	$244,000
Roof (2)	16	39	23	Fair	$32,000	$275,000
Paving (2)	23	25	2	Good	$30,000	$229,000
HVAC (2)	7	27	20	Fair	$26,000	$192,000
Plumbing (2)	16	16	0	Fair	$36,000	$154,000
Electrical (2)	13	25	12	Fair	$7,000	$91,000
Elevators (2)	14	21	7	Fair	$0	$43,000
Fire/Life Safety (2)	8	13	5	Fair	$18,000	$60,000
Windows (2)	18	31	13	Fair	$30,000	$266,000
Siding/Facade (2)	3	11	8	Poor	$31,000	$173,000
Flooring (2)	34	40	6	Poor	$29,000	$256,000
Appliances (2)	2	12	10	Fair	$13,000	$9,000
Landscaping (2)	7	24	17	Fair	$13,000	$31,000
Pool/Amenity (2)	23	37	14	Fair	$15,000	$193,000
Signage (2)	2	16	14	Fair	$35,000	$267,000
Fencing (2)	13	36	23	Good	$19,000	$108,000

Report generated 12/18/2019. Figures are unaudited and subject to change.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Findings and Opinions of Cost

Item	Location	Observed Condition	Recommended Action	Priority	Est. Cost
Asphalt paving	Site	Alligator cracking	Mill and overlay	Reserve	$48,500
HVAC unit	Site	Beyond useful life	Replace RTU	Year 2-5	$88,000
Stair treads	Common	Worn / loose	Replace treads	Year 2-5	$80,500
Roof membrane	Common	Ponding / seams	Re-seal and repair	Year 2-5	$77,000
HVAC unit	Roof	Beyond useful life	Replace RTU	Reserve	$66,000
Water heater	Site	Corrosion	Replace	Immediate	$16,000
Roof membrane	Mechanical	Ponding / seams	Re-seal and repair	Reserve	$41,000
Sprinkler heads	Roof	Painted heads	Replace	Year 1	$72,000
Water heater	Site	Corrosion	Replace	Reserve	$17,000
Sprinkler heads	Roof	Painted heads	Replace	Immediate	$48,500
Fire extinguishers	Bldg B	Expired tags	Service	Year 1	$76,500
HVAC unit	Roof	Beyond useful life	Replace RTU	Year 2-5	$35,500
Stair treads	Site	Worn / loose	Replace treads	Reserve	$34,500
Sprinkler heads	Bldg B	Painted heads	Replace	Immediate	$4,000
Asphalt paving	Bldg A	Alligator cracking	Mill and overlay	Year 1	$38,000
Stair treads	Common	Worn / loose	Replace treads	Year 1	$61,000
Asphalt paving	Site	Alligator cracking	Mill and overlay	Reserve	$37,500
Water heater	Bldg B	Corrosion	Replace	Year 2-5	$62,000
Asphalt paving	Roof	Alligator cracking	Mill and overlay	Immediate	$88,500
Fire extinguishers	Site	Expired tags	Service	Year 1	$52,500
Sprinkler heads	Bldg B	Painted heads	Replace	Year 2-5	$37,500
Fire extinguishers	Site	Expired tags	Service	Year 1	$57,000
HVAC unit	Common	Beyond useful life	Replace RTU	Year 2-5	$32,500
Asphalt paving	Roof	Alligator cracking	Mill and overlay	Year 2-5	$4,500
Handrail	Mechanical	Loose	Secure	Year 2-5	$24,500
Stair treads	Common	Worn / loose	Replace treads	Reserve	$87,500
Sidewalk	Mechanical	Trip hazards	Grind / replace	Reserve	$34,000
Water heater	Bldg B	Corrosion	Replace	Immediate	$75,000
Water heater	Common	Corrosion	Replace	Immediate	$11,500
Asphalt paving	Mechanical	Alligator cracking	Mill and overlay	Reserve	$68,000
Dumpster enclosure	Bldg B	Damaged gate	Repair	Year 1	$86,000
Roof membrane	Bldg A	Ponding / seams	Re-seal and repair	Year 1	$18,500
Stair treads	Bldg B	Worn / loose	Replace treads	Year 1	$41,000
Water heater	Common	Corrosion	Replace	Immediate	$74,500
Sidewalk	Common	Trip hazards	Grind / replace	Year 1	$43,500
Stair treads	Roof	Worn / loose	Replace treads	Immediate	$37,500
Water heater	Bldg A	Corrosion	Replace	Year 1	$12,000
Handrail	Bldg A	Loose	Secure	Immediate	$77,500
Asphalt paving	Bldg A	Alligator cracking	Mill and overlay	Year 1	$21,000
Stair treads	Mechanical	Worn / loose	Replace treads	Immediate	$36,500

Report generated 12/18/2019. Figures are unaudited and subject to change.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Deferred Maintenance

Elevators were last modernized 10 years ago and are operating without deficiency. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 12 months. Domestic water piping is copper and PVC with no evidence of widespread leakage. Electrical service is adequate for current demand; select panels are nearing the end of their useful life.

Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 2 months. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $353,000.

Deferred Maintenance

Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $198,000.

Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 29 months. Domestic water piping is copper and PVC with no evidence of widespread leakage. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $396,000.

Deferred Maintenance

Electrical service is adequate for current demand; select panels are nearing the end of their useful life. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $121,000. Elevators were last modernized 7 years ago and are operating without deficiency. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 28 months. Domestic water piping is copper and PVC with no evidence of widespread leakage.

The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Elevators were last modernized 7 years ago and are operating without deficiency. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 3 months. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $22,000. Domestic water piping is copper and PVC with no evidence of widespread leakage.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Improvements Description

The roof is a 28-year membrane system with an estimated remaining useful life of 3 years. The property is located 4 blocks from the main campus with a dedicated shuttle serving fall and spring terms. Sterling Student Living was originally constructed in 1973 and consists of 434 beds in a building of 7 stories. Pre-leasing for the coming academic year stands at 91.1% with rental rates per bed averaging $1,062.

Pre-leasing for the coming academic year stands at 90.7% with rental rates per bed averaging $1,062. The structure is of wood-frame, masonry and steel-frame construction on a slab-on-grade foundation. Amenities include study lounges, a rooftop terrace, 24-hour fitness and a game room. The community is leased by the bed on individual lease liability with parent guaranties and furnished units. Common area interiors have been refreshed within the last 8 years and are in average to good condition. Mechanical systems include rooftop package units and central plant equipment of varying age.

Observed Conditions

Elevators were last modernized 5 years ago and are operating without deficiency. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $478,000. Domestic water piping is copper and PVC with no evidence of widespread leakage. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 8 months. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Electrical service is adequate for current demand; select panels are nearing the end of their useful life.

The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Elevators were last modernized 6 years ago and are operating without deficiency. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 13 months. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations.

Building Systems

Sterling Student Living was originally constructed in 1973 and consists of 434 beds in a building of 20 stories. Pre-leasing for the coming academic year stands at 93.0% with rental rates per bed averaging $1,062. Mechanical systems include rooftop package units and central plant equipment of varying age. The community is leased by the bed on individual lease liability with parent guaranties and furnished units. The structure is of wood-frame, masonry and steel-frame construction on a slab-on-grade foundation. Life-safety systems include a fully sprinklered building, addressable fire alarm panel and emergency lighting.

The property is located 8 blocks from the main campus with a dedicated shuttle serving fall and spring terms. The roof is a 46-year membrane system with an estimated remaining useful life of 7 years. The community is leased by the bed on individual lease liability with parent guaranties and furnished units. The structure is of wood-frame, masonry and steel-frame construction on a slab-on-grade foundation. Life-safety systems include a fully sprinklered building, addressable fire alarm panel and emergency lighting.

Recommendations

Domestic water piping is copper and PVC with no evidence of widespread leakage. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $414,000. Elevators were last modernized 9 years ago and are operating without deficiency.

Elevators were last modernized 9 years ago and are operating without deficiency. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $115,000. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 48 months.

Construction Details

Sterling Student Living was originally constructed in 1973 and consists of 434 beds in a building of 4 stories. Common area interiors have been refreshed within the last 4 years and are in average to good condition. Life-safety systems include a fully sprinklered building, addressable fire alarm panel and emergency lighting. The property is located 9 blocks from the main campus with a dedicated shuttle serving fall and spring terms. The structure is of wood-frame, masonry and steel-frame construction on a slab-on-grade foundation.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Immediate Repairs and Replacement Reserve Schedule

System	Age (yrs)	EUL	RUL	Condition	Immediate	Reserve (10-yr)
Roof	35	38	3	Good	$40,000	$95,000
Paving	30	40	10	Poor	$31,000	$171,000
HVAC	20	22	2	Poor	$22,000	$145,000
Plumbing	1	31	30	Poor	$13,000	$57,000
Electrical	4	14	10	Fair	$16,000	$192,000
Elevators	6	16	10	Fair	$36,000	$236,000
Fire/Life Safety	20	38	18	Good	$18,000	$104,000
Windows	5	10	5	Fair	$19,000	$45,000
Siding/Facade	16	31	15	Good	$38,000	$17,000
Flooring	12	19	7	Poor	$15,000	$17,000
Appliances	2	11	9	Good	$10,000	$9,000
Landscaping	16	18	2	Fair	$26,000	$8,000
Pool/Amenity	4	12	8	Poor	$11,000	$79,000
Signage	23	35	12	Fair	$19,000	$76,000
Fencing	22	40	18	Fair	$14,000	$111,000
Roof (2)	10	21	11	Fair	$30,000	$63,000
Paving (2)	37	40	3	Fair	$27,000	$114,000
HVAC (2)	10	10	0	Fair	$33,000	$79,000
Plumbing (2)	13	24	11	Good	$2,000	$58,000
Electrical (2)	27	37	10	Fair	$39,000	$37,000
Elevators (2)	19	37	18	Fair	$20,000	$152,000
Fire/Life Safety (2)	26	29	3	Poor	$17,000	$18,000
Windows (2)	20	21	1	Fair	$34,000	$159,000
Siding/Facade (2)	2	16	14	Good	$18,000	$122,000
Flooring (2)	8	15	7	Fair	$18,000	$266,000
Appliances (2)	38	40	2	Fair	$34,000	$142,000
Landscaping (2)	23	39	16	Fair	$5,000	$236,000
Pool/Amenity (2)	31	40	9	Fair	$37,000	$238,000
Signage (2)	25	32	7	Good	$35,000	$137,000
Fencing (2)	13	33	20	Good	$32,000	$256,000

Report generated 12/18/2019. Figures are unaudited and subject to change.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Findings and Opinions of Cost

Item	Location	Observed Condition	Recommended Action	Priority	Est. Cost
Roof membrane	Mechanical	Ponding / seams	Re-seal and repair	Reserve	$8,000
Dumpster enclosure	Mechanical	Damaged gate	Repair	Immediate	$13,500
Handrail	Site	Loose	Secure	Year 2-5	$7,000
Asphalt paving	Common	Alligator cracking	Mill and overlay	Reserve	$69,000
Roof membrane	Site	Ponding / seams	Re-seal and repair	Immediate	$9,000
HVAC unit	Mechanical	Beyond useful life	Replace RTU	Year 2-5	$15,500
Water heater	Bldg B	Corrosion	Replace	Year 1	$58,500
Stair treads	Roof	Worn / loose	Replace treads	Year 2-5	$67,500
Roof membrane	Site	Ponding / seams	Re-seal and repair	Reserve	$500
Stair treads	Common	Worn / loose	Replace treads	Year 1	$44,500
Asphalt paving	Bldg A	Alligator cracking	Mill and overlay	Immediate	$21,500
Sidewalk	Mechanical	Trip hazards	Grind / replace	Immediate	$49,000
Asphalt paving	Common	Alligator cracking	Mill and overlay	Year 2-5	$41,000
Window sealant	Bldg B	Failed	Re-caulk	Year 1	$78,500
Stair treads	Bldg B	Worn / loose	Replace treads	Immediate	$27,000
Asphalt paving	Common	Alligator cracking	Mill and overlay	Immediate	$29,500
Roof membrane	Roof	Ponding / seams	Re-seal and repair	Immediate	$28,000
Dumpster enclosure	Site	Damaged gate	Repair	Reserve	$3,000
Water heater	Bldg A	Corrosion	Replace	Reserve	$19,500
Dumpster enclosure	Bldg B	Damaged gate	Repair	Year 1	$23,000
Window sealant	Mechanical	Failed	Re-caulk	Year 1	$74,500
Dumpster enclosure	Site	Damaged gate	Repair	Reserve	$69,500
HVAC unit	Common	Beyond useful life	Replace RTU	Reserve	$40,500
Water heater	Mechanical	Corrosion	Replace	Immediate	$72,000
Water heater	Mechanical	Corrosion	Replace	Immediate	$38,000
Handrail	Common	Loose	Secure	Reserve	$88,000
Window sealant	Site	Failed	Re-caulk	Immediate	$8,500
Stair treads	Bldg B	Worn / loose	Replace treads	Immediate	$38,500
Dumpster enclosure	Bldg B	Damaged gate	Repair	Immediate	$58,500
Sprinkler heads	Site	Painted heads	Replace	Immediate	$9,000
Stair treads	Bldg A	Worn / loose	Replace treads	Year 2-5	$45,500
Fire extinguishers	Bldg B	Expired tags	Service	Year 2-5	$75,000
Dumpster enclosure	Bldg B	Damaged gate	Repair	Year 2-5	$2,000
Water heater	Mechanical	Corrosion	Replace	Year 1	$15,500
Handrail	Bldg B	Loose	Secure	Year 1	$57,500
Handrail	Mechanical	Loose	Secure	Year 1	$45,000
Dumpster enclosure	Bldg A	Damaged gate	Repair	Reserve	$1,000
Sprinkler heads	Roof	Painted heads	Replace	Immediate	$3,000
Window sealant	Mechanical	Failed	Re-caulk	Year 1	$80,000
Dumpster enclosure	Common	Damaged gate	Repair	Immediate	$53,500
Dumpster enclosure	Roof	Damaged gate	Repair	Year 2-5	$81,500

Report generated 12/18/2019. Figures are unaudited and subject to change.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Observed Conditions

Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 10 months. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Domestic water piping is copper and PVC with no evidence of widespread leakage. Elevators were last modernized 10 years ago and are operating without deficiency.

Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Domestic water piping is copper and PVC with no evidence of widespread leakage. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 27 months. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Elevators were last modernized 8 years ago and are operating without deficiency. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations.

Observed Conditions

Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 3 months. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $380,000. Elevators were last modernized 5 years ago and are operating without deficiency. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations.

Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $320,000. Elevators were last modernized 12 years ago and are operating without deficiency. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 34 months.

Recommendations

Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 42 months. Elevators were last modernized 11 years ago and are operating without deficiency. Domestic water piping is copper and PVC with no evidence of widespread leakage. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months.

Elevators were last modernized 5 years ago and are operating without deficiency. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Domestic water piping is copper and PVC with no evidence of widespread leakage. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $122,000. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 26 months. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Improvements Description

The roof is a 48-year membrane system with an estimated remaining useful life of 5 years. Mechanical systems include rooftop package units and central plant equipment of varying age. Exterior finishes comprise brick veneer, fiber-cement siding and aluminum storefront glazing in good condition. The community is leased by the bed on individual lease liability with parent guaranties and furnished units. The structure is of wood-frame, masonry and steel-frame construction on a slab-on-grade foundation.

Amenities include study lounges, a rooftop terrace, 24-hour fitness and a game room. The property is located 8 blocks from the main campus with a dedicated shuttle serving fall and spring terms. Mechanical systems include rooftop package units and central plant equipment of varying age. Pre-leasing for the coming academic year stands at 90.3% with rental rates per bed averaging $1,062. The roof is a 22-year membrane system with an estimated remaining useful life of 10 years.

Observed Conditions

Domestic water piping is copper and PVC with no evidence of widespread leakage. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 45 months. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $367,000. Electrical service is adequate for current demand; select panels are nearing the end of their useful life.

The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Elevators were last modernized 6 years ago and are operating without deficiency. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 34 months.

Construction Details

Mechanical systems include rooftop package units and central plant equipment of varying age. Common area interiors have been refreshed within the last 7 years and are in average to good condition. Amenities include study lounges, a rooftop terrace, 24-hour fitness and a game room. The roof is a 18-year membrane system with an estimated remaining useful life of 4 years.

Common area interiors have been refreshed within the last 3 years and are in average to good condition. Pre-leasing for the coming academic year stands at 88.8% with rental rates per bed averaging $1,062. The roof is a 34-year membrane system with an estimated remaining useful life of 6 years. Mechanical systems include rooftop package units and central plant equipment of varying age. The property is located 2 blocks from the main campus with a dedicated shuttle serving fall and spring terms.

Recommendations

Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Elevators were last modernized 4 years ago and are operating without deficiency. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 24 months. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Domestic water piping is copper and PVC with no evidence of widespread leakage.

Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Elevators were last modernized 9 years ago and are operating without deficiency. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 27 months. Domestic water piping is copper and PVC with no evidence of widespread leakage.

Building Systems

The property is located 6 blocks from the main campus with a dedicated shuttle serving fall and spring terms. Life-safety systems include a fully sprinklered building, addressable fire alarm panel and emergency lighting. The roof is a 26-year membrane system with an estimated remaining useful life of 7 years. The structure is of wood-frame, masonry and steel-frame construction on a slab-on-grade foundation. The community is leased by the bed on individual lease liability with parent guaranties and furnished units. Pre-leasing for the coming academic year stands at 88.2% with rental rates per bed averaging $1,062.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Immediate Repairs and Replacement Reserve Schedule

System	Age (yrs)	EUL	RUL	Condition	Immediate	Reserve (10-yr)
Roof	10	27	17	Poor	$14,000	$204,000
Paving	8	16	8	Good	$32,000	$145,000
HVAC	8	12	4	Good	$11,000	$85,000
Plumbing	14	37	23	Poor	$35,000	$268,000
Electrical	3	16	13	Good	$26,000	$163,000
Elevators	4	37	33	Fair	$36,000	$107,000
Fire/Life Safety	30	32	2	Fair	$8,000	$229,000
Windows	4	30	26	Fair	$14,000	$91,000
Siding/Facade	14	37	23	Fair	$37,000	$233,000
Flooring	3	19	16	Good	$11,000	$270,000
Appliances	19	30	11	Fair	$31,000	$168,000
Landscaping	6	23	17	Fair	$10,000	$118,000
Pool/Amenity	30	31	1	Good	$32,000	$22,000
Signage	5	37	32	Fair	$5,000	$40,000
Fencing	8	13	5	Good	$12,000	$56,000
Roof (2)	13	27	14	Poor	$7,000	$174,000
Paving (2)	10	10	0	Fair	$28,000	$257,000
HVAC (2)	21	24	3	Good	$0	$239,000
Plumbing (2)	19	33	14	Poor	$17,000	$160,000
Electrical (2)	22	32	10	Poor	$30,000	$243,000
Elevators (2)	21	25	4	Poor	$21,000	$51,000
Fire/Life Safety (2)	16	20	4	Poor	$32,000	$97,000
Windows (2)	20	37	17	Good	$12,000	$56,000
Siding/Facade (2)	9	10	1	Fair	$36,000	$47,000
Flooring (2)	9	15	6	Fair	$10,000	$178,000
Appliances (2)	1	20	19	Fair	$9,000	$78,000
Landscaping (2)	6	16	10	Fair	$20,000	$137,000
Pool/Amenity (2)	21	33	12	Poor	$12,000	$153,000
Signage (2)	9	14	5	Good	$30,000	$267,000
Fencing (2)	11	19	8	Fair	$7,000	$275,000

Report generated 12/18/2019. Figures are unaudited and subject to change.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Findings and Opinions of Cost

Item	Location	Observed Condition	Recommended Action	Priority	Est. Cost
Sidewalk	Roof	Trip hazards	Grind / replace	Reserve	$10,500
Dumpster enclosure	Bldg B	Damaged gate	Repair	Reserve	$75,000
Water heater	Bldg B	Corrosion	Replace	Year 2-5	$79,500
Roof membrane	Roof	Ponding / seams	Re-seal and repair	Year 2-5	$34,000
Window sealant	Mechanical	Failed	Re-caulk	Year 1	$46,000
Roof membrane	Common	Ponding / seams	Re-seal and repair	Immediate	$27,000
Asphalt paving	Site	Alligator cracking	Mill and overlay	Year 1	$64,500
Fire extinguishers	Roof	Expired tags	Service	Reserve	$56,000
Roof membrane	Site	Ponding / seams	Re-seal and repair	Immediate	$83,000
Asphalt paving	Mechanical	Alligator cracking	Mill and overlay	Year 2-5	$82,500
Handrail	Bldg B	Loose	Secure	Year 1	$61,000
Sprinkler heads	Site	Painted heads	Replace	Year 2-5	$24,000
Stair treads	Mechanical	Worn / loose	Replace treads	Immediate	$62,000
Sidewalk	Site	Trip hazards	Grind / replace	Year 2-5	$35,500
Window sealant	Mechanical	Failed	Re-caulk	Immediate	$73,000
Roof membrane	Mechanical	Ponding / seams	Re-seal and repair	Year 2-5	$58,000
Dumpster enclosure	Bldg B	Damaged gate	Repair	Reserve	$70,500
Fire extinguishers	Bldg A	Expired tags	Service	Immediate	$52,000
Water heater	Mechanical	Corrosion	Replace	Immediate	$62,000
Window sealant	Roof	Failed	Re-caulk	Year 2-5	$8,500
Water heater	Mechanical	Corrosion	Replace	Reserve	$88,000
HVAC unit	Bldg B	Beyond useful life	Replace RTU	Year 1	$66,000
Roof membrane	Common	Ponding / seams	Re-seal and repair	Year 2-5	$57,000
Fire extinguishers	Common	Expired tags	Service	Reserve	$17,000
Fire extinguishers	Roof	Expired tags	Service	Immediate	$72,000
Fire extinguishers	Common	Expired tags	Service	Reserve	$42,500
Roof membrane	Roof	Ponding / seams	Re-seal and repair	Reserve	$71,000
Window sealant	Common	Failed	Re-caulk	Reserve	$16,000
Window sealant	Mechanical	Failed	Re-caulk	Year 2-5	$3,500
Asphalt paving	Common	Alligator cracking	Mill and overlay	Immediate	$84,500
Dumpster enclosure	Mechanical	Damaged gate	Repair	Immediate	$5,000
Fire extinguishers	Common	Expired tags	Service	Immediate	$12,000
Handrail	Mechanical	Loose	Secure	Immediate	$3,500
Roof membrane	Site	Ponding / seams	Re-seal and repair	Reserve	$81,500
Sprinkler heads	Common	Painted heads	Replace	Immediate	$23,500
HVAC unit	Bldg B	Beyond useful life	Replace RTU	Year 1	$8,500
Handrail	Mechanical	Loose	Secure	Immediate	$35,000
Sprinkler heads	Bldg B	Painted heads	Replace	Year 1	$15,000
Fire extinguishers	Roof	Expired tags	Service	Year 2-5	$1,000
Fire extinguishers	Bldg B	Expired tags	Service	Year 1	$40,500
HVAC unit	Roof	Beyond useful life	Replace RTU	Year 1	$9,500
Water heater	Mechanical	Corrosion	Replace	Reserve	$13,500
Handrail	Bldg A	Loose	Secure	Year 1	$2,500

Report generated 12/18/2019. Figures are unaudited and subject to change.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Certification

I certify that, to the best of my knowledge and belief, the statements of fact contained in this report are true and correct and that I have no present or prospective interest in Sterling Student Living and no personal interest with respect to the parties involved.

The analyses, opinions and conclusions are limited only by the reported assumptions and limiting conditions. The inspection of the property was performed on December 6, 2019.

_____

Tyrone Xu, PE

Harmon & Pike Engineering

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only