PHASE I ENVIRONMENTAL SITE ASSESSMENT

Lantern Valley Health Center | Sacramento, CA

Site	Lantern Valley Health Center
Address	3501 Centennial Way, Sacramento, CA 77833
Prepared For	Vireo Income Properties
Report Date	April 2, 2021
Standard	ASTM E1527-21

Site Description

Surrounding land uses include residential, commercial and light industrial properties of similar vintage. Access to the site is provided by 25 curb cuts and the property is served by municipal water and sanitary sewer. The site contains approximately 26.26 acres and is generally level with frontage along Centennial Way. Utilities, including electric, natural gas and telecommunications, are available to the site from the street. Soils are typical of the region and no evidence of unsuitable conditions was observed at the time of inspection. The site is not located within a designated 100-year floodplain according to the FEMA flood map in effect.

Utilities, including electric, natural gas and telecommunications, are available to the site from the street. Access to the site is provided by 13 curb cuts and the property is served by municipal water and sanitary sewer. The site is not located within a designated 100-year floodplain according to the FEMA flood map in effect. Soils are typical of the region and no evidence of unsuitable conditions was observed at the time of inspection.

Site Reconnaissance

Based on the age of construction, an asbestos operations and maintenance program is recommended for suspect materials. No evidence of underground storage tanks, stained soils or stressed vegetation was observed during the site reconnaissance. Historical sources indicate the site was previously used for agricultural and light commercial purposes. No recognized environmental conditions (RECs) were identified in connection with the subject property. A review of regulatory databases identified no listings for the subject property within the ASTM-specified search distances.

A former dry cleaner located 7 blocks to the north is listed as a closed case and is not expected to impact the site. Historical sources indicate the site was previously used for agricultural and light commercial purposes. No evidence of underground storage tanks, stained soils or stressed vegetation was observed during the site reconnaissance. Based on the age of construction, an asbestos operations and maintenance program is recommended for suspect materials. No recognized environmental conditions (RECs) were identified in connection with the subject property.

Site Description

Surrounding land uses include residential, commercial and light industrial properties of similar vintage. Access to the site is provided by 39 curb cuts and the property is served by municipal water and sanitary sewer. Soils are typical of the region and no evidence of unsuitable conditions was observed at the time of inspection. The site contains approximately 34.34 acres and is generally level with frontage along Centennial Way. Utilities, including electric, natural gas and telecommunications, are available to the site from the street.

The site contains approximately 5.5 acres and is generally level with frontage along Centennial Way. Utilities, including electric, natural gas and telecommunications, are available to the site from the street. Access to the site is provided by 48 curb cuts and the property is served by municipal water and sanitary sewer. The site is not located within a designated 100-year floodplain according to the FEMA flood map in effect. Soils are typical of the region and no evidence of unsuitable conditions was observed at the time of inspection. Surrounding land uses include residential, commercial and light industrial properties of similar vintage.

Historical Use

Based on the age of construction, an asbestos operations and maintenance program is recommended for suspect materials. A review of regulatory databases identified no listings for the subject property within the ASTM-specified search distances. Vapor encroachment screening did not identify a condition requiring further evaluation. Historical sources indicate the site was previously used for agricultural and light commercial purposes.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Site Description

Utilities, including electric, natural gas and telecommunications, are available to the site from the street. The site contains approximately 45.45 acres and is generally level with frontage along Centennial Way. Access to the site is provided by 27 curb cuts and the property is served by municipal water and sanitary sewer. The site is not located within a designated 100-year floodplain according to the FEMA flood map in effect.

Surrounding land uses include residential, commercial and light industrial properties of similar vintage. Soils are typical of the region and no evidence of unsuitable conditions was observed at the time of inspection. The site contains approximately 40.40 acres and is generally level with frontage along Centennial Way. The site is not located within a designated 100-year floodplain according to the FEMA flood map in effect.

Historical Use

Based on the age of construction, an asbestos operations and maintenance program is recommended for suspect materials. Vapor encroachment screening did not identify a condition requiring further evaluation. A former dry cleaner located 5 blocks to the north is listed as a closed case and is not expected to impact the site. Historical sources indicate the site was previously used for agricultural and light commercial purposes. No recognized environmental conditions (RECs) were identified in connection with the subject property. A review of regulatory databases identified no listings for the subject property within the ASTM-specified search distances.

No evidence of underground storage tanks, stained soils or stressed vegetation was observed during the site reconnaissance. Historical sources indicate the site was previously used for agricultural and light commercial purposes. Vapor encroachment screening did not identify a condition requiring further evaluation. A former dry cleaner located 7 blocks to the north is listed as a closed case and is not expected to impact the site. Based on the age of construction, an asbestos operations and maintenance program is recommended for suspect materials. No recognized environmental conditions (RECs) were identified in connection with the subject property.

Access and Utilities

Soils are typical of the region and no evidence of unsuitable conditions was observed at the time of inspection. Access to the site is provided by 16 curb cuts and the property is served by municipal water and sanitary sewer. The site is not located within a designated 100-year floodplain according to the FEMA flood map in effect. Surrounding land uses include residential, commercial and light industrial properties of similar vintage.

Utilities, including electric, natural gas and telecommunications, are available to the site from the street. Surrounding land uses include residential, commercial and light industrial properties of similar vintage. Access to the site is provided by 2 curb cuts and the property is served by municipal water and sanitary sewer. The site contains approximately 41.41 acres and is generally level with frontage along Centennial Way.

Findings and Opinions

No evidence of underground storage tanks, stained soils or stressed vegetation was observed during the site reconnaissance. Vapor encroachment screening did not identify a condition requiring further evaluation. Historical sources indicate the site was previously used for agricultural and light commercial purposes. A review of regulatory databases identified no listings for the subject property within the ASTM-specified search distances.

A former dry cleaner located 7 blocks to the north is listed as a closed case and is not expected to impact the site. Vapor encroachment screening did not identify a condition requiring further evaluation. Historical sources indicate the site was previously used for agricultural and light commercial purposes. A review of regulatory databases identified no listings for the subject property within the ASTM-specified search distances. No evidence of underground storage tanks, stained soils or stressed vegetation was observed during the site reconnaissance. Based on the age of construction, an asbestos operations and maintenance program is recommended for suspect materials.

Topography and Flood Zone

The site is not located within a designated 100-year floodplain according to the FEMA flood map in effect. The site contains approximately 21.21 acres and is generally level with frontage along Centennial Way. Soils are typical of the region and no evidence of unsuitable conditions was observed at the time of inspection. Access to the site is provided by 34 curb cuts and the property is served by municipal water and sanitary sewer.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Regulatory Database Search Results

Database	Search Radius (mi)	Sites Within Radius	Subject Property?	Further Evaluation
NPL (Superfund)	1.0	4	No	None
CERCLIS / SEMS	0.5	7	No	None
RCRA - Generators	0.25	4	No	None
RCRA - TSD	0.5	7	No	None
LUST	0.5	0	No	None
UST	0.25	1	No	Reviewed - no action
State Hazardous Waste Sites	1.0	0	No	None
Brownfields	0.25	7	No	Reviewed - no action
Engineering Controls	0.25	7	No	None
Institutional Controls	1.0	0	No	Reviewed - no action
ERNS	0.5	2	No	None
Drycleaner Facilities	1.0	0	No	None
Solid Waste Landfills	0.25	1	No	None
Voluntary Cleanup	0.25	1	No	Reviewed - no action
Historical Auto Stations	0.5	0	No	Reviewed - no action
NPL (Superfund)	0.5	7	No	None
CERCLIS / SEMS	1.0	1	No	Reviewed - no action
RCRA - Generators	0.5	0	No	None
RCRA - TSD	0.25	1	No	None
LUST	1.0	2	No	None
UST	0.25	7	No	Reviewed - no action
State Hazardous Waste Sites	0.5	1	No	None
Brownfields	0.25	0	No	None
Engineering Controls	0.25	4	No	Reviewed - no action
Institutional Controls	0.5	4	No	None
ERNS	0.5	4	No	None
Drycleaner Facilities	0.25	1	No	Reviewed - no action
Solid Waste Landfills	0.25	2	No	None
Voluntary Cleanup	0.5	2	No	None
Historical Auto Stations	0.5	0	No	None

Report generated 04/02/2021. Figures are unaudited and subject to change.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Certification

I certify that, to the best of my knowledge and belief, the statements of fact contained in this report are true and correct and that I have no present or prospective interest in Lantern Valley Health Center and no personal interest with respect to the parties involved.

The analyses, opinions and conclusions are limited only by the reported assumptions and limiting conditions. The inspection of the property was performed on March 18, 2021.

_____

Marcus Coleman, CPG

Ridgeway Geo-Environmental

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only