PROPERTY CONDITION ASSESSMENT

Foxglove Commons | Birmingham, AL

Property	Foxglove Commons
Address	7845 Pioneer Parkway, Birmingham, AL 41107
Site Visit Date	December 20, 2020
Client	Juniper Peak Real Estate Fund
Immediate Repairs	$346,000

Construction Details

Mechanical systems include rooftop package units and central plant equipment of varying age. Resident turnover has averaged 9.8% annually with renewal retention above 92.5%. Exterior finishes comprise brick veneer, fiber-cement siding and aluminum storefront glazing in good condition. Foxglove Commons was originally constructed in 1971 and consists of 412 apartment homes in a building of 3 stories. Unit interiors feature quartz countertops, stainless appliances, in-unit washer and dryer and plank flooring in select renovated homes.

The community offers a resort-style pool, fitness center, resident clubhouse, package lockers and a dog park. Unit interiors feature quartz countertops, stainless appliances, in-unit washer and dryer and plank flooring in select renovated homes. Average in-place rent is $2,092 per month against an average unit size of 1,018 square feet. The roof is a 9-year membrane system with an estimated remaining useful life of 12 years. Foxglove Commons was originally constructed in 1971 and consists of 412 apartment homes in a building of 26 stories.

Observed Conditions

The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $156,000. Elevators were last modernized 12 years ago and are operating without deficiency. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations.

ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $357,000. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 15 months. Elevators were last modernized 8 years ago and are operating without deficiency. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Domestic water piping is copper and PVC with no evidence of widespread leakage.

Construction Details

Life-safety systems include a fully sprinklered building, addressable fire alarm panel and emergency lighting. Common area interiors have been refreshed within the last 6 years and are in average to good condition. The community offers a resort-style pool, fitness center, resident clubhouse, package lockers and a dog park. Exterior finishes comprise brick veneer, fiber-cement siding and aluminum storefront glazing in good condition. Average in-place rent is $2,092 per month against an average unit size of 1,018 square feet. The roof is a 14-year membrane system with an estimated remaining useful life of 5 years.

Life-safety systems include a fully sprinklered building, addressable fire alarm panel and emergency lighting. Exterior finishes comprise brick veneer, fiber-cement siding and aluminum storefront glazing in good condition. The community offers a resort-style pool, fitness center, resident clubhouse, package lockers and a dog park. Average in-place rent is $2,092 per month against an average unit size of 1,018 square feet.

Observed Conditions

Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Domestic water piping is copper and PVC with no evidence of widespread leakage. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 17 months. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $315,000. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Elevators were last modernized 8 years ago and are operating without deficiency.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Construction Details

Average in-place rent is $2,092 per month against an average unit size of 1,018 square feet. Common area interiors have been refreshed within the last 6 years and are in average to good condition. The roof is a 39-year membrane system with an estimated remaining useful life of 12 years. Life-safety systems include a fully sprinklered building, addressable fire alarm panel and emergency lighting.

Average in-place rent is $2,092 per month against an average unit size of 1,018 square feet. Foxglove Commons was originally constructed in 1971 and consists of 412 apartment homes in a building of 29 stories. Mechanical systems include rooftop package units and central plant equipment of varying age. The structure is of wood-frame, masonry and steel-frame construction on a slab-on-grade foundation. Common area interiors have been refreshed within the last 6 years and are in average to good condition.

Deferred Maintenance

Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Domestic water piping is copper and PVC with no evidence of widespread leakage. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $393,000. Elevators were last modernized 3 years ago and are operating without deficiency.

Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 37 months. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $188,000. Elevators were last modernized 11 years ago and are operating without deficiency.

Construction Details

Life-safety systems include a fully sprinklered building, addressable fire alarm panel and emergency lighting. The roof is a 15-year membrane system with an estimated remaining useful life of 5 years. The structure is of wood-frame, masonry and steel-frame construction on a slab-on-grade foundation. Exterior finishes comprise brick veneer, fiber-cement siding and aluminum storefront glazing in good condition.

Life-safety systems include a fully sprinklered building, addressable fire alarm panel and emergency lighting. Exterior finishes comprise brick veneer, fiber-cement siding and aluminum storefront glazing in good condition. The structure is of wood-frame, masonry and steel-frame construction on a slab-on-grade foundation. Common area interiors have been refreshed within the last 12 years and are in average to good condition. Unit interiors feature quartz countertops, stainless appliances, in-unit washer and dryer and plank flooring in select renovated homes.

Deferred Maintenance

Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $270,000. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Domestic water piping is copper and PVC with no evidence of widespread leakage. Elevators were last modernized 11 years ago and are operating without deficiency. Electrical service is adequate for current demand; select panels are nearing the end of their useful life.

ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $480,000. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 2 months. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations.

Improvements Description

Foxglove Commons was originally constructed in 1971 and consists of 412 apartment homes in a building of 33 stories. The community offers a resort-style pool, fitness center, resident clubhouse, package lockers and a dog park. Life-safety systems include a fully sprinklered building, addressable fire alarm panel and emergency lighting. The structure is of wood-frame, masonry and steel-frame construction on a slab-on-grade foundation.

Average in-place rent is $2,092 per month against an average unit size of 1,018 square feet. Life-safety systems include a fully sprinklered building, addressable fire alarm panel and emergency lighting. Mechanical systems include rooftop package units and central plant equipment of varying age. The community offers a resort-style pool, fitness center, resident clubhouse, package lockers and a dog park. Resident turnover has averaged 5.6% annually with renewal retention above 92.8%. The structure is of wood-frame, masonry and steel-frame construction on a slab-on-grade foundation.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Immediate Repairs and Replacement Reserve Schedule

System	Age (yrs)	EUL	RUL	Condition	Immediate	Reserve (10-yr)
Roof	23	23	0	Poor	$15,000	$224,000
Paving	26	33	7	Fair	$14,000	$265,000
HVAC	11	37	26	Good	$10,000	$11,000
Plumbing	1	13	12	Fair	$40,000	$83,000
Electrical	12	13	1	Fair	$29,000	$88,000
Elevators	9	11	2	Fair	$25,000	$264,000
Fire/Life Safety	16	29	13	Fair	$10,000	$28,000
Windows	10	21	11	Fair	$20,000	$219,000
Siding/Facade	24	26	2	Fair	$4,000	$223,000
Flooring	3	15	12	Fair	$31,000	$166,000
Appliances	5	23	18	Poor	$29,000	$276,000
Landscaping	39	40	1	Poor	$5,000	$140,000
Pool/Amenity	13	17	4	Poor	$25,000	$12,000
Signage	4	39	35	Poor	$1,000	$58,000
Fencing	11	13	2	Fair	$18,000	$64,000
Roof (2)	34	36	2	Fair	$4,000	$268,000
Paving (2)	25	32	7	Poor	$14,000	$120,000
HVAC (2)	3	10	7	Good	$35,000	$42,000
Plumbing (2)	7	26	19	Good	$8,000	$86,000
Electrical (2)	14	28	14	Fair	$39,000	$143,000
Elevators (2)	7	36	29	Fair	$36,000	$263,000
Fire/Life Safety (2)	10	15	5	Poor	$12,000	$153,000
Windows (2)	6	27	21	Fair	$21,000	$73,000
Siding/Facade (2)	21	39	18	Fair	$25,000	$79,000
Flooring (2)	2	10	8	Good	$37,000	$23,000
Appliances (2)	19	19	0	Fair	$11,000	$29,000
Landscaping (2)	5	15	10	Poor	$3,000	$49,000
Pool/Amenity (2)	35	36	1	Poor	$0	$173,000
Signage (2)	21	31	10	Poor	$19,000	$179,000
Fencing (2)	16	22	6	Fair	$36,000	$31,000

Report generated 12/20/2020. Figures are unaudited and subject to change.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Findings and Opinions of Cost

Item	Location	Observed Condition	Recommended Action	Priority	Est. Cost
Dumpster enclosure	Mechanical	Damaged gate	Repair	Year 2-5	$23,000
HVAC unit	Bldg B	Beyond useful life	Replace RTU	Reserve	$84,500
HVAC unit	Bldg B	Beyond useful life	Replace RTU	Year 2-5	$17,500
HVAC unit	Roof	Beyond useful life	Replace RTU	Year 2-5	$58,500
Window sealant	Bldg A	Failed	Re-caulk	Year 2-5	$27,000
Handrail	Bldg A	Loose	Secure	Reserve	$25,000
Handrail	Mechanical	Loose	Secure	Year 2-5	$19,000
Handrail	Bldg A	Loose	Secure	Immediate	$58,000
Fire extinguishers	Mechanical	Expired tags	Service	Reserve	$57,500
Stair treads	Common	Worn / loose	Replace treads	Year 1	$77,500
Sprinkler heads	Roof	Painted heads	Replace	Year 1	$68,000
Dumpster enclosure	Mechanical	Damaged gate	Repair	Year 1	$15,500
Window sealant	Site	Failed	Re-caulk	Reserve	$14,000
Asphalt paving	Roof	Alligator cracking	Mill and overlay	Year 1	$22,000
Asphalt paving	Bldg A	Alligator cracking	Mill and overlay	Immediate	$19,000
Asphalt paving	Common	Alligator cracking	Mill and overlay	Immediate	$63,500
Roof membrane	Bldg B	Ponding / seams	Re-seal and repair	Reserve	$66,500
Roof membrane	Mechanical	Ponding / seams	Re-seal and repair	Reserve	$89,000
HVAC unit	Bldg B	Beyond useful life	Replace RTU	Year 1	$14,500
Water heater	Bldg B	Corrosion	Replace	Year 2-5	$70,500
HVAC unit	Roof	Beyond useful life	Replace RTU	Reserve	$42,000
Sidewalk	Mechanical	Trip hazards	Grind / replace	Year 2-5	$4,500
HVAC unit	Site	Beyond useful life	Replace RTU	Reserve	$75,500
Dumpster enclosure	Bldg B	Damaged gate	Repair	Year 2-5	$80,500
Sprinkler heads	Mechanical	Painted heads	Replace	Reserve	$84,500
HVAC unit	Common	Beyond useful life	Replace RTU	Year 1	$26,000
Asphalt paving	Bldg B	Alligator cracking	Mill and overlay	Year 2-5	$55,500
Stair treads	Site	Worn / loose	Replace treads	Reserve	$58,000
Dumpster enclosure	Bldg A	Damaged gate	Repair	Immediate	$46,500
Window sealant	Bldg B	Failed	Re-caulk	Year 1	$15,500
Window sealant	Bldg A	Failed	Re-caulk	Year 2-5	$20,500
Sprinkler heads	Bldg B	Painted heads	Replace	Year 1	$69,000
Roof membrane	Roof	Ponding / seams	Re-seal and repair	Year 2-5	$31,500
Roof membrane	Site	Ponding / seams	Re-seal and repair	Reserve	$64,500
Asphalt paving	Bldg A	Alligator cracking	Mill and overlay	Reserve	$63,500
Roof membrane	Bldg A	Ponding / seams	Re-seal and repair	Year 2-5	$43,500
Sidewalk	Roof	Trip hazards	Grind / replace	Year 1	$83,500
HVAC unit	Bldg A	Beyond useful life	Replace RTU	Year 2-5	$72,000
Roof membrane	Bldg A	Ponding / seams	Re-seal and repair	Year 2-5	$28,000
Window sealant	Roof	Failed	Re-caulk	Immediate	$10,000
Dumpster enclosure	Site	Damaged gate	Repair	Reserve	$5,000
Sidewalk	Bldg A	Trip hazards	Grind / replace	Reserve	$53,000
Asphalt paving	Common	Alligator cracking	Mill and overlay	Reserve	$81,500

Report generated 12/20/2020. Figures are unaudited and subject to change.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Certification

I certify that, to the best of my knowledge and belief, the statements of fact contained in this report are true and correct and that I have no present or prospective interest in Foxglove Commons and no personal interest with respect to the parties involved.

The analyses, opinions and conclusions are limited only by the reported assumptions and limiting conditions. The inspection of the property was performed on November 28, 2020.

_____

Hannah Quinn, CPG

Harmon & Pike Engineering

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only