IT INCIDENT REPORT

Specialised Treatment Centre — Doha, Qatar — Information Technology Printed: 2026-10-28

Incident	INC-2026-0457
Date	11 October 2026, 02:14
Severity	High
Duration	47 minutes

A **switch failure** on the core **network** caused a partial **outage** affecting the ward workstations and the document capture stations. Failover to the secondary link restored service. Root cause: firmware fault on the primary core switch. Corrective action: firmware **patch** applied; the **firewall** rules were reviewed with the Security team.

Confidential — for the addressee only