## Lab 0

Khari Ollivierre 1450

## Pre-Lab

- 1. 20 minutes
- 2. 10 minutes
- 3. 15 minutes before lab
- 4. 65%
- 5. Dropped, can be made up with documentation
- 6. Yes, lowest lab is dropped
- 7. Iron should touch lead and hole rim, solder should touch lead and hole rim on opposite side.