



Entergy Operations, Inc.
P.O. Box 756
Port Gibson, Mississippi 39150

Jeffery A. Hardy
Manager Regulatory Assurance
Grand Gulf Nuclear Station
Tel: 802-380-5124

10 CFR 50.73

GNRO2025-00031

September 22, 2025

U.S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, DC 20555-0001

SUBJECT: Grand Gulf Nuclear Station, Unit 1 Licensee Event Report 2025-004-00,
Standby Gas Treatment System Train Inoperable Which Led to a Failure
to Identify Condition Prohibited by Technical Specifications

Grand Gulf Nuclear Station, Unit 1
Docket No. 50-416
Renewed License No. NPF-29

Attached is Licensee Event Report (LER) 2025-004-00, Standby Gas Treatment System Train Inoperable Which Led to a Failure to Identify Condition Prohibited by Technical Specifications. This report is being made in accordance with 10 CFR 50.73(a)(2)(i)(B) for any condition which was prohibited by the plants Technical Specifications.

This letter contains no new Regulatory Commitments. Should you have any questions concerning the content of this letter, please contact me at 802-380-5124.

Sincerely,

A handwritten signature in blue ink, appearing to read "JAH" followed by a stylized flourish.

JAH/der

Attachments: Licensee Event Report 2025-004-00

cc: NRC Senior Resident Inspector
Grand Gulf Nuclear Station
Port Gibson, MS 39150

U.S Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, DC 20555-0001

Attachment
Licensee Event Report 2025-004-00



LICENSEE EVENT REPORT (LER)

(See Page 2 for required number of digits/characters for each block)

(See NUREG-1022, R.3 for instruction and guidance for completing this form
<https://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Library, and Information Collection Branch (T-6 A10M), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to Infocollects.Resource@nrc.gov, and the OMB reviewer at: OMB Office of Information and Regulatory Affairs, (3150-0104), Attn: Desk Officer for the Nuclear Regulatory Commission, 725 17th Street NW, Washington, DC 20503. The NRC may not conduct or sponsor, and a person is not required to respond to, a collection of information unless the document requesting or requiring the collection displays a currently valid OMB control number.

1. Facility Name Grand Gulf Nuclear Station, Unit 1	☒ 050	2. Docket Number 00416	3. Page 1 of 2
	☐ 052		

4. Title Standby Gas Treatment System Train Inoperable Which Led to a Failure to Identify Condition Prohibited by Technical Specifications

5. Event Date			6. LER Number			7. Report Date			8. Other Facilities Involved		
Month	Day	Year	Year	Sequential Number	Rev No.	Month	Day	Year	Facility Name	☐ 050	Docket Number
07	24	2025	2025	004	00	09	22	2025	N/A	☐ 052	Docket Number
									Facility Name	☐ 052	Docket Number
									N/A		

9. Operating Mode 1	10. Power Level 100
------------------------	------------------------

11. This Report is Submitted Pursuant to the Requirements of 10 CFR §: (Check all that apply)

☐ 10 CFR Part 20	☐ 20.2203(a)(2)(vi)	☐ 10 CFR Part 50	☐ 50.73(a)(2)(ii)(A)	☐ 50.73(a)(2)(viii)(A)	☐ 73.1200(a)
☐ 20.2201(b)	☐ 20.2203(a)(3)(i)	☐ 50.36(c)(1)(i)(A)	☐ 50.73(a)(2)(ii)(B)	☐ 50.73(a)(2)(viii)(B)	☐ 73.1200(b)
☐ 20.2201(d)	☐ 20.2203(a)(3)(ii)	☐ 50.36(c)(1)(ii)(A)	☐ 50.73(a)(2)(iii)	☐ 50.73(a)(2)(ix)(A)	☐ 73.1200(c)
☐ 20.2203(a)(1)	☐ 20.2203(a)(4)	☐ 50.36(c)(2)	☐ 50.73(a)(2)(iv)(A)	☐ 50.73(a)(2)(x)	☐ 73.1200(d)
☐ 20.2203(a)(2)(i)	☐ 10 CFR Part 21	☐ 50.46(a)(3)(ii)	☐ 50.73(a)(2)(v)(A)	☐ 10 CFR Part 73	☐ 73.1200(e)
☐ 20.2203(a)(2)(ii)	☐ 21.2(c)	☐ 50.69(g)	☐ 50.73(a)(2)(v)(B)	☐ 73.77(a)(1)(i)	☐ 73.1200(f)
☐ 20.2203(a)(2)(iii)		☐ 50.73(a)(2)(i)(A)	☐ 50.73(a)(2)(v)(C)	☐ 73.77(a)(2)(i)	☐ 73.1200(g)
☐ 20.2203(a)(2)(iv)		☒ 50.73(a)(2)(i)(B)	☐ 50.73(a)(2)(v)(D)	☐ 73.77(a)(2)(ii)	☐ 73.1200(h)
☐ 20.2203(a)(2)(v)		☐ 50.73(a)(2)(i)(C)	☐ 50.73(a)(2)(vii)		

☐ Other (Specify here, in abstract, or in NRC 366A).

12. Licensee Contact for this LER

Licensee Contact Jeff Hardy, Regulatory Assurance Manager	Phone Number (Include Area Code) 802-380-5124
--	--

13. Complete One Line for each Component Failure Described in this Report

Cause	System	Component	Manufacturer	Reportable To IRIS	Cause	System	Component	Manufacturer	Reportable To IRIS

14. Supplemental Report Expected

☒ No ☐ Yes (If yes, complete 15. Expected Submission Date)

15. Expected Submission Date

Month	Day	Year

16. Abstract (Limit to 1326 spaces, i.e., approximately 13 single-spaced typewritten lines)

On July 14, 2025, at 12:54 CT, it was identified that the flow recorder [FR] for the Standby Gas Treatment System (SGTS) B train was providing inaccurate information while SGTS B was in standby. SGTS B was determined to be inoperable. A failed flow switch was replaced and SGTS B operability was restored on July 14, 2025.

On July 24, 2025, analysis determined that the flow recorder [FR] began receiving inaccurate information on June 21, 2025. This resulted in a condition that was in violation of Technical Specification (TS) 3.6.4.3, Condition A which states that when one SGTS train is inoperable, it must be restored to operable status within seven days.

The failure to identify the prohibited condition was caused by operator rounds procedures not having a task to review the SGTS flow. An action has been created to update the relevant procedures.

This report is being made in accordance with 10 CFR 50.73(a)(2)(i)(B) for any condition which was prohibited by the plants Technical Specifications.



LICENSEE EVENT REPORT (LER) CONTINUATION SHEET

(See NUREG-1022, R.3 for instruction and guidance for completing this form
<https://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Library, and Information Collection Branch (T-6 A10M), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to Infocollects.Resource@nrc.gov, and the OMB reviewer at: OMB Office of Information and Regulatory Affairs, (3150-0104), Attn: Desk Officer for the Nuclear Regulatory Commission, 725 17th Street NW, Washington, DC 20503. The NRC may not conduct or sponsor, and a person is not required to respond to, a collection of information unless the document requesting or requiring the collection displays a currently valid OMB control number.

1. FACILITY NAME		2. DOCKET NUMBER	3. LER NUMBER		
Grand Gulf Nuclear Station, Unit 1	☒ 050	00416	YEAR	SEQUENTIAL NUMBER	REV NO.
	☐ 052		2025	004	00

NARRATIVE

Plant Conditions:

At the time of the event, Grand Gulf Nuclear Station (GGNS) Unit 1 was in MODE 1 at 100 percent power and all safety systems were operable.

Description of Event:

On July 14, 2025, at 12:54 CT, it was identified that the flow recorder [FR] for the Standby Gas Treatment System (SGTS) B train was providing inaccurate information while SGTS B was in standby. SGTS B was determined to be inoperable. A failed flow switch was replaced and SGTS B operability was restored on July 14, 2025.

On July 24, 2025, analysis determined that the flow recorder [FR] began receiving inaccurate information on June 21, 2025. This resulted in a condition that was in violation of Technical Specification (TS) 3.6.4.3, Condition A which states that when one SGTS train is inoperable, it must be restored to operable status within seven days.

During this time, SGTS A was operable, and capable of fulfilling the SGTS safety function.

Reportability:

This report is being made in accordance with 10 CFR 50.73(a)(2)(i)(B) for any condition which was prohibited by the plants Technical Specifications.

Cause(s):

The failure to identify the prohibited condition was caused by operator rounds procedures not having a task to review the SGTS flow. The cause of the failure to properly detect the inaccurate data and failed flow switch was due to the lack of a task to review the SGTS flow in operator rounds.

Corrective Actions:

- Replace the faulty filter train B flow low switch. Action completed.
- Update 02-S-01-31 Control Room Rounds procedure to include recording values from low flow switches. Action in progress.

Safety Significance:

There were no actual safety consequences associated with this condition. Plant systems responded as designed.

Previous Similar Events:

None