



Edwin D. Dean III
Site Vice President
Vogtle Units 1-2

7821 River RD
Waynesboro GA, 30830
706-848-0001 tel
706-848-3321 fax

February 27, 2023

Docket Nos.: 50-424
50-425

NL-23-0114

U. S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, D. C. 20555-0001

Vogtle Electric Generating Plant Units 1 and 2
Licensee Event Report 2023-001-00
Partial Loss of Offsite Power results in Emergency Diesel Generator and Auxiliary
Feedwater Actuation

Ladies and Gentlemen:

In accordance with the requirements of 10 CFR 50.73(a)(2)(iv)(A), Southern Nuclear Operating Company is submitting the enclosed Licensee Event Report, 2023-001-00 for Vogtle Electric Generating Plant Unit 1 and Unit 2.

This letter contains no NRC commitments. If you have any questions, please contact Jeff Deal at (706) 848-3792.

Respectfully submitted,

A handwritten signature in black ink, appearing to read "Edwin D. Dean III".

Edwin D. Dean III
Site Vice President
Vogtle 1&2

EDD/KCW

Enclosure: Units 1&2 Licensee Event Report 2023-001-00

cc: Regional Administrator
NRR Project Manager – Vogtle 1 & 2
Senior Resident Inspector – Vogtle 1 & 2
RType: CVC7000

**Vogtle Electric Generating Plant Units 1 and 2
Licensee Event Report 2023-001-00
Partial Loss of Offsite Power results in Emergency Diesel Generator and Auxiliary
Feedwater Actuation**

Enclosure

Units 1&2 Licensee Event Report 2023-001-00



LICENSEE EVENT REPORT (LER)

(See Page 2 for required number of digits/characters for each block)

(See NUREG-1022, R.3 for instruction and guidance for completing this form
<http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Library, and Information Collections Branch (T-6 A10M), U. S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by email to Infocollections.Resource@nrc.gov, and the OMB reviewer at: OMB Office of Information and Regulatory Affairs, (3150-0104), Attn: Desk Officer for the Nuclear Regulatory Commission, 725 17th Street NW, Washington, DC 20503; email: oir-submission@omb.eop.gov. The NRC may not conduct or sponsor, and a person is not required to respond to, a collection of information unless the document requesting or requiring the collection displays a currently valid OMB control number.

1. Facility Name Vogtle Electric Generating Plant, Unit 1	☒ 050 ☐ 052	2. Docket Number 00424	3. Page 1 OF 2
--	---	---------------------------	-------------------

4. Title
Partial Loss of Offsite Power results in Emergency Diesel Generator and Auxiliary Feedwater Actuation

5. Event Date			6. LER Number			7. Report Date			8. Other Facilities Involved		
Month	Day	Year	Year	Sequential Number	Revision No.	Month	Day	Year	Facility Name	☒ 050 ☐ 052	Docket Number
01	03	2023	2023	- 001 -	00	02	27	2023	Vogtle, Unit 2		00425
									Facility Name N/A	☐ 052	Docket Number

9. Operating Mode 1	10. Power Level 100
------------------------	------------------------

11. This Report is Submitted Pursuant to the Requirements of 10 CFR §: (Check all that apply)

☒ 10 CFR Part 20	☐ 20.2203(a)(2)(vi)	☒ 10 CFR Part 50	☐ 50.73(a)(2)(ii)(A)	☐ 50.73(a)(2)(viii)(A)	☐ 73.1200(a)
☐ 20.2201(b)	☐ 20.2203(a)(3)(i)	☐ 50.36(c)(1)(i)(A)	☐ 50.73(a)(2)(ii)(B)	☐ 50.73(a)(2)(viii)(B)	☐ 73.1200(b)
☐ 20.2201(d)	☐ 20.2203(a)(3)(ii)	☐ 50.36(c)(1)(ii)(A)	☐ 50.73(a)(2)(iii)	☐ 50.73(a)(2)(ix)(A)	☐ 73.1200(c)
☐ 20.2203(a)(1)	☐ 20.2203(a)(4)	☐ 50.36(c)(2)	☒ 50.73(a)(2)(iv)(A)	☐ 50.73(a)(2)(x)	☐ 73.1200(d)
☐ 20.2203(a)(2)(i)	☒ 10 CFR Part 21	☐ 50.46(a)(3)(ii)	☐ 50.73(a)(2)(v)(A)	☒ 10 CFR Part 73	☐ 73.1200(e)
☐ 20.2203(a)(2)(ii)	☐ 21.2(c)	☐ 50.69(g)	☐ 50.73(a)(2)(v)(B)	☐ 73.77(a)(1)	☐ 73.1200(f)
☐ 20.2203(a)(2)(iii)		☐ 50.73(a)(2)(i)(A)	☐ 50.73(a)(2)(v)(C)	☐ 73.77(a)(2)(i)	☐ 73.1200(g)
☐ 20.2203(a)(2)(iv)		☐ 50.73(a)(2)(i)(B)	☐ 50.73(a)(2)(v)(D)	☐ 73.77(a)(2)(ii)	☐ 73.1200(h)
☐ 20.2203(a)(2)(v)		☐ 50.73(a)(2)(i)(C)	☐ 50.73(a)(2)(vii)		

☐ OTHER (Specify here, in abstract, or NRC 366A).

12. Licensee Contact for this LER

Licensee Contact Jeff Deal, Licensing Manager	Phone Number (Include area code) 706-848-3792
--	--

13. Complete One Line for each Component Failure Described in this Report

Cause	System	Component	Manufacturer	Reportable to IRIS	Cause	System	Component	Manufacturer	Reportable to IRIS
X	FK	LAR	HUBBELL	Y	N/A				

14. Supplemental Report Expected

☒ No	☐ Yes (If yes, complete 15. Expected Submission Date)	15. Expected Submission Date	Month	Day	Year
--	--	------------------------------	-------	-----	------

16. Abstract (Limit to 1326 spaces, i.e., approximately 13 single-spaced typewritten lines)

On January 03, 2023 at 2259 EST, with both Unit 1 and Unit 2 in Mode 1 and 100 percent power, an automatic actuation of the Unit 1 Bravo and the Unit 2 Alpha Emergency Diesel Generator Systems and associated Auxiliary Feedwater Systems occurred. These systems actuated due to the failure of a lightning arrestor associated with the Unit 1 Bravo Reserve Auxiliary Transformer. This resulted in the upstream breaker to the Unit 1 Bravo and Unit 2 Alpha Reserve Auxiliary Transformers opening, causing the Unit 1 Bravo and Unit 2 Alpha emergency electrical buses to de-energize and the automatic start of the associated Emergency Diesel Generator and Auxiliary Feedwater Systems. The units remained in Mode 1 and 100 percent power, and the operating crew performed as expected. The lightning arrestor was replaced and the Reserve Auxiliary Transformers were returned to service.

Due to the automatic actuation of the Emergency Diesel Generator and Auxiliary Feedwater Systems on each unit, this event is being reported under 10 CFR 50.73(a)(2)(iv)(A).



LICENSEE EVENT REPORT (LER) CONTINUATION SHEET

(See NUREG-1022, R.3 for instruction and guidance for completing this form
<http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Library, and Information Collections Branch (T-6 A10M), U. S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by email to Infocollects.Resource@nrc.gov, and the OMB reviewer at: OMB Office of Information and Regulatory Affairs, (3150-0104), Attn: Desk Officer for the Nuclear Regulatory Commission, 725 17th Street NW, Washington, DC 20503; email: oira_submission@omb.eop.gov. The NRC may not conduct or sponsor, and a person is not required to respond to, a collection of information unless the document requesting or requiring the collection displays a currently valid OMB control number.

1. FACILITY NAME Vogtle Electric Generating Plant, Unit 1	☒ 050	2. DOCKET NUMBER 00424	3. LER NUMBER		
	☐ 052		YEAR 2023	SEQUENTIAL NUMBER 001	REV NO. 00

NARRATIVE

NARRATIVE

A. Event Description

On January 3, 2023 at 2259 EST, with both Unit 1 and Unit 2 in Mode 1 and 100 percent power, a partial loss of offsite power occurred due to a failed Hubbell MVN lightning arrestor [LAR] on the Unit 1 Bravo Reserve Auxiliary Transformer (RAT)[XFMR].

This resulted in the upstream breaker [BKR] to the Unit 1 Bravo and Unit 2 Alpha Reserve Auxiliary Transformers opening, causing the Unit 1 Bravo and Unit 2 Alpha emergency electrical buses to de-energize and the automatic start of the associated Emergency Diesel Generator (EDG)[EK] and Auxiliary Feedwater Systems (AFW)[BA].

There were no Structures, Systems, or Components (SSCs) that were out of service at the beginning of the event that contributed to the event.

Due to the actuation of the EDG and the AFW systems this event is being reported in accordance with 10 CFR 50.73(a)(2)(iv)(A).

B. Cause of Event

The cause of the event was a failure of the lightning arrestor on the Unit 1 Bravo Reserve Auxiliary Transformer.

C. Safety Assessment

When the lightning arrestor failed, the upstream breaker for offsite power opened. This resulted in one safety-related electrical bus on each unit becoming de-energized. The EDGs associated with the affected electrical buses started automatically and re-energized the electrical buses. The AFW systems started as a result of the electrical bus being de-energized. All the systems operated as designed. The operating crew responded as expected. The event was within the analysis of the Updated Final Safety Analysis Report, Chapter 15. There were no safety consequences as a result of this event.

D. Corrective Actions

The lightning arrestor for the affected transformer was replaced.

E. Previous Similar Events

None.