Hands-on: Humidity Alert

"Design a state machine with this specification: Button press sets humidity += 10% as threshold. Red LED turns on, as long as monitoring is active. Once threshold has been crossed, blue LED turns on. Button confirms alert, red led turns on 1 s, then off."

device state machine:

