Auto Service Summary

Shop: Performance Tire & Auto, 1735 N Kansas Ave., Topeka, KS 66608

Date: 6/11/2025

Reason For Visit

The customer brought in their 2018 GMC Yukon XL for an inspection and alignment due to issues such as a crooked steering wheel, pulling to one side, potential new parts needing installation, vibrations, and weird noises.

Repair Summary

We conducted a thorough courtesy inspection and addressed several major and moderate repairs to ensure your vehicle is safe and performing optimally.

Major

- Installed two new control arms.
- · Replaced two ball joints.

Moderate

• Performed a vehicle alignment.

Minor

Conducted a detailed tire and wheel inspection.

Cost Breakdown

• Control Arms: \$306.30

• Ball Joints: \$260.26

Alignment: \$119.21

Mechanic Labor: \$942.14

Environmental and Technology Fee: \$3.88

• Job Supplies: \$86.43

• Subtotal: \$1,718.22

• Sales Tax: \$160.65

Total Amount Due: \$1,878.87

What Does This Actually Mean?

We replaced important parts of your suspension system called control arms and ball joints. These help keep the wheels properly aligned with your car's frame. We also realigned your vehicle to ensure it drives straight and true. The tire and wheel inspection ensured no immediate issues remain, keeping the ride smooth and steering safe.

Recommendations

Make use of the 24-month/24,000-mile warranty if you notice any lingering issues or if the problems recur after the repair. Keep an ear out for unusual noises and a hand on how the steering feels in the coming weeks as this can help catch small issues before they become big problems.

This report was generated by ServiceCipher. Contact your repair shop with any questions. © 2025 ServiceCipher.