ServiceCipher Invoice Report

DATE

• June 11, 2025

SHOP_NAME

Performance Tire & Auto, 1735 N Kansas Ave., Topeka, KS 66608

REASON_FOR_VISIT

 Customer reported steering issues, including a crooked steering wheel and possible alignment issues.

REPAIR_SUMMARY

- Performed a detailed courtesy inspection.
- Replaced front control arms.
- Installed new ball joints.
- Conducted a precision alignment.
- Completed a comprehensive tire and wheel inspection.

MAJOR

- Control arm replacement to improve overall steering stability.
- Installation of new ball joints for safer handling.

MODERATE

• Full alignment service to correct steering wheel misalignment.

MINOR

Tire and wheel inspection to ensure safety and evaluate alignment effectiveness.

COST_BREAKDOWN

• Control Arm (2): \$306.30

• Ball Joint (2): \$260.26

Alignment: \$119.21

Mechanic Labor: \$942.14

Enviro & Technology Fee: \$3.88

Job Supplies: \$86.43Subtotal: \$1,718.22Sales Tax: \$160.65

Total Amount Due: \$1,878.87

EDUCATION_SNIPPET

Regular maintenance such as alignment and component inspection ensures long-term vehicle safety and performance. Control arm and ball joint replacements are crucial for maintaining proper wheel alignment and suspension system integrity.

OTHER_NOTES

All service work is covered by a nationwide warranty of 24 months/24,000 miles. For inquiries, please call 1-866-588-0728. We appreciate your trust in Performance Tire & Auto.

RECOMMENDATIONS

- Schedule regular maintenance checks every 6 months to avoid steering and alignment issues in the future.
- Monitor vehicle performance and return if any unusual vibrations or noise occur.
- Consider routine tire rotations to extend tire life and maintain alignment.