

## Digidesign Mbox USB Driver Update Version 1.0.1

### For Pro Tools LE (Mac) v.5.2

Note: Neither the Pro Tools LE 5.2 CD that originally shipped with Mbox or the download of Pro Tools LE (Mac) v.5.2.1 available at [www.DigiProNet.com](http://www.DigiProNet.com) include this updated USB Driver. To download this driver, go to the Support/Downloads section of the Digidesign website at [www.digidesign.com/download](http://www.digidesign.com/download)

**This driver will be included with the next revision of Pro Tools LE v5.2.1 CDs included with retail Mbox packages.**

### What's Fixed with USB Driver v1.0.1?

- The USB Driver Update fixes a problem that could result in corrupted audio recordings. Typically, the recorded audio would contain clicks and pops after long periods of recording time. Digidesign recommends that all Mbox users replace their "Digidesign USB Driver" version 1.0 (located in the System Folder /Extensions Folder) with this version 1.0.1 driver.

### Who Should Use this Update?

- All Mbox Users

### Updating the Digidesign USB Driver for Mbox

1. Download the Digidesign USB Driver version 1.0.1 from [www.digidesign.com/download/mbox.html](http://www.digidesign.com/download/mbox.html)
2. If the download does not automatically expand, use [Stuffit Expander](#) version 5.1 or higher to expand. The expanded folder will be named "Digidesign USB Driver v1.0.1".
3. Quit Pro Tools LE or any other audio application currently accessing Mbox.
4. Unplug the USB cable from Mbox
5. Place the new Digidesign USB Driver v1.0.1 in the Extensions Folder inside the System Folder.
6. Click "OK" when prompted to replace the current file. (it is not necessary to restart)
7. Reconnect the USB cable to Mbox
8. Once the "USB" LED on the front of the unit is lit, re-launch Pro Tools and continue working. If the USB LED does not light, unplug and then replug the USB cable back into the computer.