Equipment Inspection Form

Northwind Analytics, Inc.

Asset: Cooling loop flange FL-204
Site: Plant 3, Bay C
Inspection date: 2026-09-18
Inspector: R. Okafor

SECTION B - VISUAL CHECKS

☐ Gasket intact	☑ Labels legible
☑ No visible corrosion	☐ Guard in place
☑ Weld seams sound	☑ No leaks observed
☑ Bolts torqued to spec	☑ Grounding connected

Inspector notes

Hairline crack at weld, east flange.
Recommend replace gasket before Q4.
Re-inspect in 30 days - R. Okafor

Findings summary

1. Visual checks: 6 of 8 items passed; gasket and guard require action.

2. A crack was found at the weld seam at the pipe-to-flange joint; see the defect photo on page 2.

3. Asset tagged and removed from the active inspection schedule pending repair.

Inspector signature - R. Okafor

Equipment Inspection Form (continued)

Defect photo




Photo ref D-0417: crack at the weld seam at the pipe-to-flange joint, east flange FL-204. The yellow arrow marks the crack; light rust staining is visible below it.

Disposition: Open - replace gasket, repair weld and re-inspect in 30 days.