


Extreme to Faye

Jefferson County to Belmont County



Driving Directions

When exiting the lease road, turn left onto CR 14.

Drive 1.15 miles to stop sign at CR 15. Turn right.

Drive 0.2 mile and turn right to continue on CR 15.


Drive 3.2 miles to stop sign at OH 150. Turn left.

Drive 0.5 miles and turn left onto Old State Route 7 just across the railroad tracks.

Drive 0.3 mile and turn right onto ramp to OH 7 south.

Drive 28 miles on OH 7 to the signal in Powhatan Point.

Any loads requiring an ODOT moving permit will also require a county moving permit. Contact Eric Hilty at 740-283-8574



At the signal in Powhatan Point, turn right onto OH 148. Drive 17 miles.

Turn left onto CR 92. Drive 0.1 mile.

Turn right onto Mt. Horeb Road. Access will be on the right.

Total length, 51.3 miles.

Any loads requiring an ODOT moving permit will also require a county moving permit. Permit information can be found at <http://belmontcountyengineer.com/data/forms/>