


## Heston Take Point Haul Route

### Jefferson County

From the south:



### Driving Directions

While going north on OH 7, take the Rayland-Dillonvale exit for OH 150 north of Tiltonsville.

Make a right onto Liberty Avenue at the bottom of the exit and drive 0.25 miles.

Turn right onto OH 150.

Drive 3.5 miles and turn left onto TR 112.

Turn left as soon as you go under the railroad bridge.


Take point is ahead on the left.

Please note that in order to leave on OH 7 south, make a left onto Old State Rt. 7 just past the railroad tracks and prior to the overpass in Rayland and drive 0.5 miles to the on ramp.

Any loads requiring an ODOT moving permit will also require a county moving permit. Contact Eric Hilty at 740-283-8574



**From the north:**



### **Driving Directions**

**While going south on OH 7, take the Rayland Dillonvale exit for OH 150 south of Brilliant.**

**Make a left at the bottom of the ramp and drive 0.3 miles.**

**Turn right onto OH 150.**

**Drive 3.5 miles and turn left onto TR 112.**

**Turn left as soon as you go under the railroad bridge.**

**Take point is ahead on the left.**

**Please note that in order to leave on OH 7 north, continue straight past the railroad tracks and past the overpass.**

**Make a left onto Liberty Avenue.**

**Drive 0.3 mile to the north bound on ramp.**

**Any loads requiring an ODOT moving permit will also require a county moving permit. Contact Eric Hilty at 740-283-8574**