


## Horsemill Haul Route, Revised

### Belmont County



### Driving Directions

From the interchange of OH 7 and the Moundsville Bridge in Dilles Bottom, drive 1.2 miles north on OH 7.

Turn left onto TR 534, Broadview Road.

Drive 3.1 miles and turn left onto TR 296, Cash Ridge.

Drive 3 miles and turn left onto TR 298, Lockwood Run Road.

Drive 1.5 miles and keep left onto TR 501, Horsemill Hill Road.

Drive 0.4 mile. Access will be on the right.

## **From the west:**

**From the OH 9 and OH 147 intersection in Centerville (OH 9 south of St. Clairsville), drive east on OH 147 for 6.2 miles.**

**Turn right onto CR 48, Wegee Road just past the gasoline station/corner store.**

**Drive for 0.9 mile and turn right onto TR 296, Cash Ridge Road.**

**Drive 1.4 mile and turn right onto TR 298, Lockwood Run Road.**

**Drive 0.5 mile and keep left onto Lockwood Run Road.**

**Drive 1.5 miles and keep left onto TR 501, Horsemill Hill Road.**

**Drive 0.4 mile. Access will be on the right.**

**Any loads requiring an ODOT moving permit will also require a county moving permit. Contact John Parkinson at 740-699-2160. Permit information can be found at <http://belmontcountyengineer.com/data/forms/>**

**Any load requiring an ODOT moving permit will also need a Mead Township permit. Contact Ed Good at 740-312-8411**