


Lance Haul Route

Belmont County



Driving Directions

From the east, west and south:

From the intersection of I-470 and OH 7, drive north for 5.5 miles and turn left on CR 4, Glenns Run Road.

Drive 0.5 mile and turn right on CR 16, Nixon Run Road.

Drive 1.8 miles. Access will be on the left.

From the north:

From the intersection of OH 647 and CR 2 south of Mt. Pleasant, drive 1.9 miles east on CR 2, Deep Run Road.

Bear left on CR 16, Nixon Run Road.

Drive 1 mile. Access will be on the right.

Notes:

All overlength loads need to come from Mt. Pleasant on OH 647 to CR 2, Deep Run.

For loads over 100,000#, please contact Bob Whipp @ 740-310-8748.

All vehicles requiring an ODOT moving permit will also need a permit from the Belmont County Engineer at 740-699-2160.