


Lance, Ridgetop and Ware Inbound Completions Truck Traffic


Belmont County



Driving Directions

From the intersection of OH 7 and US 250 in Bridgeport, drive 11 miles west on 250 to the turn-around just past a sharp right hand turn.

Use the second entrance to enter and the first entrance to exit.



From the turn-around, drive back on US 250 for 0.4 miles and turn left onto OH 150.

Drive 3.8 miles to the intersection with OH 647 in Mt. Pleasant.

Go straight onto OH 647 for 4.6 miles and turn left onto TR 466, Barnes Road.



For the Ware:

Drive 1.1 miles. Access will be on the right.

For the Ridgetop:

Drive 1.4 miles to the stop sign. Turn left onto TR 464, Treadway Road.

Drive 0.1 mile to the stop sign and turn right onto CR 16, Nixon Run Road.

Drive 0.2 miles. Access will be on the left.

For the Lance:

Drive 1.4 miles to the stop sign. Turn left onto TR 464, Treadway Road.

Drive 0.1 mile to the stop sign and turn right onto CR 16, Nixon Run Road.

Drive 0.6 miles. Access will be on the right.