


ORC Haul Route

Belmont County



Driving Directions

From the East:

70 WB

When going west on I-70, take exit 218 and turn left at the signal.

Drive 0.2 mile and turn right at the 2nd signal onto US 40 east.

Drive 1.1 miles and turn left onto TR 437, Hindman Road.

Drive 0.2 mile and turn left onto the lease Road.

I-470 WB

When going west on I-470, take Exit 1 and turn right at the stop sign.

Drive 0.1 mile and turn right onto US 40 east at the signal.

Drive 0.5 mile and turn left onto TR 437, Hindman Road.

Drive 0.2 mile and turn left onto the lease road.

From the West:

When going east on I-70, take exit 218 and turn right at the signal.

Drive .5 mile and turn right onto US 40 east at the 3rd signal.

Drive 1.1 miles and turn left onto TR 437, Hindman Road.

Drive 0.2 mile and turn left onto the lease Road.

Any loads requiring an ODOT moving permit will also require a county moving permit. Permit information can be found at <http://belmontcountyengineer.com/data/forms/>