


Ridgetop Haul Route

Belmont County

From the west:

For all vehicles including Semis.



Directions:

From the intersection of OH 647 and CR 2, Deep Run Road south of Mt. Pleasant, drive southeast on CR 2 for 1.8 miles.

Bear left onto CR 16, Nixon Run.

Drive 0.5 miles. Access will be on the left.


For vehicles over 100,000 pounds, contact a Gulfport representative.

Note:

All vehicles requiring an ODOT moving permit will also need a permit from the Belmont County Engineer at 740-699-2160.

From north or south on RT. 7

Driving Directions for passenger vehicles:



Driving directions for vehicles smaller than a semi:


From the intersection of OH 7 and CR 4, Glenns Run Road at the north end of Martins Ferry, go west on CR 4 for 0.5 miles.

Turn right onto CR 16, Dixon Run Road.

Drive 2.4 miles. Access will be on the right.

From the north or south on Rt. 7

Driving directions for semis:



From the intersection of OH 7 and CR 4, Glenns Run Road at the north end of Martins Ferry, go west on CR 4 for 0.5 miles.

Turn right onto CR 16, Dixon Run Road.

Semis will need to go past the pad entrance for another 1.3 miles.

Turn left into gravel turnaround.

Head back to the Ridgetop, 1.3 miles.

Note:

All vehicles requiring an ODOT moving permit will also need a permit from the Belmont County Engineer at 740-699-2160.