

Stout Haul Route

Harrison County



Driving Directions

From the west:

From the intersection of US 22 and OH 800 north just west of Piedmont, drive 2.7 miles east and turn right onto CR 16, Old Piedmont Road.

Drive 1.3 miles and turn left onto the lease road.

From the East:

From the intersection of US 22 and OH 331 in Piedmont, drive west for .1 mile and turn left onto CR 16, Old Piedmont Road.

Drive 1.3 miles and turn left onto the lease road.

Any loads requiring an ODOT moving permit will also require a county moving permit.

Contact Kris Miller at 740-942-8867. More information can be found at

<http://www.harrisoncountyohio.org/county-engineer-permits>