


Stronz Impoundment to Vaughn Impoundment




Driving Directions

When you leave the Stronz Impoundment, turn right on TR 29, Flat Rock Road.

Drive 0.4 miles and turn right to continue on Flat Rock Road.

Drive 1.6 miles and turn left at the stop sign onto OH 800.

Drive 13.7 miles to the signal in Woodsfield at McDonalds.



Turn right and drive 0.1 mile to the next traffic signal.

Turn left onto OH 78.

Drive 1.7 miles and turn right onto CR 41, Sugartree Cranesnest Road.

Drive 1.1 miles and turn right onto TR 354, Newhart Ridge.

Drive 0.2 miles and turn left into the Vaughn access.

**Any loads requiring an ODOT moving permit will also require a county moving permit.
Contact John Parkinson at 740-699-2160. Permit information can be found at
<http://belmontcountyengineer.com/data/forms/>**