


TR 112 WT Haul Route

Jefferson County



Driving directions:

From the south:

Going north on OH 7 at Rayland, take the OH 150 Rayland Dillonvale exit and turn right at the end of the ramp.

Drive 0.25 mile and turn right onto OH 150.

Drive 3.5 miles. Turn left onto TR 112. Project begins just past the railroad.

From the north:

When coming south from Steubenville, take the OH 150 Rayland Dillonvale exit.

Turn left at the end of the ramp and drive 0.3 mile.

Turn right onto OH 150 and drive 3.4 miles.

Turn left onto TR 112. Project begins just past the railroad.