


Ware Haul Route

Belmont County



Driving Directions

From the east, west and south:

From the intersection of I-470 and OH 7, drive north for 5.5 miles and turn left on CR 4, Glenns Run Road.

Drive 0.5 mile and turn right on CR 16, Nixon Run Road.

Drive 2.4 miles and turn left onto TR 464, Treadway Road.

Drive 500 feet and turn right onto TR 466, Barnes Road.

Drive 0.3 miles. Access will be on the left.

Any loads requiring an ODOT moving permit will also require a county moving permit. Contact John Parkinson at 740-699-2160. Permit information can be found at <http://belmontcountyengineer.com/data/forms/>

From the north:

THIS ROUTE IS LIMITED TO 100,000#. FOR LOADS GREATER THAN 100,000#, CONTACT GULFPORT FOR DIRECTIONS.

From the intersection of OH 647 and CR 2 south of Mt. Pleasant, drive 1.9 miles east on CR 2, Deep Run Road.

Bear right on CR 16, Nixon Run Road.

Drive 0.4 miles and turn right onto TR 464, Treadway Road.

Drive 500' and turn right onto TR 466, Barnes Road.

Drive 0.3 miles. Access will be on the left.

Any loads requiring an ODOT moving permit will also require a county moving permit. Contact John Parkinson at 740-699-2160. Permit information can be found at <http://belmontcountyengineer.com/data/forms/>