

State Energy Resilience Review

Report section: 4.2 Distribution Readiness

Docket: SER-2026-14

4.2.1 Scope

This section covers transformer inventory, feeder inspection cadence, and emergency mutual-aid triggers.

Finding A

Inventory coverage is adequate for urban substations but below threshold for rural feeders RF-12 and RF-19.

Finding B

The mutual-aid trigger is currently set at 72 hours. Staff recommends changing it to 48 hours.

> Compliance notice: utilities must preserve the incident code SER-2026-14-B in public filings.

Appendix 4B: Threshold Table

Metric	Current	Proposed
Rural spare transformer coverage	62%	80%
Mutual-aid trigger	72h	48h
Feeder inspection interval	18 mo	12 mo