



Incident ID:	inc_1
Logged By (Rep):	Clarence Kuiken
Report Date:	2026-05-28
Affected Part Number:	86286761
Area Discovered:	Scrap table at Sequence Area
Defect Coordinates:	X: 0.3 Y: 0.5
Immediate Action:	Removed bulb, returned light to sequence area
Supplier QM Contact:	Martin
Review Status Level:	Closed
Classification Reasoning:	Sensitive defect narrative detected

Affected Parts Checklist:

PN 86286761 - Tail Light Assembly (Qty: 1, Bin: BIN-MAG-6761)

Defect Narrative details:

Light on scrap table at sequence area for rattle. Spare bulb in housing again. Removed bulb and returned light to sequence area. Bulb was removed before scrap tag was written up. Please ensure all base lights do not have spare bulbs in housing causing rattling sound.