

Incident ID:	inc_3
Logged By (Rep):	Clarence Kuiken
Report Date:	2026-05-28
Affected Part Number:	86286761
Area Discovered:	Online assembly
Defect Coordinates:	X: 0.5 Y: 0.74
Immediate Action:	Realigned gasket, initiated Sort / RMA action
Supplier QM Contact:	Martin
Review Status Level:	Red Alert
Classification Reasoning:	Critical alert status / RMA required

Affected Parts Checklist:

PN 86286761 - Tail Light Assembly (Qty: 1, Bin: BIN-MAG-6761)

Defect Narrative details:

Gasket seal misaligned, creating outer gap on right edge. CRITICAL SAFETY ISSUE: Possible water leakage into tail light casing causing circuit short and immediate signal failure. High risk of field recall. Requires immediate supplier sort and RMA containment.