==========

DETAILED DEFECT REPORT (DDR)

==========

1. Property Issue Summary

Leakage due to damage in Nahani trap/Brickbat coba under, Condition of separation cracks observed at beam-column, Observed mild dampness at the ceiling of, Condition of leakage at adjacent walls, outlet Leakage, Dampness, Observed dampness & efflorescence on, Observed dampness at the skirting level, Observed cracks on the External wall of building, Condition of leakage observed from overhead water tank, Leakage during:, Hall Skirting level Dampness, Condition of leakage below WC, Parking Area seepage, Internal WC/Bath/Balcony leakage observed, Are there any major or minor cracks observed over external, Are the external plumbing pipes cracked and leaked? If yes its, External wall crack and Duct, Leakage due to concealed plumbing, Observed leakage at the Parking ceiling, Condition of leakage at interior side, Condition of cracks observed on RCC Column and Beam

2. Area-wise Observations

- Leakage due to damage in Nahani trap/Brickbat coba under
- Condition of separation cracks observed at beam-column
- Observed mild dampness at the ceiling of
- Condition of leakage at adjacent walls
- outlet Leakage
- Dampness
- Observed dampness & efflorescence on
- Observed dampness at the skirting level
- Observed cracks on the External wall of building
- Condition of leakage observed from overhead water tank
- Leakage during:
- Hall Skirting level Dampness

- Condition of leakage below WC
- Parking Area seepage
- Internal WC/Bath/Balcony leakage observed
- Are there any major or minor cracks observed over external
- Are the external plumbing pipes cracked and leaked? If yes its
- External wall crack and Duct
- Leakage due to concealed plumbing
- Observed leakage at the Parking ceiling
- Condition of leakage at interior side
- Condition of cracks observed on RCC Column and Beam

3. Probable Root Cause

Possible structural moisture intrusion

Ventilation issues

Material ageing or leakage pathways

4. Severity Assessment

Overall Severity Level:

High severity due to multiple structural indicators

5. Recommended Actions

Conduct detailed site verification

Repair affected structural components

Monitor moisture spread using thermal tools

Schedule maintenance follow-up inspection

6. Additional Notes

Inspection Data Length: 7375 characters

Thermal Observations Count: 180

7. Missing Information

No missing inspection information detected.

8. Conflict Detection Summary

No conflicts detected between inspection and thermal data.

Inspection Images

UrbanRoof

UrbanRoof

Flat - 908

UrbanRoof

UrbanRoof

UrbanRoof

UrbanRoof

UrbanRoof

UrbanRoof

UrbanRoof

UrbanRoof

UrbanRoof

UrbanRoof

UrbanRoof

UrbanRoof

UrbanRoof

Flat - 908

UrbanRoof

UrbanRoof

Flat - 908

UrbanRoof