## SDNALIKA

## INTERNATIONAL TRACTORS LIMITED

Vill. Chak Gujran, P.O. Piplanwala , Jalandhar Road, Hoshiarpur

## Warranty Claim

										PRINT		
OUNTRY NAME BANGLADESH				DBR NAME ACI LTD			D	DBR CODE			2700036	
DEALER NAME	ACI BARISAL Barisal			DEALER ADDRESS			Barisal		CUSTOMER NAME		Jabed Hossain	
CUSTOMER ADDRESS												
Warranty Claim No	2700036	-9476B7-2022-67		Card No		2700036-94			ssis No		ZVDR1107397S3 2-Dec-2022	
Tractor Model	DI 47 RX SUPREME			Engine No 3105ELU14I11			1101768	01768 Job Card Date Date of Failure			2-Dec-2022 2-Dec-2022	
Date	22-Dec-2022 22-Nov-2021			Last Service Date Hours Worked 1235.00					oice No		602803904	
Date of Sale	22-1104-2	2021	110	uis vvoiked		GEAR OIL V	VAS COMI	NG				
ast Service Hours			Cu	stomer Compla	aint	FROM THE HOUSING.						
Invoice Date	23-Sep-2	2021	Bu	yer Ref No								
PDI & Service Details												
PDI 1s	1st Service		3rd Serv	ice	4th Service		5th Service		6th Service		7th Service	
04-Oct-2021												
Complaint Details												
Aggregates Sub Aggregates				Complaint C					Complaint Desc			
ENGINE				CL13				CLUTCH-PLATE FACINGS WITH OIL/GREASE			SWITH	
Part Details												
Complaint Code	T .	Failure Type	P	art No	Pa	rt Descripti	on	Quantity	Billing Ty	30	SE Analysis	
	CONSEQUEN		0407025			50.68.10		1.00	WARRANTY			
	CONSEQUEN		0407022			35*25*7		1.00	WARRANTY			
	CULPRIT PAR		0400015			RING 6210		1.00	WARRANTY			
abour Detail(B)												
Complaint Code	Action Taken			Labour Code			Labour Hours			Labour Charg		
Data not available.												
Consumables C									-		the second secon	
Complaint Code	Description			Qty				Rate	Rate Amount			
Data not available.												
OutsideJob (D)												
Complaint Code	Details of Job			BillNo			Date A		Amou	int		
Data not available.										741100		
Claim Summary												
Part(A)			Labour (B)									
Outside Job (D)								Consumables (C)  Total(A+B+C+D+E) 22850				
			Sale lax (E)					Total(A+B+	C+D+E)	22850		
Culprit Part No	04000	0150090		Culprit Part I	Name	-						
Dealer Analysis	AFTER INSPECTION WE FOUND THAT BALL BEARING 6210 HAS & DRIVE SHAFT Z-18 TEETH HAS CORRODED.				Dealer Action Taken				Complaint status Close			

