

INTERNATIONAL TRACTORS LIMITED

Vill. Chak Gujran, P.O. Piplanwala , Jalandhar Road, Hoshiarpur

Warranty Claim

											PRIN	NT	
COUNTRY NAME	BANGLADESH			DBR NAME			ACI LTD			DBR CODE		2700036	
DEALER NAME	ACI BOGRA BOGRA			DEALER ADDRESS			Bogra			CUSTOMER NAME		Md.Moti Miah (Ullahpa	
CUSTOMER ADDRESS													,
Warranty Claim No	2700036-9476B3-2023-10			Job	JobCard No			2700036-9476B3-2023-204		Chassis No		BXCDJ113552	783
Tractor Model	ALL ROUNDER 55 SUPREME			Engine No			4100FL24A1135846		Jol	b Card Date		16-Jan-2023	
Date	16-Jan-2023			Last Service Date					Da	ite of Failure		16-Jan-2023	
Date of Sale	23-Feb-2022			Hours Worked			1597.00			voice No		3602806985	
Last Service Hours				Cus	stomer Comp	laint	ROTAVATOR SLOWLY AU						
Invoice Date	21-Jan-2022				Buyer Ref No			TOWATIO	JALLI.				
IIIVOIGO DATO												STATE OF THE PROPERTY OF THE PARTY OF THE PA	
PDI & Service Details								ru		I			
PDI	1st Service	2nd Service	nd Service		3rd Service		4th Service		5th Service		6th Service	7th Service	
03-Feb-2022													
Complaint Details													
Data not available.													
Data not available.											and the residence of the later		
Part Details													
Compleint Code	Failure	Type	Par	t No	T	Part De	scription		Quantity	Billin	g Type	SE Analy	ais
Complaint Code	CULPRIT PART N		10012651		FEATHERIN			_	1.00	WARRAN		Om Mini	310
Complaint Code Action Taken					Labour Code				Labour Hours			Labour C	harg
Data not available.													
Consumables C													
Complaint Code	nint Code Description				Qty Rai					ate Amount			
Data not available.													
Data not available.													
OutsideJob (D)												TOTAL CONTRACTOR AND ADDRESS OF THE PARTY OF	-
Complaint Code	Details of Job				BillNo				Date	Date Amount			
Data not available.	V												
Claim Summary													
Dod(A)			Labour	· (B)					Consumabl	les (C)			
Part(A)	Sale Tax (E)				0			Total(A+B+C+D+E) 22850			0		
Outside Job (D)			Sale la	ax (C)		-			IUIAI(A+B+	J.D.E)	2230		
Culprit Part No	10012651	AB			Culprit Part	Name							
Dealer Analysis	AFTER INSPECTION WE FOUND THAT FEATHERING VALVE COULD NOT BUILD PRESSURE.				Dealer Action Taken					Complaint status Close			

