

Quality Control Inspection Report: Industrial Solar Panels

Date: July 9, 2026

Report ID: QC-SP-2026-004

Subject: Inspection Findings – Batch #SOL-2026-B08

Site Location: [Insert Site Location]-----**Inspection Summary:**

A comprehensive quality control inspection was conducted on the most recent delivery of industrial solar panels (Batch #SOL-2026-B08) upon arrival at the site. The inspection focused on visual integrity, frame alignment, and internal structural soundness via micro-crack detection testing.

Findings:

While the majority of the batch met the project's technical specifications, the micro-crack detection testing identified significant structural non-conformities.

- **Total Panels Inspected:** [Insert Total Count]
- **Defective Units Identified:** 15% of the total batch
- **Primary Issue:** Micro-cracking detected in crystalline silicon cells, compromising panel output efficiency and long-term durability.

Action Required:

Given the critical nature of these components to the project's performance benchmarks, the identified defective units are deemed unsuitable for installation.

- **Immediate Action:** The affected 15% of the batch has been quarantined in the holding area to prevent accidental installation.
- **Resolution:** Please initiate the Return Merchandise Authorization (RMA) process immediately to return these units to the manufacturer. A replacement shipment must be expedited to avoid further impact on the construction schedule.

We require a formal remediation plan and the revised shipping schedule from the vendor by end of business tomorrow to ensure project continuity.-----**Report**

Prepared By:

John Doe

[Company/Organization]

Would you like me to draft a cover letter to the manufacturer regarding this return?