SmartSketch Environment - Quick Lab

- 1. Select the *Circle by 3 Points* command from the *Circle* fly-out on the *Draw* toolbar.
- 2. Review the properties for circle placement in the *Dynamic Ribbon Bar*.
- 3. Follow the prompts displayed in the Status Bar and place a circle.
- 4. Select the *Esc* key or the *Select Tool* to terminate the command.
- 5. Move the cursor around the drawing sheet and read the *Cursor Coordinate Display*.
- 6. Display the *Dimension* and *Change* toolbars and dock them under the *Main* toolbar.
- 7. Undock the *Dimension* toolbar and leave it floating in the application window.
- 8. Select the *Fit* command from the *Main* toolbar to display all objects on the sheet.
- 9. Select the *New Window* command from the *Window* pull-down menu to create a new window.
- 10. Select the *Zoom Area* command and zoom in to the circle.
- 11. Select the *Tile Horizontally* command from the *Window* pull-down menu.
- 12. Close one of the windows using the *Close* icon in the upper right corner of the window.
- 13. Maximize the remaining window using the *Maximize* icon.
- 14. Exit SmartSketch Drawing Editor without saving the document.