

Product: RTL8811C/RTL8821C/RTL8731A USB Software Package - Linux

Driver

Version: v5.8.1.4_36409.20200313_COEX20191014-4141

Release History:

Release mistory:		
v5.2.5_21684.20170329_C	1.	First release.
OEX20170310-1212		
v5.2.5.1_22211.20170517_		Fix not expected IQK
COEX20170310-1212	2.	Update adaptivity for new ETSI spec. (CE-RED)
v5.2.5.2_23102.20170725_	1.	Add 8811CU PID VID
COEX20170310-1212	2.	Update phydm
v5.2.5.3_24795.20171031_	1.	Fixed WPA2 vulnerability - key reinstallation
COEX20170310-1212		attacks(KRACKs)
v5.2.15_26201.20180116_C	1.	Update BT coex to 20171114-2525
OEX20171114-2525	2.	Update phy parameters to 0x48
	3.	Support 8811CU
	4.	Support Android 8.0
	5.	Support LED
	6.	Support Kernel 4.12.12
		Fix monitor mode can not sniffer Beacon pkt
	8.	Correct SoftAP Beacon TIM IE
v5.2.15.1_27326.20180403	1.	Supoort Android O CTS/VTS testing
_COEX20171114-2525	2.	Support DFS Slave CSA action frame
	3.	Fix DFS Master issue
	4.	Fix some RFE type efuse power index issue
v5.2.15.2_27778.20180515	1.	Fix MU-MIMO with some AP IOT issue
_COEX20171114-2525		
v5.2.15.3_28211.20180611		Fix compile errror when kernel version less than 3.0
_COEX20171114-2525	2.	Fix WOWLAN GPIO wakeup can not control GPIO 6, 7
v5.4.1_28754.20180921_C	1.	Update BT coex to 20180712-3232
OEX20180712-3232	2.	Update phy parameters to 0x49
	3.	Support Mesh
	4.	Support Linux kernel 4.16
	5.	1 1
		Fix Softap mode 8 STA connected issue
	7.	Fix some DFS issue
v5.4.1.1_31831.20181227_	1.	Support RWTK feature
COEX20180712-3232		
v5.8.1_34171.20190628_C	1.	Update BT coex to 20190509-4141
OEX20190509-4141	2.	Update phy parameters to 0x54
	3.	Support WPA3-SAE (Personal)
	4.	Support Kernel 5.0
	5.	
v5.8.1.1_34311.20190729_	1.	Fix WPA3 concurrent issue
COEX20190509-4141	2.	8 1
v5.8.1.2_35530.20191025_	1.	Hotfix P2P NoA buffer potentially overflow
COEX20191014-4141		
v5.8.1.3_35898.20191211_	1.	Support up to kernel 5.3





COEX20191014-4141	
v5.8.1.3_35898.20200225_	1. Support 8731AU
COEX20191014-4141	
v5.8.1.4_36409.20200313_	1. Support 8731AU PID
COEX20191014-4141	2. Fix compiler error for WPA3
	3. Fixed for BT can't write eFuse
	4. Fix MP mode bug





Description:

Realtek provides the solution for WLAN in hardware and software. The software package could be adopted for Realtek RTL8811C/RTL8821C/RTL8731A USB WLAN series hardware on Linux based platforms.

Software Version:

RTL8811C/RTL8821C/RTL8731A USB Linux Driver Version: v5.8.1.4 36409.20200313 COEX20191014-4141

Hardware Supported:

- RTL8811CU
- RTL8821CU
- RTL8731AU

Software Package Feature:

- IEEE 802.11 b/g/n/ac WiFi compliant
- 802.1x, WEP, WPA TKIP and WPA2 AES/Mixed mode for PSK and TLS (Radius)
- WPA3-SAE (Personal)
- WPS PIN and PBC Methods
- IEEE 802.11b/g/n/ac Client mode
 - Support wireless security for WEP, WPA TKIP and WPA2 AES PSK
 - Support site survey scan and manual connect
 - Support WPA/WPA2 TLS client
 - Support power saving mode
- Soft AP mode
- WiFi-Direct
- Miracast
- MU-MIMO
- BT-COEXist
- Mesh
- Wake on WLAN

Platform Supported:

- Linux (kernel 2.6.18 ~ 5.3)
- Android $1.6 \sim 2.3$, $4.0 \sim 9.x$

CPU supported:

- x86
- ARM
- MIPS