

GOVERNMENT OF INDIA • MINISTRY OF COAL

COAL INDIA LIMITED (CIL) • CENTRAL MINE GOVERNANCE SYSTEM

Official Statutory Inspection & Compliance Audit Report — Generated: 2026-09-29 12:05 UTC

Report Ref No:	REP-260929-051B58	Inspection Date:	2026-09-28
Mine Facility:	Rajmahal Open Cast Project (ECL-OCF-01)	Subsidiary:	Eastern Coalfields Limited
Contractor Agency:	Direct Operations	Inspecting Officer:	Amitabh Singh (Senior Overman / Safety Inspector)
Inspection Type:	Safety	Geo-Coordinates:	25.0489° N, 87.3821° E
Compliance Score:	80.0 / 100	Workflow Status:	APPROVED

AI-ASSISTED RISK ASSESSMENT: 45.0/100 — [LOW]

Contributing Factors: Normal operation standards met.

Statutory Checklist Findings

Item / Rule	Category	Result	Remarks
Haul road berm height ≥ tyre height (DGMS Reg 115)	Safety	FAIL	Berm height only 1.1m against 2.2m dumper tyre requirement.
Reverse horn (AVRA) functional on all HEMM	Safety	PASS	Tested functional.
Dust suppression mist / bowser operational	Environmental	PASS	Misting bowser active.

Recorded Violations & Corrective Directives

Violation Code	Category	Severity	Statutory Reference & Details
VIO-260928-4F95F9	Safety	MEDIUM	Non-Compliance: Haul road berm height ≥ tyre height (DGMS Reg 115): Field observation recorded: Berm height only 1.1m against 2.2m dumper tyre requirement.
VIO-260928-2053BB	Safety	HIGH	Critical Observation: Substandard Haul Road Berm: Berm height at Bench 3 is sub-regulation under DGMS Reg 115.

FIELD OFFICER VERIFICATION
Digitally Signed & Submitted
Date: 2026-09-28

MINE MANAGER VALIDATION
Reviewed and Enforced
Action Assigned

CORPORATE GOVERNANCE (CIL)
Statutory Compliance Seal
Status: APPROVED