

GOVERNMENT OF INDIA • MINISTRY OF COAL

COAL INDIA LIMITED (CIL) • CENTRAL MINE GOVERNANCE SYSTEM

Official Statutory Inspection & Compliance Audit Report — Generated: 2026-09-26 22:16 UTC

Report Ref No:	REP-2026-CIL-001	Inspection Date:	2026-09-26
Mine Facility:	Rajmahal Open Cast Project (ECL-OCP-01)	Subsidiary:	Eastern Coalfields Limited
Contractor Agency:	ABC Mining Services Pvt Ltd	Inspecting Officer:	Amitabh Singh (Senior Overman / Safety Inspector)
Inspection Type:	Safety	Geo-Coordinates:	25.0492° N, 87.3830° E
Compliance Score:	68.5 / 100	Workflow Status:	UNDER_MINE_MANAGER_REVIEW

AI-ASSISTED RISK ASSESSMENT: 78.4/100 — [HIGH]

Contributing Factors: 2 active workers with expired statutory Form O medical fitness certificates, Berm height on haul road < 2.5m (DGMS Safety Regulation 115 failure), Ambient dust suppression mist nozzles non-functional at dumping point, Contractor historical open violations: 2

Statutory Checklist Findings

Item / Rule	Category	Result	Remarks
Haul road width >= 3 times largest vehicle width	Safety	PASS	Compliant at 18 meters width.
Earthen berm height at least equal to largest tyre height (2.7m)	Safety	FAIL	Deficient berm of 1.4m on eastern slope (DGMS violation).
Audio-visual reverse alarms (AVRA) functional on dumpers	Safety	PASS	Tested on 6 dumpers, all functional.
Water sprinkling / mist cannon operational on haul road	Environmental	FAIL	Water bowser pump broken; severe airborne coal dust visible.
Valid Form O Medical Fitness certificates verified on-site	Labour Compliance	FAIL	2 Dumper drivers have expired PME certificates.
Mandatory PPE (fluorescent jacket, hard hat, steel-toe boots)	Personal Safety	PASS	100% compliant wearing observed.
Valid DGMS Blaster certification on duty during charge loading	Statutory Clearance	PASS	Certificate verified.

Recorded Violations & Corrective Directives

Violation Code	Category	Severity	Statutory Reference & Details
VIO-ECL-26-001	Safety	HIGH	Substandard Haul Road Berm Height (DGMS Reg 115): Failure to maintain continuous earthen parapet/berm of required height along steep haulage gradient.

VIO-ECL-26-002	Labour & Health Compliance	HIGH	Active Workers with Expired PME Medical Certificates: Deploying HEMM operators with expired Periodical Medical Fitness examination records.
VIO-ECL-26-003	Environmental	MEDIUM	Non-Functional Dust Suppression at Active Loading Face: Failure to suppress respirable dust leading to ambient air quality exceedance.

FIELD OFFICER VERIFICATION Digitally Signed & Submitted Date: 2026-09-26	MINE MANAGER VALIDATION Reviewed and Enforced Action Assigned	CORPORATE GOVERNANCE (CIL) Statutory Compliance Seal Status: APPROVED
---	--	--