

Survey of Windsor Castle

A survey of the fabric and furnishings of Windsor Castle.

The roof of the great hall wants attention before winter. The kitchens are sound. The moat requires dredging.

Estimated cost of necessary works appended.

Works	Estimate (£)
Roof	120
Drainage	60
Glazing	45