

AN4744

Microchip KSZ9131MNX to LAN8831 Migration Guide

Author: John MacKay

Microchip Technology Inc.

INTRODUCTION

This document is for customers with an existing KSZ9131MNX board design migrating to the LAN8831 for their board design. This features a comparison of hardware and software register specifications between the two products. Details on the hardware and software of each device can be found on each product's Microchip web page.

Table 1 summarizes the hardware attribute differences between the KSZ9131MNX and the LAN8831. Table 2 summarizes the register differences between the KSZ9131MNX and the LAN8831. For LAN8831 RGMII usage, please see the AN4742 KSZ9131RNX to LAN8830 Migration Guide.

TABLE 1: HARDWARE DIFFERENCES BETWEEN KSZ9131MNX AND LAN8831

Device Attribute	KSZ9131MNX	LAN8831
Analog Low Voltage	AVDDL – 1.2V	VDDAL – 1.1V
Digital Low Voltage	DVDDL – 1.2V	VDD – 1.1V
Management Modes	GMII/MII Only	RGMII_EN Strap PU: RGMII RGMII_EN Strap PD: GMII/RGMII
MODE Strapping Pins	MODE[3:0] - 0001: GMII mode – Advertise all capabilities (10/100/1000 speed Half-/Full-duplex), except 1000BASE-T Half-duplex - 0100: NAND Tree - 0111: Chip Power Down - 1001: GMII/MII mode – 10/100 FD/HD, PME on LED1 - 1001: GMII/MII mode – 10/100 FD/HD, PME on LED2	MODE[4:0] - 10000: GMII mode – Advertise all capabilities (10/100/1000 speed Half-/Full-duplex), except 1000BASE-T Half-duplex, EEE Disabled - 11000: GMII mode – Advertise all capabilities (10/100/1000 speed Half-/Full-duplex), except 1000BASE-T Half-duplex, EEE Enabled - 00100: NAND Tree - 00111: Device Power Down mode - 01000: Chip Power Down – PLL Enabled - 01001: Chip Power Down – PLL Disabled Note that PME can map to any GPIO.
PME	Needs mode setting to set LED1/ LED2 as PME signal	No mode setting needed to set PME. Registers set the GPIO pin to set as PME signal.
ALL-PHYAD	Pin 53 can be set to respond to the KSZ9131MNX PHY Address (from PHYAD[2:0]) and PHY Address 0.	Pin 16 can be set to respond to the LAN8831 PHY Address (from PHYAD[4:0]) and PHY Address 0.
Fast Link Failure	None	Can indicate link failure in 1 ms when enabled at 100/1000
PHYAD Strap Range	PHYAD[2:0]	PHYAD[4:0]

TABLE 1: HARDWARE DIFFERENCES BETWEEN KSZ9131MNX AND LAN8831

Device Attribute	KSZ9131MNX	LAN8831
LED Modes	No straps for LED modes	LED mode strap for Individual (PU) and Tri- color (PD)
LED Polarity Control	None	LEDPOL[5:1] available
LEDs	2 LEDs (LED1, LED2)	5 LEDs (LED1, LED2, LED3, LED4, LED5)
GPIOs	None	10 GPIOs (GPIO0-GPIO10)
Shorted-center Tap Magnetic Support	None	MAGJACK Strap
Quiet-WIRE	Supported	No Functionality

TABLE 2: REGISTER DIFFERENCES BETWEEN KSZ9131MNX AND LAN8831

Register	KSZ9131MNX	LAN8831
16h	Bits[15:8] – Reserved Bits[7:4] – LED2 Configuration Bits[3:0] – LED1 Configuration	Bits[15:12] - LED4 Configuration Bits[11:8] - LED3 Configuration Bits[7:4] - LED2 Configuration Bits[3:0] - LED1 Configuration
17h	Bits 15, 13, [9:7], [4:2] – Reserved Bits[6:5] – LED Pulse Stretch Enables Bits[1:0] – LED Combination Disables	Bits 15, 13, 9, 4 – Reserved Bits[8:5] – LED Pulse Stretch Enables Bits[3:0] – LED Combination Disables
19h	Bit 15 – Reserved Bit 1 – MDIO Drive Bit 0 – Reserved	Bit 15 – MDIO Buffer Type Bit 14 – INT Buffer Type Bits[13:8] LED Buffer Type Bit[7] – PME Polarity Bits[5:0] – LED Polarity
1Bh	Bit 15 – Jabber Interrupt Enable Bit 14 – Receive Error Interrupt Bit 13 – Page Receive Interrupt Bit 12 – Parallel Detect Fault Interrupt Bit 11 – Link Partner Acknowledgment Interrupt Bit 10 – Link Down Interrupt Bit 9 – Remote Fault Interrupt Bit 1 – Remote Fault Interrupt	Bits[15:12], 9 – Reserved Bit 11 – Energy Not Detected Interrupt Bit 10 – Energy Detected Interrupt Bit 1 – ADC FIFO Error Interrupt
Address 2, Reg. 1h	Bits[13:8] – Reserved	Bits[13:8] – LED Polarity
Address 2, Reg. 2h	Bits 14, 8, 0 – Reserved Bit 11 – GMII mode with PME_N2 mapped to INT_N Bit 9 – GMII mode with PME_N1 mapped to LED1 Bit 7 – Chip Power-Down Strap Override Bit 4 – NAND Tree Strap Override Bit 1 – GMII/MII Strap Override	Bits 11, 7, 0 – Reserved Bit 14 – MagJack Strap Bit 9 – Software Power Down w/ PLL Disabled Bit 8 – Software Power Down w/ PLL Enabled Bit 4 – NAND Tree Strap Override Bit 1 – GMII/MII Strap Override Bit 0 – RGMII mode
Address 2, Reg. 3h	Bits 14, 8, 0 – Reserved Bit 11 – GMII mode with PME_N2 mapped to INT_N Status Bit 9 – GMII mode with PME_N1 mapped to LED1 Status Bit 7 – Chip Power-Down Strap Override Status Bit 4 – NAND Tree Strap Override Bit 1 – GMII/MII Strap Status	Bits 11, 7, 0 – Reserved Bit 14 – MagJack Strap Status Bit 9 – Software Power-down w/ PLL Disabled Status Bit 8 – Software Power-down w/ PLL Enabled Status Bit 4 – NAND Tree Strap Override Status Bit 1 – GMII/MII Strap Status Bit 0 – RGMII Strap Status

TABLE 2: REGISTER DIFFERENCES BETWEEN KSZ9131MNX AND LAN8831

Register	KSZ9131MNX	LAN8831
Address 2, Reg. 4h	Reserved (not used)	When LAN8831 is in RGMII mode: Bits[7:4] – RX_CTL Pad Skew Bits[3:0] – TX_CTL Pad Skew
		When LAN8831 is in GMII mode, Bits[7:0] should remain unchanged.
Address 2, Reg. 5h	Reserved (not used)	When LAN8831 is in RGMII mode: Bits[15:12] – RXD3 Pad Skew Bits[11:8] – RXD2 Pad Skew Bits[7:4] – RXD1 Pad Skew Bits[3:0] – RXD0 Pad Skew
		When LAN8831 is in GMII mode, Bits[15:0] should remain unchanged.
Address 2, Reg. 6h	Reserved (not used)	When LAN8831 is in RGMII mode: Bits[15:12] – TXD3 Pad Skew Bits[11:8] – TXD2 Pad Skew Bits[7:4] – TXD1 Pad Skew Bits[3:0] – TXD0 Pad Skew When LAN8831 is in GMII mode, Bits[15:0] should remain unchanged.
Address 2, Reg. 40h	Bits[15:0] – Bad SFD Count Lo	Reserved (Not shown)
Address 2, Reg. 41h	Bits[15:0] – Bad SFD Count Hi	Reserved (Not shown)
Address 1C, 0Dh	Bit 15 – LDO Enabled	Bit 15 – LDO Enabled Bits 14:12 – LDO Reference Tune
Address 1F, Reg. 13h	Bit 10 – Quiet-WIRE Enable	Reserved (Not shown)

Additional features, such as EEE, MSE/SQI, and self-test for frame generation or checking, are accessible in the Indirect Address Registers.

APPENDIX A: APPLICATION NOTE REVISION HISTORY

TABLE A-1: REVISION HISTORY

Revision Level & Date	Section/Figure/Entry	Correction
DS00004744A (09-19-22)	Initial release.	

NOTES:

THE MICROCHIP WEB SITE

Microchip provides online support via our WWW site at www.microchip.com. This web site is used as a means to make files and information easily available to customers. Accessible by using your favorite Internet browser, the web site contains the following information:

- **Product Support** Data sheets and errata, application notes and sample programs, design resources, user's guides and hardware support documents, latest software releases and archived software
- General Technical Support Frequently Asked Questions (FAQ), technical support requests, online discussion groups, Microchip consultant program member listing
- Business of Microchip Product selector and ordering guides, latest Microchip press releases, listing of seminars and events, listings of Microchip sales offices, distributors and factory representatives

CUSTOMER CHANGE NOTIFICATION SERVICE

Microchip's customer notification service helps keep customers current on Microchip products. Subscribers will receive e-mail notification whenever there are changes, updates, revisions or errata related to a specified product family or development tool of interest.

To register, access the Microchip web site at www.microchip.com. Under "Support", click on "Customer Change Notification" and follow the registration instructions.

CUSTOMER SUPPORT

Users of Microchip products can receive assistance through several channels:

- · Distributor or Representative
- · Local Sales Office
- · Field Application Engineer (FAE)
- · Technical Support

Customers should contact their distributor, representative or Field Application Engineer (FAE) for support. Local sales offices are also available to help customers. A listing of sales offices and locations is included in the back of this document.

Technical support is available through the web site at: http://microchip.com/support

Note the following details of the code protection feature on Microchip products:

- Microchip products meet the specifications contained in their particular Microchip Data Sheet.
- Microchip believes that its family of products is secure when used in the intended manner, within operating specifications, and under normal conditions.
- Microchip values and aggressively protects its intellectual property rights. Attempts to breach the code protection features of Microchip product is strictly prohibited and may violate the Digital Millennium Copyright Act.
- Neither Microchip nor any other semiconductor manufacturer can guarantee the security of its code. Code protection does not
 mean that we are guaranteeing the product is "unbreakable" Code protection is constantly evolving. Microchip is committed to
 continuously improving the code protection features of our products.

This publication and the information herein may be used only with Microchip products, including to design, test, and integrate Microchip products with your application. Use of this information in any other manner violates these terms. Information regarding device applications is provided only for your convenience and may be superseded by updates. It is your responsibility to ensure that your application meets with your specifications. Contact your local Microchip sales office for additional support or, obtain additional support at https://www.microchip.com/en-us/support/design-help/client-support-services.

THIS INFORMATION IS PROVIDED BY MICROCHIP "AS IS". MICROCHIP MAKES NO REPRESENTATIONS OR WAR-RANTIES OF ANY KIND WHETHER EXPRESS OR IMPLIED, WRITTEN OR ORAL, STATUTORY OR OTHERWISE, RELATED TO THE INFORMATION INCLUDING BUT NOT LIMITED TO ANY IMPLIED WARRANTIES OF NON- INFRINGEMENT, MERCHANTABILITY, AND FITNESS FOR A PARTICULAR PURPOSE, OR WARRANTIES RELATED TO ITS CONDITION, QUALITY, OR PERFORMANCE.

IN NO EVENT WILL MICROCHIP BE LIABLE FOR ANY INDI- RECT, SPECIAL, PUNITIVE, INCIDENTAL, OR CONSEQUENTIAL LOSS, DAMAGE, COST, OR EXPENSE OF ANY KIND WHATSOEVER RELATED TO THE INFORMATION OR ITS USE, HOWEVER CAUSED, EVEN IF MICROCHIP HAS BEEN ADVISED OF THE POSSIBILITY OR THE DAMAGES ARE FORESEEABLE. TO THE FULLEST EXTENT ALLOWED BY LAW, MICROCHIP'S TOTAL LIABILITY ON ALL CLAIMS IN ANY WAY RELATED TO THE INFORMATION OR ITS USE WILL NOT EXCEED THE AMOUNT OF FEES, IF ANY, THAT YOU HAVE PAID DIRECTLY TO MICROCHIP FOR THE INFORMATION.

Use of Microchip devices in life support and/or safety applications is entirely at the buyer's risk, and the buyer agrees to defend, indemnify and hold harmless Microchip from any and all damages, claims, suits, or expenses resulting from such use. No licenses are conveyed, implicitly or otherwise, under any Microchip intellectual property rights unless otherwise stated.

Trademarks

The Microchip name and logo, the Microchip logo, Adaptec, AVR, AVR logo, AVR Freaks, BesTime, BitCloud, CryptoMemory, CryptoRF, dsPIC, flexPWR, HELDO, IGLOO, JukeBlox, KeeLoq, Kleer, LANCheck, LinkMD, maXStylus, maXTouch, MediaLB, megaAVR, Microsemi, Microsemi logo, MOST, MOST logo, MPLAB, OptoLyzer, PIC, picoPower, PICSTART, PIC32 logo, PolarFire, Prochip Designer, QTouch, SAM-BA, SenGenuity, SpyNIC, SST, Logo, SuperFlash, Symmetricom, SyncServer, Tachyon, TimeSource, tinyAVR, UNI/O, Vectron, and XMEGA are registered trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

AgileSwitch, APT, ClockWorks, The Embedded Control Solutions Company, EtherSynch, Flashtec, Hyper Speed Control, HyperLight Load, Libero, motorBench, mTouch, Powermite 3, Precision Edge, ProASIC, ProASIC Plus, ProASIC Plus logo, Quiet-Wire, SmartFusion, SyncWorld, Temux, TimeCesium, TimeHub, TimePictra, TimeProvider, TrueTime, and ZL are registered trademarks of Microchip Technology Incorporated in the U.S.A.

Adjacent Key Suppression, AKS, Analog-for-the-Digital Age, Any Capacitor, AnyIn, AnyOut, Augmented Switching, BlueSky, BodyCom, Clockstudio, CodeGuard, CryptoAuthentication, CryptoAuthomotive, CryptoCompanion, CryptoController, dsPICDEM, dsPICDEM, net, Dynamic Average Matching, DAM, ECAN, Espresso T1S, EtherGREEN, GridTime, IdealBridge, In-Circuit Serial Programming, ICSP, INICnet, Intelligent Paralleling, IntelliMOS, Inter-Chip Connectivity, JitterBlocker, Knob-on-Display, KoD, maxCrypto, maxView, memBrain, Mindi, MiWi, MPASM, MPF, MPLAB Certified logo, MPLIB, MPLINK, MultiTRAK, NetDetach, Omniscient Code Generation, PICDEM, PICDEM.net, PICkit, PICtail, PowerSmart, PureSilicon, QMatrix, REAL ICE, Ripple Blocker, RTAX, RTG4, SAM-ICE, Serial Quad I/O, simpleMAP, SimpliPHY, SmartBuffer, SmartHLS, SMART-I.S., storClad, SQI, SuperSwitcher, SuperSwitcher II, Switchtec, SynchroPHY, Total Endurance, Trusted Time, TSHARC, USBCheck, VariSense, VectorBlox, VeriPHY, ViewSpan, WiperLock, XpressConnect, and ZENA are trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

SQTP is a service mark of Microchip Technology Incorporated in the U.S.A.

The Adaptec logo, Frequency on Demand, Silicon Storage Technology, and Symmcom are registered trademarks of Microchip Technology Inc. in other countries.

GestIC is a registered trademark of Microchip Technology Germany II GmbH & Co. KG, a subsidiary of Microchip Technology Inc., in other countries.

All other trademarks mentioned herein are property of their respective companies.

© 2022, Microchip Technology Incorporated and its subsidiaries.

All Rights Reserved.

ISBN: 978-1-6683-1255-1

For information regarding Microchip's Quality Management Systems, please visit www.microchip.com/quality.



Worldwide Sales and Service

AMERICAS

Corporate Office 2355 West Chandler Blvd. Chandler, AZ 85224-6199

Tel: 480-792-7200 Fax: 480-792-7277 Technical Support:

http://www.microchip.com/

support Web Address:

www.microchip.com

Atlanta Duluth, GA

Tel: 678-957-9614 Fax: 678-957-1455

Austin, TX Tel: 512-257-3370

Boston

Westborough, MA Tel: 774-760-0087 Fax: 774-760-0088

Chicago Itasca, IL

Tel: 630-285-0071 Fax: 630-285-0075

Dallas

Addison, TX Tel: 972-818-7423 Fax: 972-818-2924

Detroit Novi. MI

Tel: 248-848-4000

Houston, TX

Tel: 281-894-5983 Indianapolis

Noblesville, IN Tel: 317-773-8323 Fax: 317-773-5453 Tel: 317-536-2380

Los Angeles

Mission Viejo, CA Tel: 949-462-9523 Fax: 949-462-9608 Tel: 951-273-7800

Raleigh, NC Tel: 919-844-7510

New York, NY Tel: 631-435-6000

San Jose, CA Tel: 408-735-9110 Tel: 408-436-4270

Canada - Toronto Tel: 905-695-1980 Fax: 905-695-2078

ASIA/PACIFIC

Australia - Sydney Tel: 61-2-9868-6733

China - Beijing Tel: 86-10-8569-7000

China - Chengdu Tel: 86-28-8665-5511

China - Chongqing Tel: 86-23-8980-9588

China - Dongguan Tel: 86-769-8702-9880

China - Guangzhou Tel: 86-20-8755-8029

China - Hangzhou Tel: 86-571-8792-8115

China - Hong Kong SAR Tel: 852-2943-5100

China - Nanjing Tel: 86-25-8473-2460

China - Qingdao Tel: 86-532-8502-7355

China - Shanghai Tel: 86-21-3326-8000

China - Shenyang Tel: 86-24-2334-2829

China - Shenzhen

Tel: 86-755-8864-2200

China - Suzhou Tel: 86-186-6233-1526

China - Wuhan Tel: 86-27-5980-5300

China - Xian Tel: 86-29-8833-7252

China - Xiamen
Tel: 86-592-2388138

China - Zhuhai Tel: 86-756-3210040

ASIA/PACIFIC

India - Bangalore Tel: 91-80-3090-4444

India - New Delhi Tel: 91-11-4160-8631

India - Pune Tel: 91-20-4121-0141

Japan - Osaka

Tel: 81-6-6152-7160 Japan - Tokyo

Tel: 81-3-6880- 3770

Korea - Daegu Tel: 82-53-744-4301

Korea - Seoul Tel: 82-2-554-7200

Malaysia - Kuala Lumpur Tel: 60-3-7651-7906

Malaysia - Penang Tel: 60-4-227-8870

Philippines - Manila Tel: 63-2-634-9065

Singapore Tel: 65-6334-8870

Taiwan - Hsin Chu Tel: 886-3-577-8366

Taiwan - Kaohsiung Tel: 886-7-213-7830

Taiwan - Taipei Tel: 886-2-2508-8600

Thailand - Bangkok Tel: 66-2-694-1351

Vietnam - Ho Chi Minh Tel: 84-28-5448-2100

EUROPE

Austria - Wels Tel: 43-7242-2244-39

Fax: 43-7242-2244-393

Denmark - Copenhagen Tel: 45-4485-5910 Fax: 45-4485-2829

Finland - Espoo Tel: 358-9-4520-820

France - Paris
Tel: 33-1-69-53-63-20

Fax: 33-1-69-30-90-79 **Germany - Garching**

Tel: 49-8931-9700 **Germany - Haan** Tel: 49-2129-3766400

Germany - Heilbronn Tel: 49-7131-72400

Germany - Karlsruhe Tel: 49-721-625370

Germany - Munich Tel: 49-89-627-144-0 Fax: 49-89-627-144-44

Germany - Rosenheim Tel: 49-8031-354-560

Israel - Ra'anana Tel: 972-9-744-7705

Italy - Milan Tel: 39-0331-742611 Fax: 39-0331-466781

Italy - Padova Tel: 39-049-7625286

Netherlands - Drunen Tel: 31-416-690399 Fax: 31-416-690340

Norway - Trondheim Tel: 47-7288-4388

Poland - Warsaw Tel: 48-22-3325737

Romania - Bucharest Tel: 40-21-407-87-50

Spain - Madrid Tel: 34-91-708-08-90 Fax: 34-91-708-08-91

Sweden - Gothenberg Tel: 46-31-704-60-40

Sweden - Stockholm Tel: 46-8-5090-4654

UK - Wokingham Tel: 44-118-921-5800 Fax: 44-118-921-5820