

# NON-CONFORMANCE REPORT (NCR) & REJECTION NOTICE

|              |                                      |             |                  |
|--------------|--------------------------------------|-------------|------------------|
| Supplier:    | (■)■■■■■■■ (Gyeongnam Precision Mold | Date:       | 2026-09-20       |
| Part Number: | INJ-H401-BK                          | Lot Number: | LOT-20260920-A01 |
| Disposition: | REJECTED / RETURN                    | Quantity:   | 3,000 EA         |

| Item Name      | Spec    | USL / LSL     | Measured  | Defect Reason                                |
|----------------|---------|---------------|-----------|----------------------------------------------|
| Outer Diameter | 85.0 mm | 84.85 ~ 85.15 | 70.018 mm | Lower Limit Deficit (-14.832 mm < LSL 84.85) |
| Inner Diameter | 62.0 mm | 61.9 ~ 62.1   | 70.018 mm | Upper Limit Exceeded (+7.918 mm > USL 62.1)  |
| Total Height   | 42.5 mm | 42.3 ~ 42.7   | 70.018 mm | Upper Limit Exceeded (+27.318 mm > USL 42.7) |
| Wall Thickness | 2.5 mm  | 2.4 ~ 2.6     | 70.018 mm | Upper Limit Exceeded (+67.418 mm > USL 2.6)  |

Mandatory Corrective Action:

- 1. Rejected lot must be quarantined immediately to prevent assembly line contamination.
- 2. Supplier must provide an 8D Root Cause Analysis within 3 business days.
- 3. Emergency replacement lot with pre-inspection required.