

Ensure cooling coils are suppressing the vapour fumes and that the freeboard height is correct.