

A

B

(C)

D





UART OUT UART IN GND

D6 OUT D7 OUT GND

TRACE ON

PICO RESET

6800 RESET

TRAINER UART

GND D2IN 60HZ SW IRQ NMI

+5V GND 3.3V GND A3 A2 A1

 D Do
 E Examine
 F Forward

 A Auto
 B Back
 C Change

 7 RTI
 8 Single Step
 9 Break Point

 4 IndeX
 5 CC
 6 SP2

 1 ACCA
 2 ACCB
 3 PC

 0
 Grey 0x20
 Red 0x10 Exit