


(a) G10 Rotor Angle — Effect of STATCOM Saturation



(b) STATCOM Reactive-Power Output — Saturation Clamping Visible

