

USB Network Native Driver for ESXi

version 1.13 — September 21, 2023

USB

USB DRIVER

I have read and agree to the Technical Preview License I also understand that Flings are experimental and should not be run on production systems.

ESXi80U1-VMKUSB-NIC-FLING-64098092-component-21669994.zip

DOWNLOAD

Contributors 2



View All

Comments 697



View All

Release Date: February 06, 2019

Share on:





Cookies Settings

Project Details

Summary

Requirements

Instructions

Changelog

Contributors

Discover

Similar Flings

Community

Comments 697

Bugs 37

REQUIREMENTS

• VMware ESXi 6.5, 6.7, 7.0 & 8.0 (x86)

Any adapters using the following chipsets and with the following VID/PID are supported.

Vendor	Chipset	VendorID	ProductID
AQUANTIA	AQC111U	0xe05a	0x20f4
AQUANTIA	Aquantia Pacific	0x2eca	0xc101
ASIX	AX88179	0x0b95	0x1790
ASIX	AX88178a	0x0b95	0x178a

1.41 AIVI	OSB Network Native Driver for ESALLY	/iviware riiiigs	
CISCO LINKSYS	RTL8153	0x13b1	0x0041
DLINK	RTL8156	0x2001	0xb301
DLINK	AX88179	0x2001	0x4a00
INSYDE SOFTWARE CORP	Insyde Software Corp.	0x0b1f	0x03ee
LENOVO	RTL8153	0x17ef	0x3062
LENOVO	RTL8153	0x17ef	0x3069
LENOVO	RTL8153	0x17ef	0x720a
LENOVO	AX88179	0x17ef	0x304b
LENOVO	RTL8153	0x17ef	0x7205
NVIDIA	RTL8153	0x0955	0x09ff
Qualcomm	NA	0x1A56	0x3100
Qualcomm	NA	0x0b05	0x1976
REALTEK	RTL8152	0x0bda	0x8152
REALTEK	RTL8156	0x0bda	0x8156
REALTEK	RTL8153	0x045e	0x07c6
REALTEK	RTL8153	0x0bda	0x8153
SITECOMEU	AX88179	0x0df6	0x0072
SUPERMICRO	Supermicro computer Inc	0x15d9	0x1b83
TP-LINK	RTL8153	0x2357	0x0601
TRENDNET	AQC111U	0xe05a	0x20f4

OCTO Blog About VMware {code}™ Legal Contact © 2023 VMware, Inc Terms of Use Your California Privacy Rights Privacy Accessibility Site Map Trademarks Glossary Help Feedback y f in D